

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL C10543  
 SIERRA  
 CARLINE 01CP  
 ASSEMBLY LOC: SILAO

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | 1.0434                        | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED       | .6807                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS      | 1.0722                        | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                  | 2.0355                        | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES        | .3601                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE             | .4402                         | BODY PRIMED AND SEALED                              |
| DOORS                   | 2.2100                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                  | 8.0096                        | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                 | 2.9917                        | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM       | .1086                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC    | .6169                         | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS      | .2210                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.      | 1.6019                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES    | 1.2489                        | SEATS INSTALLED                                     |
| HVAC                    | 1.6473                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL        | .5769                         | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS      | 3.0691                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL      | .1636                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL          | .5044                         | FINISHED VEHICLE SHIPPED                            |
| ROOF                    | 1.0896                        |   |
| SEATS                   | .5521                         |   |
| STEERING                | 1.1582                        |   |
| STEP PLT./EXT. ASST.    | .8973                         |   |
| TRANSMISSION            | 3.9594                        |   |
| UNDER BODY              | 2.6937                        |   |
| WHEELS & TIRES          | 2.3100                        |   |
| WIPER & WASHER          | .1930                         |   |
| TOTAL US CONTENT        | 41.4569                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL C10553  
 SILVERADO  
 CARLINE 01CP  
 ASSEMBLY LOC: FORT WAYNE

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | 1.1491                        | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED       | .3432                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS      | 1.3547                        | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                  | 1.3907                        | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES        | .4314                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE             | .3765                         | BODY PRIMED AND SEALED                              |
| DOORS                   | 4.0257                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                  | 14.7380                       | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                 | 3.8981                        | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM       | .1344                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC    | 1.4001                        | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS      | .3327                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.      | 1.9828                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES    | 1.1898                        | SEATS INSTALLED                                     |
| HVAC                    | 2.4068                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL        | .7435                         | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS      | 2.6937                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL      | .1349                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL          | .6471                         | FINISHED VEHICLE SHIPPED                            |
| ROOF                    | 1.1723                        |   |
| SEATS                   | 6.8460                        |   |
| STEERING                | 1.9303                        |   |
| STEP PLT./EXT. ASST.    | 1.1141                        |   |
| TRANSMISSION            | 2.2496                        |   |
| UNDER BODY              | 3.3910                        |   |
| WHEELS & TIRES          | 3.5143                        |   |
| WIPER & WASHER          | .1648                         |   |
| TOTAL US CONTENT        | 59.7568                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL C10903  
 SIERRA  
 CARLINE 01CP  
 ASSEMBLY LOC: PONTIAC

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | 1.1531                        | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED       | .3638                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS      | .9946                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                  | 1.7030                        | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES        | .4725                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE             | .1669                         | BODY PRIMED AND SEALED                              |
| DOORS                   | 2.5144                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                  | 16.1188                       | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                 | 4.1686                        | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM       | .1433                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC    | 1.5237                        | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS      | .3810                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.      | 1.9874                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES    | .2829                         | SEATS INSTALLED                                     |
| HVAC                    | 2.8761                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL        | .7965                         | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS      | 3.3140                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL      | .0709                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL          | .6057                         | FINISHED VEHICLE SHIPPED                            |
| ROOF                    | .8649                         |   |
| SEATS                   | 4.6639                        |   |
| STEERING                | 1.9164                        |   |
| STEP PLT./EXT. ASST.    | 1.1850                        |   |
| TRANSMISSION            | 2.3762                        |   |
| UNDER BODY              | 3.2096                        |   |
| WHEELS & TIRES          | 3.1775                        |   |
| WIPER & WASHER          | .2555                         |   |
| TOTAL US CONTENT        | 57.2878                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL C10936  
 CHEVY AVALANCHE  
 CARLINE 01CU  
 ASSEMBLY LOC: SILAO

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | .2935                         | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED       | 1.0118                        | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS      | .9109                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                  | .8871                         | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES        | .5252                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE             | .6701                         | BODY PRIMED AND SEALED                              |
| DOORS                   | 2.2702                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                  | 5.7682                        | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                 | 2.3815                        | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM       | .0051                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC    | .1295                         | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS      | .0102                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.      | 3.2193                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES    | .2583                         | SEATS INSTALLED                                     |
| HVAC                    | 1.0724                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL        | .5914                         | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS      | 2.8096                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL      | .1517                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL          | .4412                         | FINISHED VEHICLE SHIPPED                            |
| ROOF                    | 1.1526                        |   |
| SEATS                   | .1197                         |   |
| STEERING                | 1.0035                        |   |
| STEP PLT./EXT. ASST.    | .4051                         |   |
| TRANSMISSION            | 2.6902                        |   |
| UNDER BODY              | 3.1152                        |   |
| WHEELS & TIRES          | 1.6926                        |   |
| WIPER & WASHER          | .0730                         |   |
| TOTAL US CONTENT        | 33.6603                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL C10953  
 SIERRA  
 CARLINE 01CP  
 ASSEMBLY LOC: PONTIAC

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | .4064                                  | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED                | .2553                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS               | 1.0773                                 | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                           | 1.7960                                 | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES                 | .3890                                  | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE                      | .1878                                  | BODY PRIMED AND SEALED                              |
| DOORS                            | 3.1331                                 | EXTERIOR PAINT APPLIED                              |
| ENGINE                           | 13.6653                                | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                          | 3.5147                                 | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM                | .1131                                  | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC             | 1.1833                                 | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS               | .3238                                  | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.               | 1.6514                                 | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES             | .2242                                  | SEATS INSTALLED                                     |
| HVAC                             | 2.0462                                 | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL                 | .6189                                  | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS               | 2.5372                                 | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL               | .1693                                  | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL                   | .4947                                  | FINISHED VEHICLE SHIPPED                            |
| ROOF                             | .9359                                  |   |
| SEATS                            | 5.4786                                 |   |
| STEERING                         | 1.1210                                 |   |
| STEP PLT./EXT. ASST.             | .8998                                  |   |
| TRANSMISSION                     | 2.0426                                 |   |
| UNDER BODY                       | 2.9457                                 |   |
| WHEELS & TIRES                   | 2.5179                                 |   |
| WIPER & WASHER                   | .2614                                  |   |
| TOTAL US CONTENT                 | 49.9912                                |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL C20743  
 SILVERADO  
 CARLINE 01CP  
 ASSEMBLY LOC: FLINT LIGHT

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | .2150                         | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED       | .2995                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS      | .9338                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                  | 2.1214                        | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES        | .3998                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE             | .3771                         | BODY PRIMED AND SEALED                              |
| DOORS                   | 3.3652                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                  | 12.6644                       | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                 | 4.9848                        | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM       | .1413                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC    | 1.0274                        | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS      | .2476                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.      | 3.3030                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES    | .1636                         | SEATS INSTALLED                                     |
| HVAC                    | 1.8717                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL        | .5467                         | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS      | 2.3303                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL      | .2536                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL          | .5599                         | FINISHED VEHICLE SHIPPED                            |
| ROOF                    | .9096                         |   |
| SEATS                   | 5.9463                        |   |
| STEERING                | 2.5269                        |   |
| STEP PLT./EXT. ASST.    | .7730                         |   |
| TRANSMISSION            | 6.7416                        |   |
| UNDER BODY              | 2.5547                        |   |
| WHEELS & TIRES          | 2.4916                        |   |
| WIPER & WASHER          | .1221                         |   |
| TOTAL US CONTENT        | 57.8732                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL C20753  
 SIERRA  
 CARLINE 01CP  
 ASSEMBLY LOC: PONTIAC

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|-------------------------------|---|
| AXLE & HALF SHAFT                | .1954                         | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED                | .2700                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS               | 1.0677                        | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                           | 2.2241                        | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES                 | .3955                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE                      | .2799                         | BODY PRIMED AND SEALED                              |
| DOORS                            | 3.0124                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                           | 10.9127                       | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                          | 5.8345                        | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM                | .1454                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC             | 1.0758                        | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS               | .3082                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.               | 3.3865                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES             | .1466                         | SEATS INSTALLED                                     |
| HVAC                             | 2.0259                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL                 | .5736                         | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS               | 2.1170                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL               | .2707                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL                   | .4662                         | FINISHED VEHICLE SHIPPED                            |
| ROOF                             | .9260                         |   |
| SEATS                            | 5.1446                        |   |
| STEERING                         | 2.6541                        |   |
| STEP PLT./EXT. ASST.             | .8098                         |   |
| TRANSMISSION                     | 7.2256                        |   |
| UNDER BODY                       | 2.6854                        |   |
| WHEELS & TIRES                   | 2.5388                        |   |
| WIPER & WASHER                   | .2388                         |   |
| TOTAL US CONTENT                 | 56.9325                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL C20903  
 SIERRA  
 CARLINE 01CP  
 ASSEMBLY LOC: PONTIAC

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | 2.4033                        | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED       | .2768                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS      | .9422                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                  | .6962                         | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES        | .5183                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE             | .1335                         | BODY PRIMED AND SEALED                              |
| DOORS                   | 1.8069                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                  | 9.4532                        | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                 | 9.2934                        | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM       | .1277                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC    | 1.2319                        | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS      | .3469                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.      | 6.0015                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES    | .3302                         | SEATS INSTALLED                                     |
| HVAC                    | 2.5425                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL        | .6689                         | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS      | 1.9420                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL      | .1954                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL          | .4871                         | FINISHED VEHICLE SHIPPED                            |
| ROOF                    | .6969                         |   |
| SEATS                   | 3.6898                        |   |
| STEERING                | 2.9558                        |   |
| STEP PLT./EXT. ASST.    | .5610                         |   |
| TRANSMISSION            | 8.6019                        |   |
| UNDER BODY              | 2.3073                        |   |
| WHEELS & TIRES          | 2.7647                        |   |
| WIPER & WASHER          | .2714                         |   |
| TOTAL US CONTENT        | 61.2482                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL C20906  
 GMC YUKON XL  
 CARLINE 01CU  
 ASSEMBLY LOC: ARLINGTON

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | .3908                         | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED       | .2241                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS      | .7675                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                  | 1.5530                        | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES        | .3869                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE             | .4710                         | BODY PRIMED AND SEALED                              |
| DOORS                   | 3.5463                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                  | 6.1204                        | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                 | 3.1566                        | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM       | .3858                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC    | 1.0236                        | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS      | -.0009                        | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.      | 3.3912                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES    | .3627                         | SEATS INSTALLED                                     |
| HVAC                    | 1.3357                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL        | .5516                         | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS      | 3.1295                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL      | .0767                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL          | 1.0321                        | FINISHED VEHICLE SHIPPED                            |
| ROOF                    | 1.5475                        |   |
| SEATS                   | 8.6919                        |   |
| STEERING                | 1.4669                        |   |
| STEP PLT./EXT. ASST.    | 2.2828                        |   |
| TRANSMISSION            | 7.4986                        |   |
| UNDER BODY              | 3.6829                        |   |
| WHEELS & TIRES          | 2.7945                        |   |
| WIPER & WASHER          | .1135                         |   |
| TOTAL US CONTENT        | 55.9845                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL C20943  
 SILVERADO  
 CARLINE 01CP  
 ASSEMBLY LOC: FLINT LIGHT

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | .2386                         | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED       | .2864                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS      | .9583                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                  | .6558                         | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES        | .4809                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE             | .2286                         | BODY PRIMED AND SEALED                              |
| DOORS                   | 3.2299                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                  | 10.0720                       | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                 | 6.2508                        | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM       | .1501                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC    | 1.1298                        | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS      | .2718                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.      | 4.0821                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES    | .2548                         | SEATS INSTALLED                                     |
| HVAC                    | 2.2479                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL        | .6136                         | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS      | 2.5718                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL      | .2711                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL          | .5124                         | FINISHED VEHICLE SHIPPED                            |
| ROOF                    | .8365                         |   |
| SEATS                   | 5.9273                        |   |
| STEERING                | 2.7102                        |   |
| STEP PLT./EXT. ASST.    | .7210                         |   |
| TRANSMISSION            | 7.7615                        |   |
| UNDER BODY              | 2.6845                        |   |
| WHEELS & TIRES          | 2.5926                        |   |
| WIPER & WASHER          | .1297                         |   |
| TOTAL US CONTENT        | 57.8713                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL C20953  
 SIERRA  
 CARLINE 01CP  
 ASSEMBLY LOC: PONTIAC

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | .2119                         | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED       | .2661                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS      | 1.1108                        | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                  | .6697                         | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES        | .4722                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE             | .1884                         | BODY PRIMED AND SEALED                              |
| DOORS                   | 2.9827                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                  | 8.8681                        | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                 | 8.0721                        | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM       | .1466                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC    | 1.1589                        | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS      | .3397                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.      | 4.6540                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES    | .2575                         | SEATS INSTALLED                                     |
| HVAC                    | 2.2450                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL        | .6304                         | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS      | 2.2185                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL      | .2510                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL          | .4764                         | FINISHED VEHICLE SHIPPED                            |
| ROOF                    | .9069                         |   |
| SEATS                   | 5.1674                        |   |
| STEERING                | 2.7861                        |   |
| STEP PLT./EXT. ASST.    | .7068                         |   |
| TRANSMISSION            | 8.0740                        |   |
| UNDER BODY              | 2.7726                        |   |
| WHEELS & TIRES          | 2.6700                        |   |
| WI PER & WASHER         | .2559                         |   |
| TOTAL US CONTENT        | 58.5612                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL C30903  
 SIERRA  
 CARLINE 01CP  
 ASSEMBLY LOC: PONTIAC

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | 1.0574                        | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED       | .2951                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS      | .8965                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                  | .6891                         | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES        | .4356                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE             | .1286                         | BODY PRIMED AND SEALED                              |
| DOORS                   | 1.5650                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                  | 9.6366                        | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                 | 11.4879                       | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM       | .0741                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC    | 1.2379                        | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS      | .2759                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.      | 4.1175                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES    | .4332                         | SEATS INSTALLED                                     |
| HVAC                    | 2.5025                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL        | .6682                         | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS      | 1.3449                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL      | .0870                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL          | .4881                         | FINISHED VEHICLE SHIPPED                            |
| ROOF                    | .6936                         |   |
| SEATS                   | 3.7131                        |   |
| STEERING                | 2.9547                        |   |
| STEP PLT./EXT. ASST.    | .2811                         |   |
| TRANSMISSION            | 8.6638                        |   |
| UNDER BODY              | 1.9026                        |   |
| WHEELS & TIRES          | 1.9172                        |   |
| WIPER & WASHER          | .2715                         |   |
| TOTAL US CONTENT        | 57.8202                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL C30943  
 SILVERADO  
 CARLINE 01CP  
 ASSEMBLY LOC: FLINT LIGHT

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | .2052                         | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED       | .3512                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS      | .8324                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                  | .5702                         | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES        | .4095                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE             | .2259                         | BODY PRIMED AND SEALED                              |
| DOORS                   | 2.7022                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                  | 16.9818                       | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                 | 2.3809                        | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM       | .1072                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC    | .9950                         | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS      | .2376                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.      | 3.6625                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES    | .3638                         | SEATS INSTALLED                                     |
| HVAC                    | 2.1978                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL        | .5261                         | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS      | 1.9490                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL      | .1640                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL          | .5737                         | FINISHED VEHICLE SHIPPED                            |
| ROOF                    | .7842                         |   |
| SEATS                   | 5.2541                        |   |
| STEERING                | 2.3363                        |   |
| STEP PLT./EXT. ASST.    | .4809                         |   |
| TRANSMISSION            | 6.1892                        |   |
| UNDER BODY              | 2.3147                        |   |
| WHEELS & TIRES          | 3.0723                        |   |
| WI PER & WASHER         | .1193                         |   |
| TOTAL US CONTENT        | 55.9885                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL C30953  
 SIERRA  
 CARLINE 01CP  
 ASSEMBLY LOC: PONTIAC

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | .1835                         | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED       | .3206                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS      | .9488                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                  | .5814                         | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES        | .3602                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE             | .2417                         | BODY PRIMED AND SEALED                              |
| DOORS                   | 2.6645                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                  | 15.3889                       | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                 | 3.9039                        | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM       | .1129                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC    | 1.0207                        | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS      | .2629                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.      | 3.5816                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES    | .3251                         | SEATS INSTALLED                                     |
| HVAC                    | 2.1077                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL        | .5359                         | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS      | 1.5777                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL      | .2073                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL          | .4514                         | FINISHED VEHICLE SHIPPED                            |
| ROOF                    | .8479                         |   |
| SEATS                   | 4.7845                        |   |
| STEERING                | 2.3840                        |   |
| STEP PLT./EXT. ASST.    | .6873                         |   |
| TRANSMISSION            | 6.4287                        |   |
| UNDER BODY              | 2.5769                        |   |
| WHEELS & TIRES          | 2.6477                        |   |
| WIPER & WASHER          | .2252                         |   |
| TOTAL US CONTENT        | 55.3600                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL C31053  
 SIERRA  
 CARLINE 01CP  
 ASSEMBLY LOC: PONTIAC

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | .1718                         | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED       | .3332                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS      | .9169                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                  | .5462                         | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES        | .3869                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE             | .1699                         | BODY PRIMED AND SEALED                              |
| DOORS                   | 2.1964                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                  | 17.8704                       | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                 | 4.7792                        | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM       | .0682                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC    | .9741                         | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS      | .2605                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.      | 3.9328                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES    | 1.5565                        | SEATS INSTALLED                                     |
| HVAC                    | 2.1960                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL        | .5182                         | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS      | 1.1331                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL      | .0698                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL          | .4116                         | FINISHED VEHICLE SHIPPED                            |
| ROOF                    | .7775                         |   |
| SEATS                   | 4.5121                        |   |
| STEERING                | 2.2832                        |   |
| STEP PLT./EXT. ASST.    | .1674                         |   |
| TRANSMISSION            | 6.0937                        |   |
| UNDER BODY              | 1.7671                        |   |
| WHEELS & TIRES          | 3.0817                        |   |
| WIPER & WASHER          | .2107                         |   |
| TOTAL US CONTENT        | 57.3864                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL C31403  
 SIERRA  
 CARLINE 01CP  
 ASSEMBLY LOC: PONTIAC

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | .2333                                  | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED                | .3168                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS               | .9456                                  | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                           | .6543                                  | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES                 | .4912                                  | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE                      | .1263                                  | BODY PRIMED AND SEALED                              |
| DOORS                            | 1.4335                                 | EXTERIOR PAINT APPLIED                              |
| ENGINE                           | 13.1187                                | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                          | 4.1760                                 | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM                | .0744                                  | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC             | 1.1454                                 | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS               | .3146                                  | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.               | 4.7244                                 | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES             | 1.9256                                 | SEATS INSTALLED                                     |
| HVAC                             | 2.5248                                 | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL                 | .6195                                  | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS               | 1.2447                                 | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL               | .0815                                  | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL                   | .4599                                  | FINISHED VEHICLE SHIPPED                            |
| ROOF                             | .6483                                  |   |
| SEATS                            | 3.3622                                 |   |
| STEERING                         | 2.7322                                 |   |
| STEP PLT./EXT. ASST.             | .1711                                  |   |
| TRANSMISSION                     | 7.7642                                 |   |
| UNDER BODY                       | 1.7478                                 |   |
| WHEELS & TIRES                   | 3.3243                                 |   |
| WIPER & WASHER                   | .2512                                  |   |
| TOTAL US CONTENT                 | 54.6133                                |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL G13405  
 FSV GMC SAVANA  
 CARLINE 08  
 ASSEMBLY LOC: WENTZVILLE

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | . 9770                                 | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED                | . 2962                                 | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS               | . 4683                                 | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                           | 2. 1472                                | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES                 | . 6561                                 | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE                      | . 0795                                 | BODY PRIMED AND SEALED                              |
| DOORS                            | 7. 0826                                | EXTERIOR PAINT APPLIED                              |
| ENGINE                           | 15. 1448                               | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                          | 4. 2195                                | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM                | . 0311                                 | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC             | 1. 7729                                | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS               | . 1239                                 | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.               | 3. 4339                                | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES             | 1. 9822                                | SEATS INSTALLED                                     |
| HVAC                             | 3. 5648                                | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL                 | 1. 6237                                | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS               | 3. 1914                                | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL               | . 0208                                 | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL                   | . 5600                                 | FINISHED VEHICLE SHIPPED                            |
| ROOF                             | 1. 5113                                |   |
| SEATS                            | 3. 9623                                |   |
| STEERING                         | 1. 8222                                |   |
| STEP PLT./EXT. ASST.             | 1. 3738                                |   |
| TRANSMISSION                     | 1. 9503                                |   |
| UNDER BODY                       | 9. 4507                                |   |
| WHEELS & TIRES                   | 3. 7033                                |   |
| WIPER & WASHER                   | . 0813                                 |   |
| TOTAL US CONTENT                 | 71. 2324                               |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL G13406  
 FSV GMC SAVANA  
 CARLINE 08  
 ASSEMBLY LOC: WENTZVILLE

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | .7625                         | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED       | .2349                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS      | 1.6189                        | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                  | 1.9952                        | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES        | .5120                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE             | .0828                         | BODY PRIMED AND SEALED                              |
| DOORS                   | 5.4447                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                  | 12.8521                       | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                 | 3.4721                        | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM       | .0353                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC    | 1.3872                        | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS      | .0525                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.      | 5.2360                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES    | 1.5806                        | SEATS INSTALLED                                     |
| HVAC                    | 3.8268                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL        | 1.3109                        | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS      | 5.1558                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MISC MTRL       | .0154                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL          | .4599                         | FINISHED VEHICLE SHIPPED                            |
| ROOF                    | 2.5726                        |   |
| SEATS                   | 7.6243                        |   |
| STEERING                | 1.6129                        |   |
| STEP PLT./EXT. ASST.    | 1.1297                        |   |
| TRANSMISSION            | 2.0223                        |   |
| UNDER BODY              | 7.9121                        |   |
| WHEELS & TIRES          | 2.8852                        |   |
| WI PER & WASHER         | .0641                         |   |
| TOTAL US CONTENT        | 71.8601                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL G23405  
 FSV GMC SAVANA  
 CARLINE 08  
 ASSEMBLY LOC: WENTZVILLE

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | .8924                                  | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED                | .2811                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS               | .3524                                  | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                           | 1.7440                                 | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES                 | .6079                                  | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE                      | .0677                                  | BODY PRIMED AND SEALED                              |
| DOORS                            | 6.4443                                 | EXTERIOR PAINT APPLIED                              |
| ENGINE                           | 15.1027                                | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                          | 1.2672                                 | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM                | .0289                                  | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC             | 1.6417                                 | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS               | .1163                                  | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.               | 7.9082                                 | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES             | 1.8559                                 | SEATS INSTALLED                                     |
| HVAC                             | 2.8915                                 | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL                 | 1.5001                                 | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS               | 2.9354                                 | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL               | .0359                                  | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL                   | .5743                                  | FINISHED VEHICLE SHIPPED                            |
| ROOF                             | 1.4080                                 |   |
| SEATS                            | 2.0657                                 |   |
| STEERING                         | 3.1128                                 |   |
| STEP PLT./EXT. ASST.             | 1.2935                                 |   |
| TRANSMISSION                     | 9.1413                                 |   |
| UNDER BODY                       | 9.0770                                 |   |
| WHEELS & TIRES                   | 3.9488                                 |   |
| WIPER & WASHER                   | .0753                                  |   |
| TOTAL US CONTENT                 | 76.3717                                |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL G23406  
 FSV GMC SAVANA  
 CARLINE 08  
 ASSEMBLY LOC: WENTZVILLE

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | . 7233                        | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED       | . 2264                        | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS      | 1. 5049                       | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                  | 1. 7349                       | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES        | . 4927                        | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE             | . 0703                        | BODY PRIMED AND SEALED                              |
| DOORS                   | 5. 3070                       | EXTERIOR PAINT APPLIED                              |
| ENGINE                  | 6. 2431                       | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                 | 1. 5520                       | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM       | . 0357                        | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC    | 1. 3277                       | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS      | . 0543                        | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.      | 7. 6076                       | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES    | 1. 4789                       | SEATS INSTALLED                                     |
| HVAC                    | 3. 5637                       | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL        | 1. 2493                       | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS      | 4. 8986                       | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL      | . 0581                        | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL          | . 4406                        | FINISHED VEHICLE SHIPPED                            |
| ROOF                    | 2. 3599                       |   |
| SEATS                   | 8. 0517                       |   |
| STEERING                | 2. 7609                       |   |
| STEP PLT./EXT. ASST.    | 1. 1070                       |   |
| TRANSMISSION            | 7. 4065                       |   |
| UNDER BODY              | 7. 9458                       |   |
| WHEELS & TIRES          | 3. 1433                       |   |
| WIPER & WASHER          | . 0617                        |   |
| TOTAL US CONTENT        | 71. 4072                      |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL G23705  
 FSV GMC SAVANA  
 CARLINE 08  
 ASSEMBLY LOC: WENTZVILLE

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | .3438                                  | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED                | .2790                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS               | .3433                                  | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                           | 1.7221                                 | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES                 | .5918                                  | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE                      | .0696                                  | BODY PRIMED AND SEALED                              |
| DOORS                            | 6.2228                                 | EXTERIOR PAINT APPLIED                              |
| ENGINE                           | 13.9626                                | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                          | 1.3754                                 | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM                | .0325                                  | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC             | 1.5982                                 | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS               | .0985                                  | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.               | 7.4988                                 | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES             | 1.8443                                 | SEATS INSTALLED                                     |
| HVAC                             | 2.9338                                 | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL                 | 1.5023                                 | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS               | 3.0242                                 | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL               | .0545                                  | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL                   | .5549                                  | FINISHED VEHICLE SHIPPED                            |
| ROOF                             | 1.7699                                 |   |
| SEATS                            | 2.0159                                 |   |
| STEERING                         | 3.0649                                 |   |
| STEP PLT./EXT. ASST.             | 1.2792                                 |   |
| TRANSMISSION                     | 8.8993                                 |   |
| UNDER BODY                       | 9.1549                                 |   |
| WHEELS & TIRES                   | 3.7740                                 |   |
| WIPER & WASHER                   | .0733                                  |   |
| TOTAL US CONTENT                 | 74.0847                                |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL G33405  
 FSV GMC SAVANA  
 CARLINE 08  
 ASSEMBLY LOC: WENTZVILLE

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | .8927                         | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED       | .2868                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS      | .3489                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                  | 1.7461                        | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES        | .6081                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE             | .0684                         | BODY PRIMED AND SEALED                              |
| DOORS                   | 6.3563                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                  | 10.3952                       | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                 | 1.2604                        | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM       | .0353                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC    | 1.6388                        | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS      | .1069                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.      | 6.6086                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES    | 1.8572                        | SEATS INSTALLED                                     |
| HVAC                    | 2.8976                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL        | 1.5670                        | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS      | 2.9313                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL      | .0929                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL          | .6461                         | FINISHED VEHICLE SHIPPED                            |
| ROOF                    | 1.4056                        |   |
| SEATS                   | 2.1066                        |   |
| STEERING                | 3.1458                        |   |
| STEP PLT./EXT. ASST.    | 1.3135                        |   |
| TRANSMISSION            | 9.1502                        |   |
| UNDER BODY              | 9.1390                        |   |
| WHEELS & TIRES          | 4.0104                        |   |
| WIPER & WASHER          | .0762                         |   |
| TOTAL US CONTENT        | 70.6933                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL G33406  
 FSV GMC SAVANA  
 CARLINE 08  
 ASSEMBLY LOC: WENTZVILLE

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | . 7153                                 | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED                | . 2238                                 | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS               | 1. 4482                                | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                           | 1. 7139                                | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES                 | . 4873                                 | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE                      | . 0724                                 | BODY PRIMED AND SEALED                              |
| DOORS                            | 5. 2705                                | EXTERIOR PAINT APPLIED                              |
| ENGINE                           | 6. 1764                                | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                          | 1. 3574                                | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM                | . 0336                                 | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC             | 1. 3157                                | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS               | . 0444                                 | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.               | 7. 5385                                | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES             | 1. 4627                                | SEATS INSTALLED                                     |
| HVAC                             | 3. 5500                                | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL                 | 1. 2358                                | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS               | 4. 9133                                | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL               | . 0830                                 | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL                   | . 4433                                 | FINISHED VEHICLE SHIPPED                            |
| ROOF                             | 2. 3465                                |   |
| SEATS                            | 8. 5239                                |   |
| STEERING                         | 2. 7577                                |   |
| STEP PLT./EXT. ASST.             | 1. 1063                                |   |
| TRANSMISSION                     | 7. 3273                                |   |
| UNDER BODY                       | 7. 9789                                |   |
| WHEELS & TIRES                   | 3. 1885                                |   |
| WIPER & WASHER                   | . 0604                                 |   |
| TOTAL US CONTENT                 | 71. 3765                               |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL G33503  
 FSV GMC SAVANA  
 CARLINE 08  
 ASSEMBLY LOC: WENTZVILLE

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | .8696                         | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED       | .3391                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS      | .3721                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                  | 1.5396                        | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES        | .6212                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE             | .0466                         | BODY PRIMED AND SEALED                              |
| DOORS                   | 2.7210                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                  | 15.9583                       | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                 | 1.4404                        | EXTERIOR MOLDINGS INSTALLED                         |
| F. SHEET MET/PLASTIC    | 1.6764                        | AIR CONDITIONING AND HEATER INSTALLED               |
| FRONT & REAR LAMPS      | .0909                         | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR SUSP.      | 8.2499                        | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FUEL TANK/PUMP/LINES    | 1.9786                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| HVAC                    | 3.2728                        | SEATS INSTALLED                                     |
| INSTRUMENT PANEL        | 1.5424                        | SUB FRAME AND ENGINE INSTALLED                      |
| MAJOR METAL PANELS      | 1.1290                        | TRANSMISSION INSTALLED                              |
| PAINT & MISC MTRL       | .0489                         | TIRES MOUNTED AND INSTALLED                         |
| POWER & SIGNAL          | .6060                         | VEHICLE TESTED AND INSPECTED                        |
| ROOF                    | .7375                         | FINISHED VEHICLE SHIPPED                            |
| SEATS                   | 1.8557                        |   |
| STEERING                | 3.2089                        |   |
| STEP PLT./EXT. ASST.    | .6965                         |   |
| TRANSMISSION            | 9.4177                        |   |
| UNDER BODY              | 6.9520                        |   |
| WHEELS & TIRES          | 3.5751                        |   |
| WIPER & WASHER          | .0777                         |   |
| TOTAL US CONTENT        | 69.0251                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL G33705  
 FSV GMC SAVANA  
 CARLINE 08  
 ASSEMBLY LOC: WENTZVILLE

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | .3237                         | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED       | .3080                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS      | .3211                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                  | 1.6097                        | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES        | .5574                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE             | .0633                         | BODY PRIMED AND SEALED                              |
| DOORS                   | 5.8045                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                  | 13.7536                       | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                 | 1.1597                        | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM       | .0361                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC    | 1.5072                        | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS      | .0713                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.      | 5.6225                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES    | 1.9270                        | SEATS INSTALLED                                     |
| HVAC                    | 3.0777                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL        | 1.4293                        | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS      | 2.8555                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL      | .0859                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL          | .6863                         | FINISHED VEHICLE SHIPPED                            |
| ROOF                    | 1.6823                        |   |
| SEATS                   | 1.9525                        |   |
| STEERING                | 2.9016                        |   |
| STEP PLT./EXT. ASST.    | 1.2247                        |   |
| TRANSMISSION            | 8.4430                        |   |
| UNDER BODY              | 8.5670                        |   |
| WHEELS & TIRES          | 3.3663                        |   |
| WIPER & WASHER          | .0690                         |   |
| TOTAL US CONTENT        | 69.4078                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL G33706  
 FSV GMC SAVANA  
 CARLINE 08  
 ASSEMBLY LOC: WENTZVILLE

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | .2742                                  | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED                | .2171                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS               | 1.4205                                 | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                           | 1.6730                                 | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES                 | .4719                                  | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE                      | .0679                                  | BODY PRIMED AND SEALED                              |
| DOORS                            | 5.0983                                 | EXTERIOR PAINT APPLIED                              |
| ENGINE                           | 5.9792                                 | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                          | 1.2058                                 | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM                | .0321                                  | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC             | 1.2716                                 | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS               | .0393                                  | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.               | 7.2997                                 | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES             | 1.4297                                 | SEATS INSTALLED                                     |
| HVAC                             | 3.7398                                 | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL                 | 1.2096                                 | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS               | 3.1011                                 | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL               | .0664                                  | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL                   | .4248                                  | FINISHED VEHICLE SHIPPED                            |
| ROOF                             | 2.7022                                 |   |
| SEATS                            | 10.2984                                |   |
| STEERING                         | 2.6653                                 |   |
| STEP PLT./EXT. ASST.             | 1.0984                                 |   |
| TRANSMISSION                     | 7.0883                                 |   |
| UNDER BODY                       | 8.2048                                 |   |
| WHEELS & TIRES                   | 3.0405                                 |   |
| WIPER & WASHER                   | .0591                                  |   |
| TOTAL US CONTENT                 | 70.1801                                |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL G33803  
 FSV GMC SAVANA  
 CARLINE 08  
 ASSEMBLY LOC: WENTZVILLE

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | .2331                         | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED       | .3333                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS      | .3605                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                  | 1.7960                        | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES        | .5858                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE             | .0376                         | BODY PRIMED AND SEALED                              |
| DOORS                   | 2.2363                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                  | 15.5036                       | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                 | 1.2865                        | EXTERIOR MOLDINGS INSTALLED                         |
| F. SHEET MET/PLASTIC    | 1.5847                        | AIR CONDITIONING AND HEATER INSTALLED               |
| FRONT & REAR LAMPS      | .0737                         | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR SUSP.      | 8.2244                        | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FUEL TANK/PUMP/LINES    | 2.2678                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| HVAC                    | 3.2458                        | SEATS INSTALLED                                     |
| INSTRUMENT PANEL        | 1.4947                        | SUB FRAME AND ENGINE INSTALLED                      |
| MAJOR METAL PANELS      | 1.0538                        | TRANSMISSION INSTALLED                              |
| PAINT & MISC MTRL       | .0520                         | TIRES MOUNTED AND INSTALLED                         |
| POWER & SIGNAL          | .6492                         | VEHICLE TESTED AND INSPECTED                        |
| ROOF                    | .6937                         | FINISHED VEHICLE SHIPPED                            |
| SEATS                   | 1.4872                        |   |
| STEERING                | 3.0573                        |   |
| STEP PLT./EXT. ASST.    | .6734                         |   |
| TRANSMISSION            | 8.8992                        |   |
| UNDER BODY              | 6.9159                        |   |
| WHEELS & TIRES          | 3.6343                        |   |
| WIPER & WASHER          | .0726                         |   |
| TOTAL US CONTENT        | 66.4539                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL G33903  
 FSV GMC SAVANA  
 CARLINE 08  
 ASSEMBLY LOC: WENTZVILLE

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | .2035                         | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED       | .3062                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS      | .3683                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                  | 1.8799                        | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES        | .6074                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE             | .0585                         | BODY PRIMED AND SEALED                              |
| DOORS                   | 3.1364                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                  | 12.1614                       | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                 | 1.4973                        | EXTERIOR MOLDINGS INSTALLED                         |
| F. SHEET MET/PLASTIC    | 1.6379                        | AIR CONDITIONING AND HEATER INSTALLED               |
| FRONT & REAR LAMPS      | .1030                         | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR SUSP.      | 9.4353                        | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FUEL TANK/PUMP/LINES    | 2.1659                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| HVAC                    | 3.0161                        | SEATS INSTALLED                                     |
| INSTRUMENT PANEL        | 1.5483                        | SUB FRAME AND ENGINE INSTALLED                      |
| MAJOR METAL PANELS      | 1.1173                        | TRANSMISSION INSTALLED                              |
| PAINT & MISC MTRL       | .0422                         | TIRES MOUNTED AND INSTALLED                         |
| POWER & SIGNAL          | .5110                         | VEHICLE TESTED AND INSPECTED                        |
| ROOF                    | .7114                         | FINISHED VEHICLE SHIPPED                            |
| SEATS                   | 2.1321                        |   |
| STEERING                | 3.1134                        |   |
| STEP PLT./EXT. ASST.    | .6632                         |   |
| TRANSMISSION            | 9.1765                        |   |
| UNDER BODY              | 6.9908                        |   |
| WHEELS & TIRES          | 3.6780                        |   |
| WIPER & WASHER          | .0760                         |   |
| TOTAL US CONTENT        | 66.3387                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL H13405  
 FSV GMC SAVANA  
 CARLINE 08  
 ASSEMBLY LOC: WENTZVILLE

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | 2.5206                        | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED       | .2582                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS      | .3955                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                  | 1.8539                        | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES        | .5559                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE             | .0869                         | BODY PRIMED AND SEALED                              |
| DOORS                   | 6.2137                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                  | 14.6858                       | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                 | 4.0887                        | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM       | .0492                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC    | 1.5079                        | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS      | .0633                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.      | 6.2779                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES    | 1.7777                        | SEATS INSTALLED                                     |
| HVAC                    | 3.2221                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL        | 1.3984                        | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS      | 2.9322                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL      | .1091                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL          | .5076                         | FINISHED VEHICLE SHIPPED                            |
| ROOF                    | 1.3228                        |   |
| SEATS                   | 3.3518                        |   |
| STEERING                | 1.5704                        |   |
| STEP PLT./EXT. ASST.    | 1.2140                        |   |
| TRANSMISSION            | 5.2883                        |   |
| UNDER BODY              | 8.0858                        |   |
| WHEELS & TIRES          | 3.1605                        |   |
| WIPER & WASHER          | .0689                         |   |
| TOTAL US CONTENT        | 72.5685                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL H13406  
 FSV GMC SAVANA  
 CARLINE 08  
 ASSEMBLY LOC: WENTZVILLE

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | 2.1405                        | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED       | .2184                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS      | 1.3896                        | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                  | 1.8401                        | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES        | .4720                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE             | .0716                         | BODY PRIMED AND SEALED                              |
| DOORS                   | 5.0617                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                  | 11.8761                       | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                 | 3.4501                        | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM       | .0374                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC    | 1.2802                        | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS      | .0319                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.      | 6.4964                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES    | 1.4894                        | SEATS INSTALLED                                     |
| HVAC                    | 3.5346                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL        | 1.2061                        | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS      | 4.7485                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL      | .0699                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL          | .4259                         | FINISHED VEHICLE SHIPPED                            |
| ROOF                    | 2.3627                        |   |
| SEATS                   | 7.4891                        |   |
| STEERING                | 1.4896                        |   |
| STEP PLT./EXT. ASST.    | 1.0585                        |   |
| TRANSMISSION            | 4.4909                        |   |
| UNDER BODY              | 7.6955                        |   |
| WHEELS & TIRES          | 2.7624                        |   |
| WIPER & WASHER          | .0593                         |   |
| TOTAL US CONTENT        | 73.2499                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL K10543  
 SIERRA  
 CARLINE 01CP  
 ASSEMBLY LOC: SILAO

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | 1.5153                        | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED       | .6160                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS      | 1.1078                        | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                  | 1.6573                        | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES        | .3327                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE             | .4340                         | BODY PRIMED AND SEALED                              |
| DOORS                   | 2.1126                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                  | 7.7036                        | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                 | 2.7486                        | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM       | .1093                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC    | .5879                         | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS      | .2086                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.      | 3.6719                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES    | .9840                         | SEATS INSTALLED                                     |
| HVAC                    | 1.5458                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL        | .5557                         | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS      | 2.9267                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL      | .1358                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL          | .4615                         | FINISHED VEHICLE SHIPPED                            |
| ROOF                    | 1.1536                        |   |
| SEATS                   | .2828                         |   |
| STEERING                | 1.0558                        |   |
| STEP PLT./EXT. ASST.    | .9138                         |   |
| TRANSMISSION            | 7.0124                        |   |
| UNDER BODY              | 2.6178                        |   |
| WHEELS & TIRES          | 2.1940                        |   |
| WIPER & WASHER          | .1985                         |   |
| TOTAL US CONTENT        | 44.8453                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL K10553  
 SILVERADO  
 CARLINE 01CP  
 ASSEMBLY LOC: FORT WAYNE

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | 1.3245                        | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED       | .2287                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS      | 1.2236                        | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                  | 1.6453                        | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES        | .4152                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE             | .4043                         | BODY PRIMED AND SEALED                              |
| DOORS                   | 3.2775                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                  | 12.1926                       | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                 | 3.1187                        | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM       | .1041                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC    | 1.0730                        | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS      | .2685                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.      | 3.4656                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES    | .9491                         | SEATS INSTALLED                                     |
| HVAC                    | 1.6251                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL        | .5743                         | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS      | 2.1318                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL      | .1468                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL          | .5292                         | FINISHED VEHICLE SHIPPED                            |
| ROOF                    | 1.0424                        |   |
| SEATS                   | 6.0714                        |   |
| STEERING                | 1.0752                        |   |
| STEP PLT./EXT. ASST.    | .8737                         |   |
| TRANSMISSION            | 4.9613                        |   |
| UNDER BODY              | 2.6762                        |   |
| WHEELS & TIRES          | 2.6109                        |   |
| WIPER & WASHER          | .1346                         |   |
| TOTAL US CONTENT        | 54.1451                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL K10753  
 SIERRA  
 CARLINE 01CP  
 ASSEMBLY LOC: PONTIAC

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | 1.8870                                 | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED                | .2243                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS               | 1.1059                                 | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                           | 1.6365                                 | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES                 | .4069                                  | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE                      | .3163                                  | BODY PRIMED AND SEALED                              |
| DOORS                            | 3.2032                                 | EXTERIOR PAINT APPLIED                              |
| ENGINE                           | 11.9852                                | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                          | 3.1753                                 | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM                | .1032                                  | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC             | 1.0314                                 | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS               | .2643                                  | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.               | 3.9830                                 | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES             | .9415                                  | SEATS INSTALLED                                     |
| HVAC                             | 1.6879                                 | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL                 | .5711                                  | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS               | 2.2838                                 | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL               | .1397                                  | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL                   | .4937                                  | FINISHED VEHICLE SHIPPED                            |
| ROOF                             | .9793                                  |   |
| SEATS                            | 3.9337                                 |   |
| STEERING                         | 1.0257                                 |   |
| STEP PLT./EXT. ASST.             | .8444                                  |   |
| TRANSMISSION                     | 4.9210                                 |   |
| UNDER BODY                       | 2.8393                                 |   |
| WHEELS & TIRES                   | 1.9187                                 |   |
| WIPER & WASHER                   | .2058                                  |   |
| TOTAL US CONTENT                 | 52.1095                                |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL K10903  
 SILVERADO  
 CARLINE 01CP  
 ASSEMBLY LOC: PONTIAC

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | 2.9119                        | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED       | .2750                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS      | .7902                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                  | 1.6112                        | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES        | .5142                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE             | .2231                         | BODY PRIMED AND SEALED                              |
| DOORS                   | 2.3264                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                  | 12.9872                       | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                 | 3.6029                        | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM       | .1055                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC    | 1.1382                        | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS      | .3255                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.      | 3.9133                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES    | .2270                         | SEATS INSTALLED                                     |
| HVAC                    | 2.2874                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL        | .6232                         | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS      | 2.3006                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL      | .1412                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL          | .4853                         | FINISHED VEHICLE SHIPPED                            |
| ROOF                    | .7913                         |   |
| SEATS                   | 4.1539                        |   |
| STEERING                | 1.2318                        |   |
| STEP PLT./EXT. ASST.    | .7463                         |   |
| TRANSMISSION            | 4.8735                        |   |
| UNDER BODY              | 2.4133                        |   |
| WHEELS & TIRES          | 1.5861                        |   |
| WI PER & WASHER         | .1952                         |   |
| TOTAL US CONTENT        | 52.7821                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL K10936  
 CHEVY AVALANCHE  
 CARLINE 01CU  
 ASSEMBLY LOC: SILAO

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | .4192                         | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED       | .8477                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS      | .9792                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                  | 1.2361                        | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES        | .3476                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE             | .7521                         | BODY PRIMED AND SEALED                              |
| DOORS                   | 2.0743                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                  | 6.8683                        | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                 | 2.0470                        | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM       | .0280                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC    | .1091                         | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS      | .2519                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.      | 3.8769                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES    | .2198                         | SEATS INSTALLED                                     |
| HVAC                    | .8523                         | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL        | .6606                         | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS      | 2.6578                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL      | .1530                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL          | .3703                         | FINISHED VEHICLE SHIPPED                            |
| ROOF                    | 1.2971                        |   |
| SEATS                   | .1005                         |   |
| STEERING                | 1.1671                        |   |
| STEP PLT./EXT. ASST.    | .4854                         |   |
| TRANSMISSION            | 4.4302                        |   |
| UNDER BODY              | 3.1705                        |   |
| WHEELS & TIRES          | 2.2128                        |   |
| WIPER & WASHER          | .1145                         |   |
| TOTAL US CONTENT        | 37.7305                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL K10953  
 SILVERADO  
 CARLINE 01CP  
 ASSEMBLY LOC: PONTIAC

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | 2.1344                        | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED       | .2244                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS      | 1.0405                        | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                  | 1.3494                        | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES        | .3555                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE             | .2293                         | BODY PRIMED AND SEALED                              |
| DOORS                   | 3.0295                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                  | 12.3346                       | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                 | 3.0791                        | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM       | .1046                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC    | 1.0672                        | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS      | .2895                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.      | 3.5706                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES    | .2050                         | SEATS INSTALLED                                     |
| HVAC                    | 1.7585                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL        | .5614                         | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS      | 2.2341                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL      | .1452                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL          | .4730                         | FINISHED VEHICLE SHIPPED                            |
| ROOF                    | .9345                         |   |
| SEATS                   | 5.4800                        |   |
| STEERING                | 1.0122                        |   |
| STEP PLT./EXT. ASST.    | .8574                         |   |
| TRANSMISSION            | 4.5447                        |   |
| UNDER BODY              | 2.6295                        |   |
| WHEELS & TIRES          | 1.6612                        |   |
| WIPER & WASHER          | .2358                         |   |
| TOTAL US CONTENT        | 51.5426                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL K20743  
 SILVERADO  
 CARLINE 01CP  
 ASSEMBLY LOC: FLINT LIGHT

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | 1.1543                        | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED       | .3450                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS      | .7070                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                  | 1.7808                        | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES        | .3306                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE             | .3899                         | BODY PRIMED AND SEALED                              |
| DOORS                   | 2.9098                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                  | 16.0458                       | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                 | 2.8035                        | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM       | .1169                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC    | .8777                         | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS      | .2058                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.      | 4.8333                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES    | .1934                         | SEATS INSTALLED                                     |
| HVAC                    | 1.6298                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL        | .4448                         | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS      | 2.0273                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL      | .1697                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL          | .4955                         | FINISHED VEHICLE SHIPPED                            |
| ROOF                    | .9870                         |   |
| SEATS                   | 5.4577                        |   |
| STEERING                | 2.1101                        |   |
| STEP PLT./EXT. ASST.    | .7880                         |   |
| TRANSMISSION            | 7.4908                        |   |
| UNDER BODY              | 2.5940                        |   |
| WHEELS & TIRES          | 2.5711                        |   |
| WI PER & WASHER         | .1276                         |   |
| TOTAL US CONTENT        | 59.5884                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL K20753  
 SILVERADO  
 CARLINE 01CP  
 ASSEMBLY LOC: PONTIAC

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | .8165                         | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED       | .2861                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS      | .9314                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                  | 2.0503                        | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES        | .3257                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE             | .2733                         | BODY PRIMED AND SEALED                              |
| DOORS                   | 2.8807                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                  | 9.4987                        | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                 | 5.5083                        | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM       | .1303                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC    | 1.0021                        | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS      | .2684                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.      | 5.5499                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES    | .1451                         | SEATS INSTALLED                                     |
| HVAC                    | 1.7606                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL        | .5287                         | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS      | 1.9995                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL      | .1937                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL          | .4617                         | FINISHED VEHICLE SHIPPED                            |
| ROOF                    | .9182                         |   |
| SEATS                   | 5.1630                        |   |
| STEERING                | 2.4542                        |   |
| STEP PLT./EXT. ASST.    | .8431                         |   |
| TRANSMISSION            | 9.1349                        |   |
| UNDER BODY              | 2.5808                        |   |
| WHEELS & TIRES          | 2.5638                        |   |
| WIPER & WASHER          | .2264                         |   |
| TOTAL US CONTENT        | 58.4967                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL K20903  
 SILVERADO  
 CARLINE 01CP  
 ASSEMBLY LOC: PONTIAC

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | 2.4118                        | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED       | .3315                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS      | .7919                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                  | .6568                         | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES        | .4315                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE             | .1490                         | BODY PRIMED AND SEALED                              |
| DOORS                   | 1.9745                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                  | 8.6919                        | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                 | 7.0621                        | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM       | .1472                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC    | 1.1425                        | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS      | .3217                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.      | 6.6707                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES    | .2458                         | SEATS INSTALLED                                     |
| HVAC                    | 2.3835                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL        | .6183                         | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS      | 2.1832                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL      | .2107                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL          | .4754                         | FINISHED VEHICLE SHIPPED                            |
| ROOF                    | .6891                         |   |
| SEATS                   | 3.6311                        |   |
| STEERING                | 2.7264                        |   |
| STEP PLT./EXT. ASST.    | .8057                         |   |
| TRANSMISSION            | 10.3142                       |   |
| UNDER BODY              | 2.4107                        |   |
| WHEELS & TIRES          | 2.6979                        |   |
| WIPER & WASHER          | .2505                         |   |
| TOTAL US CONTENT        | 60.4270                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL K20906  
 GMC YUKON XL  
 CARLINE 01CU  
 ASSEMBLY LOC: ARLINGTON

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | .4551                         | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED       | .2205                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS      | .7330                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                  | 1.4433                        | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES        | .3750                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE             | .5010                         | BODY PRIMED AND SEALED                              |
| DOORS                   | 3.2637                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                  | 5.7273                        | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                 | 2.9278                        | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM       | .3480                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC    | .9507                         | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS      | .0082                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.      | 5.5976                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES    | .3387                         | SEATS INSTALLED                                     |
| HVAC                    | 1.2538                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL        | .5093                         | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS      | 2.9166                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL      | .0101                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL          | .6419                         | FINISHED VEHICLE SHIPPED                            |
| ROOF                    | 1.5700                        |   |
| SEATS                   | 6.9799                        |   |
| STEERING                | 1.3652                        |   |
| STEP PLT./EXT. ASST.    | 2.1161                        |   |
| TRANSMISSION            | 9.6781                        |   |
| UNDER BODY              | 3.6084                        |   |
| WHEELS & TIRES          | 2.5485                        |   |
| WIPER & WASHER          | .1165                         |   |
| TOTAL US CONTENT        | 56.2059                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL K20943  
 SILVERADO  
 CARLINE 01CP  
 ASSEMBLY LOC: FLINT LIGHT

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | .7900                         | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED       | .3192                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS      | .7912                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                  | .5693                         | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES        | .3635                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE             | .3237                         | BODY PRIMED AND SEALED                              |
| DOORS                   | 3.1243                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                  | 12.9457                       | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                 | 4.5120                        | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM       | .1322                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC    | .9858                         | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS      | .2393                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.      | 5.6529                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES    | .2535                         | SEATS INSTALLED                                     |
| HVAC                    | 1.8957                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL        | .5182                         | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS      | 2.3345                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL      | .1927                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL          | .5845                         | FINISHED VEHICLE SHIPPED                            |
| ROOF                    | .8797                         |   |
| SEATS                   | 5.6593                        |   |
| STEERING                | 2.3239                        |   |
| STEP PLT./EXT. ASST.    | .7803                         |   |
| TRANSMISSION            | 8.6816                        |   |
| UNDER BODY              | 2.6385                        |   |
| WHEELS & TIRES          | 2.6043                        |   |
| WIPER & WASHER          | .1239                         |   |
| TOTAL US CONTENT        | 60.2211                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL K20953  
 SILVERADO  
 CARLINE 01CP  
 ASSEMBLY LOC: PONTIAC

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|-------------------------------|---|
| AXLE & HALF SHAFT                | 2.4246                        | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED                | .2731                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS               | .9378                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                           | .6000                         | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES                 | .3490                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE                      | .2296                         | BODY PRIMED AND SEALED                              |
| DOORS                            | 2.8872                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                           | 9.3457                        | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                          | 7.4403                        | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM                | .1351                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC             | 1.0411                        | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS               | .2848                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.               | 6.0859                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES             | .2236                         | SEATS INSTALLED                                     |
| HVAC                             | 1.9300                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL                 | .5571                         | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS               | 2.1462                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL               | .2037                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL                   | .4677                         | FINISHED VEHICLE SHIPPED                            |
| ROOF                             | .8748                         |   |
| SEATS                            | 5.0643                        |   |
| STEERING                         | 2.4671                        |   |
| STEP PLT./EXT. ASST.             | .8198                         |   |
| TRANSMISSION                     | 9.4314                        |   |
| UNDER BODY                       | 2.6318                        |   |
| WHEELS & TIRES                   | 2.5701                        |   |
| WIPER & WASHER                   | .2296                         |   |
| TOTAL US CONTENT                 | 61.6527                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL K30903  
 SILVERADO  
 CARLINE 01CP  
 ASSEMBLY LOC: PONTIAC

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | .8329                         | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED       | .3543                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS      | .7060                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                  | .5999                         | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES        | .3719                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE             | .1313                         | BODY PRIMED AND SEALED                              |
| DOORS                   | 1.7713                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                  | 14.8215                       | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                 | 4.9845                        | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM       | .1273                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC    | 1.0517                        | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS      | .2933                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.      | 5.9431                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES    | .3647                         | SEATS INSTALLED                                     |
| HVAC                    | 2.4476                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL        | .5610                         | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS      | 1.8228                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL      | .1657                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL          | .5028                         | FINISHED VEHICLE SHIPPED                            |
| ROOF                    | .6208                         |   |
| SEATS                   | 3.2852                        |   |
| STEERING                | 2.4678                        |   |
| STEP PLT./EXT. ASST.    | .6904                         |   |
| TRANSMISSION            | 8.9413                        |   |
| UNDER BODY              | 2.1559                        |   |
| WHEELS & TIRES          | 2.2004                        |   |
| WIPER & WASHER          | .2273                         |   |
| TOTAL US CONTENT        | 58.4442                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL K30943  
 SILVERADO  
 CARLINE 01CP  
 ASSEMBLY LOC: FLINT LIGHT

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | .5667                                  | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED                | .3933                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS               | .6225                                  | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                           | .4934                                  | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES                 | .3340                                  | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE                      | .3495                                  | BODY PRIMED AND SEALED                              |
| DOORS                            | 2.6903                                 | EXTERIOR PAINT APPLIED                              |
| ENGINE                           | 20.1563                                | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                          | 1.3887                                 | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM                | .1099                                  | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC             | .8610                                  | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS               | .1962                                  | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.               | 5.1045                                 | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES             | .3265                                  | SEATS INSTALLED                                     |
| HVAC                             | 1.8898                                 | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL                 | .4331                                  | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS               | 2.0036                                 | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL               | .1513                                  | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL                   | .6366                                  | FINISHED VEHICLE SHIPPED                            |
| ROOF                             | .9100                                  |   |
| SEATS                            | 5.1503                                 |   |
| STEERING                         | 1.9727                                 |   |
| STEP PLT./EXT. ASST.             | .6843                                  |   |
| TRANSMISSION                     | 6.8986                                 |   |
| UNDER BODY                       | 2.6287                                 |   |
| WHEELS & TIRES                   | 2.9395                                 |   |
| WIPER & WASHER                   | .1230                                  |   |
| TOTAL US CONTENT                 | 60.0156                                |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL K30953  
 SILVERADO  
 CARLINE 01CP  
 ASSEMBLY LOC: PONTIAC

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | 1.4503                        | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED       | .3388                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS      | .8371                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                  | .5497                         | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES        | .2875                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE             | .2275                         | BODY PRIMED AND SEALED                              |
| DOORS                   | 2.6353                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                  | 15.1731                       | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                 | 4.3906                        | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM       | .1158                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC    | .9657                         | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS      | .2410                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.      | 5.5029                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES    | .2891                         | SEATS INSTALLED                                     |
| HVAC                    | 2.0273                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL        | .5033                         | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS      | 1.8163                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL      | .1746                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL          | .4903                         | FINISHED VEHICLE SHIPPED                            |
| ROOF                    | .8533                         |   |
| SEATS                   | 4.7449                        |   |
| STEERING                | 2.2349                        |   |
| STEP PLT./EXT. ASST.    | .7745                         |   |
| TRANSMISSION            | 8.1894                        |   |
| UNDER BODY              | 2.4730                        |   |
| WHEELS & TIRES          | 2.3607                        |   |
| WIPER & WASHER          | .2176                         |   |
| TOTAL US CONTENT        | 59.8659                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL K31003  
 SILVERADO  
 CARLINE 01CP  
 ASSEMBLY LOC: PONTIAC

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | .8966                         | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED       | .3535                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS      | .8943                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                  | .6194                         | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES        | .4124                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE             | .1305                         | BODY PRIMED AND SEALED                              |
| DOORS                   | 1.3677                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                  | 12.2404                       | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                 | 5.0274                        | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM       | .0688                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC    | 1.0808                        | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS      | .2984                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.      | 7.1074                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES    | 1.8505                        | SEATS INSTALLED                                     |
| HVAC                    | 2.4024                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL        | .5823                         | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS      | 1.1709                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL      | .0155                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL          | .4365                         | FINISHED VEHICLE SHIPPED                            |
| ROOF                    | .6471                         |   |
| SEATS                   | 3.2494                        |   |
| STEERING                | 2.5661                        |   |
| STEP PLT./EXT. ASST.    | .2074                         |   |
| TRANSMISSION            | 9.5073                        |   |
| UNDER BODY              | 1.6540                        |   |
| WHEELS & TIRES          | 3.1726                        |   |
| WIPER & WASHER          | .2364                         |   |
| TOTAL US CONTENT        | 58.1972                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL K31053  
 SILVERADO  
 CARLINE 01CP  
 ASSEMBLY LOC: PONTIAC

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | .6369                         | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED       | .3222                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS      | .8137                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                  | .5214                         | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES        | .2959                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE             | .1647                         | BODY PRIMED AND SEALED                              |
| DOORS                   | 2.0785                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                  | 17.3143                       | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                 | 4.1914                        | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM       | .0585                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC    | .9174                         | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS      | .2320                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.      | 5.8942                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES    | 1.6938                        | SEATS INSTALLED                                     |
| HVAC                    | 2.1147                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL        | .4790                         | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS      | 1.0550                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL      | .0148                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL          | .5279                         | FINISHED VEHICLE SHIPPED                            |
| ROOF                    | .7152                         |   |
| SEATS                   | 3.9623                        |   |
| STEERING                | 2.1256                        |   |
| STEP PLT./EXT. ASST.    | .2223                         |   |
| TRANSMISSION            | 7.6126                        |   |
| UNDER BODY              | 1.7047                        |   |
| WHEELS & TIRES          | 2.9512                        |   |
| WI PER & WASHER         | .1962                         |   |
| TOTAL US CONTENT        | 58.8177                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL K31403  
 SILVERADO  
 CARLINE 01CP  
 ASSEMBLY LOC: PONTIAC

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | .8190                                  | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED                | .4042                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS               | .8475                                  | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                           | .5947                                  | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES                 | .4061                                  | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE                      | .1087                                  | BODY PRIMED AND SEALED                              |
| DOORS                            | 1.3061                                 | EXTERIOR PAINT APPLIED                              |
| ENGINE                           | 14.8757                                | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                          | 3.1463                                 | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM                | .0662                                  | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC             | 1.0415                                 | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS               | .2775                                  | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.               | 6.7907                                 | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES             | 1.8489                                 | SEATS INSTALLED                                     |
| HVAC                             | 2.4222                                 | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL                 | .5564                                  | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS               | 1.1194                                 | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL               | .0165                                  | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL                   | .4394                                  | FINISHED VEHICLE SHIPPED                            |
| ROOF                             | .6048                                  |   |
| SEATS                            | 3.1208                                 |   |
| STEERING                         | 2.4505                                 |   |
| STEP PLT./EXT. ASST.             | .2194                                  |   |
| TRANSMISSION                     | 8.9061                                 |   |
| UNDER BODY                       | 1.5720                                 |   |
| WHEELS & TIRES                   | 3.1143                                 |   |
| WIPER & WASHER                   | .2260                                  |   |
| TOTAL US CONTENT                 | 57.3021                                |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL N15306  
 HUMMER H3  
 CARLINE 12SP  
 ASSEMBLY LOC: SHREVEPORT

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | 1.6811                        | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED       | .3732                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS      | .7725                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                  | .7867                         | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES        | .2388                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE             | 1.4982                        | BODY PRIMED AND SEALED                              |
| DOORS                   | 4.6310                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                  | 17.7430                       | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                 | 3.0096                        | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM       | .3891                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC    | 1.1694                        | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS      | .0832                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.      | 3.6045                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES    | .9254                         | SEATS INSTALLED                                     |
| HVAC                    | 2.1428                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL        | 1.5183                        | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS      | 3.1748                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL      | .1525                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL          | 3.2928                        | FINISHED VEHICLE SHIPPED                            |
| ROOF                    | 1.6066                        |   |
| SEATS                   | 2.6784                        |   |
| STEERING                | .2551                         |   |
| STEP PLT./EXT. ASST.    | 1.3977                        |   |
| TRANSMISSION            | 9.0825                        |   |
| UNDER BODY              | 8.6859                        |   |
| WHEELS & TIRES          | 3.3647                        |   |
| WIPER & WASHER          | .2176                         |   |
| TOTAL US CONTENT        | 74.4769                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL N15543  
 HUMMER H3T  
 CARLINE 12SP  
 ASSEMBLY LOC: SHREVEPORT

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|-------------------------------|---|
| AXLE & HALF SHAFT                | 1.1028                        | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED                | .3550                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS               | .7688                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                           | .5203                         | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES                 | .2293                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE                      | 1.8991                        | BODY PRIMED AND SEALED                              |
| DOORS                            | 4.0988                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                           | 16.9947                       | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                          | 2.6814                        | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM                | .4281                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC             | 1.1283                        | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS               | .0581                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.               | 2.5783                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES             | 1.3427                        | SEATS INSTALLED                                     |
| HVAC                             | 2.0729                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL                 | 1.5111                        | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS               | 4.0465                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL               | .1476                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL                   | 2.7107                        | FINISHED VEHICLE SHIPPED                            |
| ROOF                             | 1.7997                        |   |
| SEATS                            | 3.2826                        |   |
| STEERING                         | .6719                         |   |
| STEP PLT./EXT. ASST.             | 2.1068                        |   |
| TRANSMISSION                     | 8.9823                        |   |
| UNDER BODY                       | 6.8519                        |   |
| WHEELS & TIRES                   | 3.4066                        |   |
| WIPER & WASHER                   | .1498                         |   |
| TOTAL US CONTENT                 | 71.9273                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL N25706  
 HUMMER H2  
 CARLINE 15  
 ASSEMBLY LOC: MI SHAWAKA

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|-------------------------------|---|
| AXLE & HALF SHAFT                | . 7396                        | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED                | . 3583                        | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS               | 1. 1135                       | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                           | . 2906                        | HOOD, DOORS AND FENDERS INSTALLED                   |
| CONVENIENCE                      | . 9099                        | FRONT AND REAR DOORS INSTALLED                      |
| DOORS                            | 5. 0839                       | BODY PRIMED AND SEALED                              |
| ENGINE                           | 6. 9179                       | EXTERIOR PAINT APPLIED                              |
| EXHAUST                          | 1. 9626                       | ELECTRICAL WIRING INSTALLED                         |
| EXT. TRIM & ORNAM                | . 0568                        | EXTERIOR MOLDINGS INSTALLED                         |
| F. SHEET MET/PLASTIC             | 2. 3812                       | AIR CONDITIONING AND HEATER INSTALLED               |
| FRONT & REAR LAMPS               | . 1556                        | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR SUSP.               | 4. 1323                       | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FUEL TANK/PUMP/LINES             | 1. 1678                       | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| HVAC                             | 1. 2982                       | SEATS INSTALLED                                     |
| INSTRUMENT PANEL                 | 1. 0787                       | SUB FRAME AND ENGINE INSTALLED                      |
| MAJOR METAL PANELS               | 2. 8408                       | TRANSMISSION INSTALLED                              |
| PAINT & MISC MTRL                | . 0140                        | TIRES MOUNTED AND INSTALLED                         |
| POWER & SIGNAL                   | 4. 1975                       | VEHICLE TESTED AND INSPECTED                        |
| ROOF                             | 2. 7019                       | FINISHED VEHICLE SHIPPED                            |
| SEATS                            | 8. 8291                       |   |
| STEERING                         | 1. 7873                       |   |
| STEP PLT./EXT. ASST.             | . 8195                        |   |
| TRANSMISSION                     | 6. 8450                       |   |
| UNDER BODY                       | 3. 5752                       |   |
| WHEELS & TIRES                   | 3. 9567                       |   |
| WIPER & WASHER                   | . 2199                        |   |
| TOTAL US CONTENT                 | 63. 4350                      |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL N25736  
 HUMMER H2  
 CARLINE 15  
 ASSEMBLY LOC: MI SHAWAKA

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|-------------------------------|---|
| AXLE & HALF SHAFT                | .6746                         | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED                | .3268                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS               | .8853                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                           | .2657                         | HOOD, DOORS AND FENDERS INSTALLED                   |
| CONVENIENCE                      | 1.0788                        | FRONT AND REAR DOORS INSTALLED                      |
| DOORS                            | 4.1883                        | BODY PRIMED AND SEALED                              |
| ENGINE                           | 6.1340                        | EXTERIOR PAINT APPLIED                              |
| EXHAUST                          | 1.7897                        | ELECTRICAL WIRING INSTALLED                         |
| EXT. TRIM & ORNAM                | -.2139                        | EXTERIOR MOLDINGS INSTALLED                         |
| F. SHEET MET/PLASTIC             | 2.6423                        | AIR CONDITIONING AND HEATER INSTALLED               |
| FRONT & REAR LAMPS               | .1477                         | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR SUSP.               | 3.7439                        | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FUEL TANK/PUMP/LINES             | 1.1612                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| HVAC                             | 1.2477                        | SEATS INSTALLED                                     |
| INSTRUMENT PANEL                 | .9861                         | SUB FRAME AND ENGINE INSTALLED                      |
| MAJOR METAL PANELS               | 3.1951                        | TRANSMISSION INSTALLED                              |
| PAINT & MISC MTRL                | .0091                         | TIRES MOUNTED AND INSTALLED                         |
| POWER & SIGNAL                   | 3.2567                        | VEHICLE TESTED AND INSPECTED                        |
| ROOF                             | 2.5601                        | FINISHED VEHICLE SHIPPED                            |
| SEATS                            | 7.0695                        |   |
| STEERING                         | 1.6294                        |   |
| STEP PLT./EXT. ASST.             | .8434                         |   |
| TRANSMISSION                     | 6.0051                        |   |
| UNDER BODY                       | 12.5254                       |   |
| WHEELS & TIRES                   | 3.7784                        |   |
| WIPER & WASHER                   | .1098                         |   |
| TOTAL US CONTENT                 | 66.0413                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL R14526  
 CHEVY TRAVERSE  
 CARLINE 17  
 ASSEMBLY LOC: SPRING HILL

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | .6032                         | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED       | .5181                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS      | .8380                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                  | 1.5134                        | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES        | .1474                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE             | .7454                         | BODY PRIMED AND SEALED                              |
| DOORS                   | 5.2596                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                  | 8.4040                        | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                 | 5.1520                        | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM       | .1825                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC    | 1.6272                        | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS      | .9820                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.      | 4.5442                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES    | 1.1607                        | SEATS INSTALLED                                     |
| HVAC                    | 2.3969                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL        | 1.6004                        | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS      | 3.3063                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL      | .0594                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL          | .7782                         | FINISHED VEHICLE SHIPPED                            |
| ROOF                    | 1.8502                        |   |
| SEATS                   | 5.6002                        |   |
| STEERING                | .8479                         |   |
| STEP PLT./EXT. ASST.    | 1.2248                        |   |
| TRANSMISSION            | 6.6295                        |   |
| UNDER BODY              | 5.7546                        |   |
| WHEELS & TIRES          | 1.2807                        |   |
| WIPER & WASHER          | .0941                         |   |
| TOTAL US CONTENT        | 63.1026                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL S15403  
 GMC CANYON  
 CARLINE 12SP  
 ASSEMBLY LOC: SHREVEPORT

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | . 7222                                 | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED                | . 6608                                 | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS               | 1. 5268                                | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                           | 1. 7019                                | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES                 | . 3517                                 | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE                      | 1. 0030                                | BODY PRIMED AND SEALED                              |
| DOORS                            | 2. 8801                                | EXTERIOR PAINT APPLIED                              |
| ENGINE                           | 24. 7639                               | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                          | 4. 2743                                | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM                | . 1277                                 | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC             | 1. 2524                                | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS               | . 0741                                 | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.               | 4. 1803                                | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES             | 1. 2347                                | SEATS INSTALLED                                     |
| HVAC                             | 1. 3022                                | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL                 | 1. 1081                                | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS               | 2. 8210                                | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL               | . 0116                                 | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL                   | . 9761                                 | FINISHED VEHICLE SHIPPED                            |
| ROOF                             | . 7500                                 |   |
| SEATS                            | 1. 1863                                |   |
| STEERING                         | . 2938                                 |   |
| STEP PLT./EXT. ASST.             | 1. 5290                                |   |
| TRANSMISSION                     | 4. 8914                                |   |
| UNDER BODY                       | 7. 5092                                |   |
| WHEELS & TIRES                   | 2. 6301                                |   |
| WIPER & WASHER                   | . 0088                                 |   |
| TOTAL US CONTENT                 | 69. 7729                               |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL S15603  
 GMC CANYON  
 CARLINE 12SP  
 ASSEMBLY LOC: SHREVEPORT

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | 1.1080                                 | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED                | .6835                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS               | 1.5941                                 | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                           | 1.8162                                 | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES                 | .3654                                  | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE                      | .8616                                  | BODY PRIMED AND SEALED                              |
| DOORS                            | 2.4574                                 | EXTERIOR PAINT APPLIED                              |
| ENGINE                           | 20.5467                                | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                          | 4.7688                                 | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM                | .1124                                  | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC             | 1.2982                                 | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS               | .1070                                  | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.               | 5.2289                                 | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES             | 1.1578                                 | SEATS INSTALLED                                     |
| HVAC                             | 2.3098                                 | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL                 | 1.1505                                 | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS               | 2.2271                                 | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL               | .1129                                  | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL                   | .9826                                  | FINISHED VEHICLE SHIPPED                            |
| ROOF                             | .7761                                  |   |
| SEATS                            | .9462                                  |   |
| STEERING                         | .3292                                  |   |
| STEP PLT./EXT. ASST.             | 1.1107                                 |   |
| TRANSMISSION                     | 6.4257                                 |   |
| UNDER BODY                       | 7.5871                                 |   |
| WHEELS & TIRES                   | 3.5233                                 |   |
| WIPER & WASHER                   | .0092                                  |   |
| TOTAL US CONTENT                 | 69.5978                                |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL S15643  
 GMC CANYON  
 CARLINE 12SP  
 ASSEMBLY LOC: SHREVEPORT

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | 1.1606                        | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED       | .5699                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS      | 1.7033                        | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                  | 1.4900                        | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES        | .3069                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE             | 1.5871                        | BODY PRIMED AND SEALED                              |
| DOORS                   | 4.4544                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                  | 19.5920                       | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                 | 3.9744                        | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM       | .1490                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC    | 1.0890                        | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS      | .0645                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.      | 3.7984                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES    | 1.0029                        | SEATS INSTALLED                                     |
| HVAC                    | 1.5638                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL        | .9614                         | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS      | 2.6435                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL      | .0236                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL          | .7828                         | FINISHED VEHICLE SHIPPED                            |
| ROOF                    | .8458                         |   |
| SEATS                   | 2.0082                        |   |
| STEERING                | .2815                         |   |
| STEP PLT./EXT. ASST.    | 1.2750                        |   |
| TRANSMISSION            | 5.3942                        |   |
| UNDER BODY              | 10.6461                       |   |
| WHEELS & TIRES          | 2.8029                        |   |
| WIPER & WASHER          | .0077                         |   |
| TOTAL US CONTENT        | 70.1802                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL S15653  
 GMC CANYON  
 CARLINE 12SP  
 ASSEMBLY LOC: SHREVEPORT

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | 1.2303                        | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED       | .5844                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS      | 1.6660                        | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                  | 1.5318                        | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES        | .3143                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE             | 1.4229                        | BODY PRIMED AND SEALED                              |
| DOORS                   | 3.8640                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                  | 21.0858                       | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                 | 4.0560                        | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM       | .1256                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC    | 1.1158                        | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS      | .0648                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.      | 3.8176                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES    | 1.0779                        | SEATS INSTALLED                                     |
| HVAC                    | 1.3800                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL        | .9888                         | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS      | 2.6800                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL      | .0142                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL          | .8305                         | FINISHED VEHICLE SHIPPED                            |
| ROOF                    | .6973                         |   |
| SEATS                   | 1.3501                        |   |
| STEERING                | .2800                         |   |
| STEP PLT./EXT. ASST.    | 1.4585                        |   |
| TRANSMISSION            | 4.5552                        |   |
| UNDER BODY              | 11.4765                       |   |
| WHEELS & TIRES          | 2.3907                        |   |
| WI PER & WASHER         | .0079                         |   |
| TOTAL US CONTENT        | 70.0685                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL T15403  
 GMC CANYON  
 CARLINE 12SP  
 ASSEMBLY LOC: SHREVEPORT

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | 1.5354                                 | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED                | .6029                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS               | 1.5091                                 | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                           | 1.5940                                 | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES                 | .3210                                  | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE                      | 1.2655                                 | BODY PRIMED AND SEALED                              |
| DOORS                            | 2.6632                                 | EXTERIOR PAINT APPLIED                              |
| ENGINE                           | 21.1587                                | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                          | 3.9643                                 | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM                | .1179                                  | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC             | 1.1856                                 | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS               | .0674                                  | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.               | 4.5396                                 | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES             | 1.0689                                 | SEATS INSTALLED                                     |
| HVAC                             | 1.4615                                 | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL                 | 1.0114                                 | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS               | 2.6123                                 | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL               | .0318                                  | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL                   | .8666                                  | FINISHED VEHICLE SHIPPED                            |
| ROOF                             | .6847                                  |   |
| SEATS                            | 1.0724                                 |   |
| STEERING                         | .2898                                  |   |
| STEP PLT./EXT. ASST.             | 1.4778                                 |   |
| TRANSMISSION                     | 4.3701                                 |   |
| UNDER BODY                       | 6.8983                                 |   |
| WHEELS & TIRES                   | 2.5947                                 |   |
| WIPER & WASHER                   | .0081                                  |   |
| TOTAL US CONTENT                 | 64.9743                                |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL T15603  
 GMC CANYON  
 CARLINE 12SP  
 ASSEMBLY LOC: SHREVEPORT

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | 2.0022                                 | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED                | .6252                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS               | 1.5040                                 | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                           | 1.6615                                 | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES                 | .3342                                  | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE                      | .8828                                  | BODY PRIMED AND SEALED                              |
| DOORS                            | 2.3668                                 | EXTERIOR PAINT APPLIED                              |
| ENGINE                           | 18.7647                                | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                          | 4.3618                                 | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM                | .1138                                  | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC             | 1.1872                                 | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS               | .0799                                  | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.               | 4.7826                                 | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES             | .9995                                  | SEATS INSTALLED                                     |
| HVAC                             | 2.1117                                 | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL                 | 1.0523                                 | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS               | 2.2872                                 | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL               | .1031                                  | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL                   | .9899                                  | FINISHED VEHICLE SHIPPED                            |
| ROOF                             | .7129                                  |   |
| SEATS                            | .4611                                  |   |
| STEERING                         | .3011                                  |   |
| STEP PLT./EXT. ASST.             | 1.2341                                 |   |
| TRANSMISSION                     | 5.7784                                 |   |
| UNDER BODY                       | 7.2089                                 |   |
| WHEELS & TIRES                   | 3.0202                                 |   |
| WIPER & WASHER                   | .0084                                  |   |
| TOTAL US CONTENT                 | 64.9369                                |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL T15643  
 GMC CANYON  
 CARLINE 12SP  
 ASSEMBLY LOC: SHREVEPORT

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | 1.8227                                 | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED                | .5394                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS               | 1.6529                                 | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                           | 1.4437                                 | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES                 | .2930                                  | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE                      | 1.5291                                 | BODY PRIMED AND SEALED                              |
| DOORS                            | 4.2957                                 | EXTERIOR PAINT APPLIED                              |
| ENGINE                           | 16.5321                                | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                          | 3.8534                                 | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM                | .2398                                  | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC             | 1.0818                                 | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS               | .0622                                  | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.               | 4.2201                                 | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES             | .8584                                  | SEATS INSTALLED                                     |
| HVAC                             | 1.9699                                 | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL                 | .9201                                  | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS               | 2.7598                                 | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL               | .0780                                  | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL                   | .6580                                  | FINISHED VEHICLE SHIPPED                            |
| ROOF                             | 1.0157                                 |   |
| SEATS                            | 2.7870                                 |   |
| STEERING                         | .2803                                  |   |
| STEP PLT./EXT. ASST.             | 1.1063                                 |   |
| TRANSMISSION                     | 5.1033                                 |   |
| UNDER BODY                       | 7.3260                                 |   |
| WHEELS & TIRES                   | 4.0621                                 |   |
| WIPER & WASHER                   | .0073                                  |   |
| TOTAL US CONTENT                 | 66.4996                                |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL T15653  
 GMC CANYON  
 CARLINE 12SP  
 ASSEMBLY LOC: SHREVEPORT

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | 1.9048                        | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED       | .5665                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS      | 1.6421                        | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                  | 1.5117                        | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES        | .3043                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE             | 1.4708                        | BODY PRIMED AND SEALED                              |
| DOORS                   | 3.7322                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                  | 18.7599                       | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                 | 3.9866                        | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM       | .1600                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC    | 1.1193                        | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS      | .0627                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.      | 4.3244                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES    | .9685                         | SEATS INSTALLED                                     |
| HVAC                    | 1.6474                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL        | .9583                         | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS      | 2.7012                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL      | .0801                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL          | .7346                         | FINISHED VEHICLE SHIPPED                            |
| ROOF                    | .7190                         |   |
| SEATS                   | 1.3427                        |   |
| STEERING                | .2800                         |   |
| STEP PLT./EXT. ASST.    | 1.4100                        |   |
| TRANSMISSION            | 4.8619                        |   |
| UNDER BODY              | 7.1563                        |   |
| WHEELS & TIRES          | 3.1137                        |   |
| WIPER & WASHER          | .0076                         |   |
| TOTAL US CONTENT        | 65.5281                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL V14526  
 CHEVY TRAVERSE  
 CARLINE 17  
 ASSEMBLY LOC: SPRING HILL

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | 1.9615                        | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED       | .4785                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS      | .8450                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                  | 1.3976                        | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES        | .1502                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE             | .9186                         | BODY PRIMED AND SEALED                              |
| DOORS                   | 4.9309                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                  | 7.7627                        | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                 | 4.8805                        | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM       | .1635                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC    | 1.5078                        | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS      | 1.0190                        | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.      | 5.6738                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES    | 1.0758                        | SEATS INSTALLED                                     |
| HVAC                    | 2.2403                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL        | 1.4751                        | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS      | 3.1117                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL      | .0782                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL          | .7434                         | FINISHED VEHICLE SHIPPED                            |
| ROOF                    | 2.1044                        |   |
| SEATS                   | 5.1390                        |   |
| STEERING                | .8204                         |   |
| STEP PLT./EXT. ASST.    | 1.1914                        |   |
| TRANSMISSION            | 7.3235                        |   |
| UNDER BODY              | 5.4619                        |   |
| WHEELS & TIRES          | 1.4173                        |   |
| WIPER & WASHER          | .0896                         |   |
| TOTAL US CONTENT        | 63.9631                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL ZLF26  
 SATURN VUE  
 CARLINE 7L  
 ASSEMBLY LOC: RAMOS

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | .0096                                  | UNDERBODY FRAMING ASSEMBLED AND WELDED              |
| BATTERY & RELATED                | .0060                                  | FLOOR PANEL WELDED TO UNDERBODY                     |
| BELTS & RESTRAINTS               | .9587                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BRAKES                           | .0572                                  | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| CONVENIENCE                      | .0245                                  | HOOD, DOORS AND FENDERS INSTALLED                   |
| DOORS                            | .4125                                  | FRONT AND REAR DOORS INSTALLED                      |
| ENGINE                           | 10.5067                                | BODY PRIMED AND SEALED                              |
| EXHAUST                          | .0013                                  | EXTERIOR PAINT APPLIED                              |
| EXT. TRIM & ORNAM                | .0054                                  | ELECTRICAL WIRING INSTALLED                         |
| F. SHEET MET/PLASTIC             | .1402                                  | EXTERIOR MOLDINGS INSTALLED                         |
| FRONT & REAR LAMPS               | .0034                                  | AIR CONDITIONING AND HEATER INSTALLED               |
| FRONT & REAR SUSP.               | 6.4542                                 | INSTRUMENT PANEL INSTALLED                          |
| FUEL TANK/PUMP/LINES             | .0035                                  | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| HVAC                             | .0219                                  | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| INSTRUMENT PANEL                 | .0021                                  | SEATS INSTALLED                                     |
| MAJOR METAL PANELS               | .0905                                  | SUB FRAME AND ENGINE INSTALLED                      |
| PAINT & MISC MTRL                | .0124                                  | TRANSMISSION INSTALLED                              |
| POWER & SIGNAL                   | .0368                                  | TIRES MOUNTED AND INSTALLED                         |
| ROOF                             | .0165                                  | VEHICLE TESTED AND INSPECTED                        |
| STEERING                         | .0419                                  | FINISHED VEHICLE SHIPPED                            |
| STEP PLT./EXT. ASST.             | .0804                                  |   |
| TRANSMISSION                     | 4.5224                                 |   |
| UNDER BODY                       | 1.2950                                 |   |
| WHEELS & TIRES                   | 3.3452                                 |   |
| WIPER & WASHER                   | .0473                                  |   |
| TOTAL US CONTENT                 | 28.0970                                |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL ZLG26  
 SATURN VUE  
 CARLINE 7L  
 ASSEMBLY LOC: RAMOS

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | .6381                                  | UNDERBODY FRAMING ASSEMBLED AND WELDED              |
| BATTERY & RELATED                | .0043                                  | FLOOR PANEL WELDED TO UNDERBODY                     |
| BELTS & RESTRAINTS               | .9148                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BRAKES                           | .0547                                  | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| CONVENIENCE                      | .0234                                  | HOOD, DOORS AND FENDERS INSTALLED                   |
| DOORS                            | .3856                                  | FRONT AND REAR DOORS INSTALLED                      |
| ENGINE                           | 4.3392                                 | BODY PRIMED AND SEALED                              |
| EXHAUST                          | .0127                                  | EXTERIOR PAINT APPLIED                              |
| EXT. TRIM & ORNAM                | -.0009                                 | ELECTRICAL WIRING INSTALLED                         |
| F. SHEET MET/PLASTIC             | .1243                                  | EXTERIOR MOLDINGS INSTALLED                         |
| FRONT & REAR LAMPS               | .0033                                  | AIR CONDITIONING AND HEATER INSTALLED               |
| FRONT & REAR SUSP.               | 9.4750                                 | INSTRUMENT PANEL INSTALLED                          |
| FUEL TANK/PUMP/LINES             | .0052                                  | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| HVAC                             | .0623                                  | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| INSTRUMENT PANEL                 | .0076                                  | SEATS INSTALLED                                     |
| MAJOR METAL PANELS               | .0850                                  | SUB FRAME AND ENGINE INSTALLED                      |
| PAINT & MISC MTRL                | .0136                                  | TRANSMISSION INSTALLED                              |
| POWER & SIGNAL                   | .0615                                  | TIRES MOUNTED AND INSTALLED                         |
| ROOF                             | .0087                                  | VEHICLE TESTED AND INSPECTED                        |
| STEERING                         | .2308                                  | FINISHED VEHICLE SHIPPED                            |
| STEP PLT./EXT. ASST.             | .0770                                  |   |
| TRANSMISSION                     | 7.2872                                 |   |
| UNDER BODY                       | 1.2531                                 |   |
| WHEELS & TIRES                   | 3.2008                                 |   |
| WIPER & WASHER                   | .0467                                  |   |
| TOTAL US CONTENT                 | 28.3149                                |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL ZLR26  
 SATURN VUE  
 CARLINE 7L  
 ASSEMBLY LOC: RAMOS

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|-------------------------------|---|
| AXLE & HALF SHAFT                | .6146                         | UNDERBODY FRAMING ASSEMBLED AND WELDED              |
| BATTERY & RELATED                | .0076                         | FLOOR PANEL WELDED TO UNDERBODY                     |
| BELTS & RESTRAINTS               | .9704                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BRAKES                           | .0530                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| CONVENIENCE                      | .0222                         | HOOD, DOORS AND FENDERS INSTALLED                   |
| DOORS                            | .3871                         | FRONT AND REAR DOORS INSTALLED                      |
| ENGINE                           | 4.9625                        | BODY PRIMED AND SEALED                              |
| EXHAUST                          | .0122                         | EXTERIOR PAINT APPLIED                              |
| EXT. TRIM & ORNAM                | .0195                         | ELECTRICAL WIRING INSTALLED                         |
| F. SHEET MET/PLASTIC             | .1292                         | EXTERIOR MOLDINGS INSTALLED                         |
| FRONT & REAR LAMPS               | .0032                         | AIR CONDITIONING AND HEATER INSTALLED               |
| FRONT & REAR SUSP.               | 6.4630                        | INSTRUMENT PANEL INSTALLED                          |
| FUEL TANK/PUMP/LINES             | .0016                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| HVAC                             | .0184                         | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| INSTRUMENT PANEL                 | .0024                         | SEATS INSTALLED                                     |
| MAJOR METAL PANELS               | .0836                         | SUB FRAME AND ENGINE INSTALLED                      |
| PAINT & MISC MTRL                | .0093                         | TRANSMISSION INSTALLED                              |
| POWER & SIGNAL                   | .0357                         | TIRES MOUNTED AND INSTALLED                         |
| ROOF                             | .0152                         | VEHICLE TESTED AND INSPECTED                        |
| STEERING                         | .0126                         | FINISHED VEHICLE SHIPPED                            |
| STEP PLT./EXT. ASST.             | .0748                         |   |
| TRANSMISSION                     | 5.5814                        |   |
| UNDER BODY                       | 1.2499                        |   |
| WHEELS & TIRES                   | 1.7498                        |   |
| WIPER & WASHER                   | .0554                         |   |
| TOTAL US CONTENT                 | 22.5357                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL ZLS26  
 SATURN VUE  
 CARLINE 7L  
 ASSEMBLY LOC: RAMOS

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | .5867                                  | UNDERBODY FRAMING ASSEMBLED AND WELDED              |
| BATTERY & RELATED                | .0067                                  | FLOOR PANEL WELDED TO UNDERBODY                     |
| BELTS & RESTRAINTS               | .9074                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BRAKES                           | .0503                                  | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| CONVENIENCE                      | .0217                                  | HOOD, DOORS AND FENDERS INSTALLED                   |
| DOORS                            | .4055                                  | FRONT AND REAR DOORS INSTALLED                      |
| ENGINE                           | 4.7024                                 | BODY PRIMED AND SEALED                              |
| EXHAUST                          | .0116                                  | EXTERIOR PAINT APPLIED                              |
| EXT. TRIM & ORNAM                | -.0013                                 | ELECTRICAL WIRING INSTALLED                         |
| F. SHEET MET/PLASTIC             | .1142                                  | EXTERIOR MOLDINGS INSTALLED                         |
| FRONT & REAR LAMPS               | .0030                                  | AIR CONDITIONING AND HEATER INSTALLED               |
| FRONT & REAR SUSP.               | 8.7169                                 | INSTRUMENT PANEL INSTALLED                          |
| FUEL TANK/PUMP/LINES             | .0015                                  | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| HVAC                             | .0269                                  | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| INSTRUMENT PANEL                 | .0073                                  | SEATS INSTALLED                                     |
| MAJOR METAL PANELS               | .0793                                  | SUB FRAME AND ENGINE INSTALLED                      |
| PAINT & MISC MTRL                | .0126                                  | TRANSMISSION INSTALLED                              |
| POWER & SIGNAL                   | .0385                                  | TIRES MOUNTED AND INSTALLED                         |
| ROOF                             | .0175                                  | VEHICLE TESTED AND INSPECTED                        |
| STEERING                         | .0119                                  | FINISHED VEHICLE SHIPPED                            |
| STEP PLT./EXT. ASST.             | .0704                                  |   |
| TRANSMISSION                     | 6.6550                                 |   |
| UNDER BODY                       | 1.1877                                 |   |
| WHEELS & TIRES                   | 1.5845                                 |   |
| WIPER & WASHER                   | .0601                                  |   |
| TOTAL US CONTENT                 | 25.2795                                |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL ZLT26  
 SATURN VUE  
 CARLINE 7L  
 ASSEMBLY LOC: RAMOS

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | .0075                                  | UNDERBODY FRAMING ASSEMBLED AND WELDED              |
| BATTERY & RELATED                | 7.3050                                 | FLOOR PANEL WELDED TO UNDERBODY                     |
| BELTS & RESTRAINTS               | .7449                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BRAKES                           | .7114                                  | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| CONVENIENCE                      | .0186                                  | HOOD, DOORS AND FENDERS INSTALLED                   |
| DOORS                            | .4208                                  | FRONT AND REAR DOORS INSTALLED                      |
| ENGINE                           | 9.4165                                 | BODY PRIMED AND SEALED                              |
| EXHAUST                          | .0010                                  | EXTERIOR PAINT APPLIED                              |
| F. SHEET MET/PLASTIC             | .0765                                  | ELECTRICAL WIRING INSTALLED                         |
| FRONT & REAR LAMPS               | .0027                                  | EXTERIOR MOLDINGS INSTALLED                         |
| FRONT & REAR SUSP.               | 5.0240                                 | AIR CONDITIONING AND HEATER INSTALLED               |
| FUEL TANK/PUMP/LINES             | .0027                                  | INSTRUMENT PANEL INSTALLED                          |
| HVAC                             | .0139                                  | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| INSTRUMENT PANEL                 | .0002                                  | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| MAJOR METAL PANELS               | .0856                                  | SEATS INSTALLED                                     |
| PAINT & MISCELLANEOUS            | .0149                                  | SUB FRAME AND ENGINE INSTALLED                      |
| POWER & SIGNAL                   | .0347                                  | TRANSMISSION INSTALLED                              |
| ROOF                             | .0147                                  | TIRES MOUNTED AND INSTALLED                         |
| STEERING                         | .0041                                  | VEHICLE TESTED AND INSPECTED                        |
| STEP PLT./EXT. ASST.             | .3492                                  | FINISHED VEHICLE SHIPPED                            |
| TRANSMISSION                     | 4.1733                                 |   |
| UNDER BODY                       | 1.0521                                 |   |
| WHEELS & TIRES                   | 1.2424                                 |   |
| WIPER & WASHER                   | .0701                                  |   |
| TOTAL US CONTENT                 | 30.7879                                |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL ZLU26  
 SATURN VUE  
 CARLINE 7L  
 ASSEMBLY LOC: RAMOS

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|-------------------------------|---|
| AXLE & HALF SHAFT                | .3246                         | UNDERBODY FRAMING ASSEMBLED AND WELDED              |
| BATTERY & RELATED                | 10.2388                       | FLOOR PANEL WELDED TO UNDERBODY                     |
| BELTS & RESTRAINTS               | .5089                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BRAKES                           | 4.0851                        | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| CONVENIENCE                      | .0119                         | HOOD, DOORS AND FENDERS INSTALLED                   |
| DOORS                            | .3673                         | FRONT AND REAR DOORS INSTALLED                      |
| ENGINE                           | 13.0124                       | BODY PRIMED AND SEALED                              |
| EXHAUST                          | .0258                         | EXTERIOR PAINT APPLIED                              |
| EXT. TRIM & ORNAM                | -.0002                        | ELECTRICAL WIRING INSTALLED                         |
| F. SHEET MET/PLASTIC             | .0575                         | EXTERIOR MOLDINGS INSTALLED                         |
| FRONT & REAR LAMPS               | .0016                         | AIR CONDITIONING AND HEATER INSTALLED               |
| FRONT & REAR SUSP.               | 3.1497                        | INSTRUMENT PANEL INSTALLED                          |
| FUEL TANK/PUMP/LINES             | .0008                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| HVAC                             | 1.8417                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| INSTRUMENT PANEL                 | .0044                         | SEATS INSTALLED                                     |
| MAJOR METAL PANELS               | .0525                         | SUB FRAME AND ENGINE INSTALLED                      |
| PAINT & MISC MTRL                | .0122                         | TRANSMISSION INSTALLED                              |
| POWER & SIGNAL                   | .0603                         | TIRES MOUNTED AND INSTALLED                         |
| ROOF                             | .0049                         | VEHICLE TESTED AND INSPECTED                        |
| STEERING                         | .0183                         | FINISHED VEHICLE SHIPPED                            |
| STEP PLT./EXT. ASST.             | .0010                         |   |
| TRANSMISSION                     | 11.5974                       |   |
| UNDER BODY                       | .9374                         |   |
| WHEELS & TIRES                   | .7691                         |   |
| WIPER & WASHER                   | .0553                         |   |
| TOTAL US CONTENT                 | 47.1400                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL ZZR69  
 SATURN AURA  
 CARLINE 3Z  
 ASSEMBLY LOC: FAIRFAX

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | .4686                                  | UNDERBODY FRAMING ASSEMBLED AND WELDED              |
| BATTERY & RELATED                | 8.0767                                 | FLOOR PANEL WELDED TO UNDERBODY                     |
| BELTS & RESTRAINTS               | .6348                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BRAKES                           | 1.4297                                 | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| CLUSTERS & GAGES                 | .0050                                  | HOOD, DOORS AND FENDERS INSTALLED                   |
| CONVENIENCE                      | 1.6508                                 | FRONT AND REAR DOORS INSTALLED                      |
| DOORS                            | 3.9197                                 | BODY PRIMED AND SEALED                              |
| ENGINE                           | 9.1319                                 | EXTERIOR PAINT APPLIED                              |
| EXHAUST                          | 5.7408                                 | ELECTRICAL WIRING INSTALLED                         |
| EXT. TRIM & ORNAM                | .0019                                  | EXTERIOR MOLDINGS INSTALLED                         |
| F. SHEET MET/PLASTIC             | .8591                                  | AIR CONDITIONING AND HEATER INSTALLED               |
| FRONT & REAR LAMPS               | .3053                                  | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR SUSP.               | 3.9370                                 | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FUEL TANK/PUMP/LINES             | 1.2844                                 | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| HVAC                             | 1.6255                                 | SEATS INSTALLED                                     |
| INSTRUMENT PANEL                 | 3.8631                                 | SUB FRAME AND ENGINE INSTALLED                      |
| MAJOR METAL PANELS               | 4.8812                                 | TRANSMISSION INSTALLED                              |
| PAINT & MI SC MTRL               | .0100                                  | TIRES MOUNTED AND INSTALLED                         |
| POWER & SIGNAL                   | .0453                                  | VEHICLE TESTED AND INSPECTED                        |
| ROOF                             | 1.3308                                 | FINISHED VEHICLE SHIPPED                            |
| SEATS                            | 4.8308                                 |   |
| STEERING                         | 1.1214                                 |   |
| STEP PLT./EXT. ASST.             | 1.2052                                 |   |
| TRANSMISSION                     | 4.1315                                 |   |
| UNDER BODY                       | 5.7982                                 |   |
| WHEELS & TIRES                   | 2.4614                                 |   |
| WIPER & WASHER                   | .1330                                  |   |
| TOTAL US CONTENT                 | 68.8845                                |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL ZZS69  
 SATURN AURA  
 CARLINE 3Z  
 ASSEMBLY LOC: FAIRFAX

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | .7824                         | UNDERBODY FRAMING ASSEMBLED AND WELDED              |
| BATTERY & RELATED       | .2171                         | FLOOR PANEL WELDED TO UNDERBODY                     |
| BELTS & RESTRAINTS      | .7912                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BRAKES                  | 1.4761                        | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| CLUSTERS & GAGES        | .0061                         | HOOD, DOORS AND FENDERS INSTALLED                   |
| CONVENIENCE             | 1.8792                        | FRONT AND REAR DOORS INSTALLED                      |
| DOORS                   | 4.7941                        | BODY PRIMED AND SEALED                              |
| ENGINE                  | 8.6668                        | EXTERIOR PAINT APPLIED                              |
| EXHAUST                 | 6.4124                        | ELECTRICAL WIRING INSTALLED                         |
| EXT. TRIM & ORNAM       | .0024                         | EXTERIOR MOLDINGS INSTALLED                         |
| F. SHEET MET/PLASTIC    | 1.0500                        | AIR CONDITIONING AND HEATER INSTALLED               |
| FRONT & REAR LAMPS      | .3766                         | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR SUSP.      | 4.8022                        | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FUEL TANK/PUMP/LINES    | 1.2812                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| HVAC                    | 1.8715                        | SEATS INSTALLED                                     |
| INSTRUMENT PANEL        | 4.7278                        | SUB FRAME AND ENGINE INSTALLED                      |
| MAJOR METAL PANELS      | 5.8384                        | TRANSMISSION INSTALLED                              |
| PAINT & MI SC MTRL      | .0087                         | TIRES MOUNTED AND INSTALLED                         |
| POWER & SIGNAL          | .0598                         | VEHICLE TESTED AND INSPECTED                        |
| ROOF                    | 1.0658                        | FINISHED VEHICLE SHIPPED                            |
| SEATS                   | 4.5879                        |   |
| STEERING                | 1.3724                        |   |
| STEP PLT./EXT. ASST.    | 1.4733                        |   |
| TRANSMISSION            | .3165                         |   |
| UNDER BODY              | 7.1550                        |   |
| WHEELS & TIRES          | 2.1695                        |   |
| WIPER & WASHER          | .1535                         |   |
| TOTAL US CONTENT        | 63.3394                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL ZZV69  
 SATURN AURA  
 CARLINE 3Z  
 ASSEMBLY LOC: FAIRFAX

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | . 7155                                 | UNDERBODY FRAMING ASSEMBLED AND WELDED              |
| BATTERY & RELATED                | . 2014                                 | FLOOR PANEL WELDED TO UNDERBODY                     |
| BELTS & RESTRAINTS               | . 8826                                 | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BRAKES                           | 1. 3742                                | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| CLUSTERS & GAGES                 | . 0057                                 | HOOD, DOORS AND FENDERS INSTALLED                   |
| CONVENIENCE                      | 1. 9165                                | FRONT AND REAR DOORS INSTALLED                      |
| DOORS                            | 4. 4443                                | BODY PRIMED AND SEALED                              |
| ENGINE                           | 7. 6715                                | EXTERIOR PAINT APPLIED                              |
| EXHAUST                          | 7. 2475                                | ELECTRICAL WIRING INSTALLED                         |
| EXT. TRIM & ORNAM                | . 0022                                 | EXTERIOR MOLDINGS INSTALLED                         |
| F. SHEET MET/PLASTIC             | . 9711                                 | AIR CONDITIONING AND HEATER INSTALLED               |
| FRONT & REAR LAMPS               | . 3431                                 | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR SUSP.               | 4. 4539                                | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FUEL TANK/PUMP/LINES             | 1. 1696                                | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| HVAC                             | 1. 9191                                | SEATS INSTALLED                                     |
| INSTRUMENT PANEL                 | 3. 7940                                | SUB FRAME AND ENGINE INSTALLED                      |
| MAJOR METAL PANELS               | 5. 4059                                | TRANSMISSION INSTALLED                              |
| PAINT & MI SC MTRL               | . 0081                                 | TIRES MOUNTED AND INSTALLED                         |
| POWER & SIGNAL                   | . 2334                                 | VEHICLE TESTED AND INSPECTED                        |
| ROOF                             | 1. 5344                                | FINISHED VEHICLE SHIPPED                            |
| SEATS                            | 6. 3698                                |   |
| STEERING                         | 1. 1237                                |   |
| STEP PLT./EXT. ASST.             | 1. 4091                                |   |
| TRANSMISSION                     | 1. 8588                                |   |
| UNDER BODY                       | 6. 7850                                |   |
| WHEELS & TIRES                   | 2. 9468                                |   |
| WIPER & WASHER                   | . 1421                                 |   |
| TOTAL US CONTENT                 | 64. 9305                               |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 1AJ37  
 CHEVY COBALT  
 CARLINE 3A  
 ASSEMBLY LOC: LORDSTOWN

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | . 7738                                 | UNDERBODY FRAMING ASSEMBLED AND WELDED              |
| BATTERY & RELATED                | . 3217                                 | FLOOR PANEL WELDED TO UNDERBODY                     |
| BELTS & RESTRAINTS               | . 6457                                 | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BRAKES                           | 1. 3373                                | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| CONVENIENCE                      | . 7916                                 | HOOD, DOORS AND FENDERS INSTALLED                   |
| DOORS                            | 3. 5264                                | FRONT AND REAR DOORS INSTALLED                      |
| ENGINE                           | 14. 0032                               | BODY PRIMED AND SEALED                              |
| EXHAUST                          | 4. 1151                                | EXTERIOR PAINT APPLIED                              |
| EXT. TRIM & ORNAM                | . 1256                                 | ELECTRICAL WIRING INSTALLED                         |
| F. SHEET MET/PLASTIC             | 1. 2566                                | EXTERIOR MOLDINGS INSTALLED                         |
| FRONT & REAR LAMPS               | . 0295                                 | AIR CONDITIONING AND HEATER INSTALLED               |
| FRONT & REAR SUSP.               | 2. 6103                                | INSTRUMENT PANEL INSTALLED                          |
| FUEL TANK/PUMP/LINES             | 1. 3084                                | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| HVAC                             | 3. 0959                                | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| INSTRUMENT PANEL                 | 1. 5157                                | SEATS INSTALLED                                     |
| MAJOR METAL PANELS               | 4. 2776                                | SUB FRAME AND ENGINE INSTALLED                      |
| PAINT & MISC MTRL                | . 0053                                 | TRANSMISSION INSTALLED                              |
| POWER & SIGNAL                   | . 5360                                 | TIRES MOUNTED AND INSTALLED                         |
| ROOF                             | . 7959                                 | VEHICLE TESTED AND INSPECTED                        |
| SEATS                            | 4. 4622                                | FINISHED VEHICLE SHIPPED                            |
| STEERING                         | . 1519                                 |   |
| STEP PLT./EXT. ASST.             | 2. 4557                                |   |
| TRANSMISSION                     | 4. 2809                                |   |
| UNDER BODY                       | 4. 2950                                |   |
| WHEELS & TIRES                   | 2. 1333                                |   |
| WIPER & WASHER                   | . 0715                                 |   |
| TOTAL US CONTENT                 | 58. 9235                               |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 1AJ69  
 CHEVY COBALT  
 CARLINE 3A  
 ASSEMBLY LOC: LORDSTOWN

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | .7485                                  | UNDERBODY FRAMING ASSEMBLED AND WELDED              |
| BATTERY & RELATED                | .3215                                  | FLOOR PANEL WELDED TO UNDERBODY                     |
| BELTS & RESTRAINTS               | .6422                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BRAKES                           | 1.3219                                 | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| CONVENIENCE                      | .8283                                  | HOOD, DOORS AND FENDERS INSTALLED                   |
| DOORS                            | 5.5322                                 | FRONT AND REAR DOORS INSTALLED                      |
| ENGINE                           | 13.7629                                | BODY PRIMED AND SEALED                              |
| EXHAUST                          | 4.0343                                 | EXTERIOR PAINT APPLIED                              |
| EXT. TRIM & ORNAM                | .0305                                  | ELECTRICAL WIRING INSTALLED                         |
| F. SHEET MET/PLASTIC             | 1.2175                                 | EXTERIOR MOLDINGS INSTALLED                         |
| FRONT & REAR LAMPS               | .0026                                  | AIR CONDITIONING AND HEATER INSTALLED               |
| FRONT & REAR SUSP.               | 2.5649                                 | INSTRUMENT PANEL INSTALLED                          |
| FUEL TANK/PUMP/LINES             | 1.2823                                 | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| HVAC                             | 3.4703                                 | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| INSTRUMENT PANEL                 | 2.5674                                 | SEATS INSTALLED                                     |
| MAJOR METAL PANELS               | 4.1129                                 | SUB FRAME AND ENGINE INSTALLED                      |
| PAINT & MISC MTRL                | .0051                                  | TRANSMISSION INSTALLED                              |
| POWER & SIGNAL                   | .4744                                  | TIRES MOUNTED AND INSTALLED                         |
| ROOF                             | .8412                                  | VEHICLE TESTED AND INSPECTED                        |
| SEATS                            | 4.2753                                 | FINISHED VEHICLE SHIPPED                            |
| STEERING                         | .1525                                  |   |
| STEP PLT./EXT. ASST.             | 2.2499                                 |   |
| TRANSMISSION                     | 5.4640                                 |   |
| UNDER BODY                       | 4.3243                                 |   |
| WHEELS & TIRES                   | 2.0954                                 |   |
| WIPER & WASHER                   | .0880                                  |   |
| TOTAL US CONTENT                 | 62.4118                                |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 1AK37  
 CHEVY COBALT  
 CARLINE 3A  
 ASSEMBLY LOC: LORDSTOWN

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | .7421                                  | UNDERBODY FRAMING ASSEMBLED AND WELDED              |
| BATTERY & RELATED                | .3059                                  | FLOOR PANEL WELDED TO UNDERBODY                     |
| BELTS & RESTRAINTS               | .8276                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BRAKES                           | 1.2479                                 | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| CONVENIENCE                      | .1756                                  | HOOD, DOORS AND FENDERS INSTALLED                   |
| DOORS                            | 3.5452                                 | FRONT AND REAR DOORS INSTALLED                      |
| ENGINE                           | 13.6022                                | BODY PRIMED AND SEALED                              |
| EXHAUST                          | 3.9403                                 | EXTERIOR PAINT APPLIED                              |
| EXT. TRIM & ORNAM                | .2074                                  | ELECTRICAL WIRING INSTALLED                         |
| F. SHEET MET/PLASTIC             | 1.1954                                 | EXTERIOR MOLDINGS INSTALLED                         |
| FRONT & REAR LAMPS               | .0286                                  | AIR CONDITIONING AND HEATER INSTALLED               |
| FRONT & REAR SUSP.               | 2.4807                                 | INSTRUMENT PANEL INSTALLED                          |
| FUEL TANK/PUMP/LINES             | 1.5797                                 | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| HVAC                             | 3.4748                                 | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| INSTRUMENT PANEL                 | 1.4411                                 | SEATS INSTALLED                                     |
| MAJOR METAL PANELS               | 4.0872                                 | SUB FRAME AND ENGINE INSTALLED                      |
| PAINT & MISC MTRL                | .0138                                  | TRANSMISSION INSTALLED                              |
| POWER & SIGNAL                   | .4149                                  | TIRES MOUNTED AND INSTALLED                         |
| ROOF                             | .8457                                  | VEHICLE TESTED AND INSPECTED                        |
| SEATS                            | 4.2437                                 | FINISHED VEHICLE SHIPPED                            |
| STEERING                         | .1445                                  |   |
| STEP PLT./EXT. ASST.             | 2.2764                                 |   |
| TRANSMISSION                     | 3.3858                                 |   |
| UNDER BODY                       | 4.1192                                 |   |
| WHEELS & TIRES                   | 2.2065                                 |   |
| WIPER & WASHER                   | .0679                                  |   |
| TOTAL US CONTENT                 | 56.6013                                |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 1AK69  
 CHEVY COBALT  
 CARLINE 3A  
 ASSEMBLY LOC: LORDSTOWN

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | . 7168                                 | UNDERBODY FRAMING ASSEMBLED AND WELDED              |
| BATTERY & RELATED                | . 3084                                 | FLOOR PANEL WELDED TO UNDERBODY                     |
| BELTS & RESTRAINTS               | . 7980                                 | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BRAKES                           | 1. 2613                                | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| CONVENIENCE                      | . 3244                                 | HOOD, DOORS AND FENDERS INSTALLED                   |
| DOORS                            | 5. 4696                                | FRONT AND REAR DOORS INSTALLED                      |
| ENGINE                           | 13. 4649                               | BODY PRIMED AND SEALED                              |
| EXHAUST                          | 3. 8859                                | EXTERIOR PAINT APPLIED                              |
| EXT. TRIM & ORNAM                | . 0841                                 | ELECTRICAL WIRING INSTALLED                         |
| F. SHEET MET/PLASTIC             | 1. 1613                                | EXTERIOR MOLDINGS INSTALLED                         |
| FRONT & REAR LAMPS               | -. 0023                                | AIR CONDITIONING AND HEATER INSTALLED               |
| FRONT & REAR SUSP.               | 2. 4525                                | INSTRUMENT PANEL INSTALLED                          |
| FUEL TANK/PUMP/LINES             | 1. 5982                                | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| HVAC                             | 3. 4790                                | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| INSTRUMENT PANEL                 | 2. 4547                                | SEATS INSTALLED                                     |
| MAJOR METAL PANELS               | 3. 9308                                | SUB FRAME AND ENGINE INSTALLED                      |
| PAINT & MISC MTRL                | . 0132                                 | TRANSMISSION INSTALLED                              |
| POWER & SIGNAL                   | . 4393                                 | TIRES MOUNTED AND INSTALLED                         |
| ROOF                             | . 8550                                 | VEHICLE TESTED AND INSPECTED                        |
| SEATS                            | 4. 0876                                | FINISHED VEHICLE SHIPPED                            |
| STEERING                         | . 1458                                 |   |
| STEP PLT./EXT. ASST.             | 2. 1863                                |   |
| TRANSMISSION                     | 5. 1040                                |   |
| UNDER BODY                       | 4. 1615                                |   |
| WHEELS & TIRES                   | 2. 0034                                |   |
| WIPER & WASHER                   | . 0894                                 |   |
| TOTAL US CONTENT                 | 60. 4740                               |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 1AL37  
 CHEVY COBALT  
 CARLINE 3A  
 ASSEMBLY LOC: LORDSTOWN

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | .6862                                  | UNDERBODY FRAMING ASSEMBLED AND WELDED              |
| BATTERY & RELATED                | .2903                                  | FLOOR PANEL WELDED TO UNDERBODY                     |
| BELTS & RESTRAINTS               | .8153                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BRAKES                           | 1.2482                                 | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| CONVENIENCE                      | .1243                                  | HOOD, DOORS AND FENDERS INSTALLED                   |
| DOORS                            | 3.3433                                 | FRONT AND REAR DOORS INSTALLED                      |
| ENGINE                           | 12.8121                                | BODY PRIMED AND SEALED                              |
| EXHAUST                          | 3.7384                                 | EXTERIOR PAINT APPLIED                              |
| EXT. TRIM & ORNAM                | .3426                                  | ELECTRICAL WIRING INSTALLED                         |
| F. SHEET MET/PLASTIC             | 1.1555                                 | EXTERIOR MOLDINGS INSTALLED                         |
| FRONT & REAR LAMPS               | .0280                                  | AIR CONDITIONING AND HEATER INSTALLED               |
| FRONT & REAR SUSP.               | 2.4178                                 | INSTRUMENT PANEL INSTALLED                          |
| FUEL TANK/PUMP/LINES             | 1.3953                                 | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| HVAC                             | 3.3305                                 | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| INSTRUMENT PANEL                 | 2.1784                                 | SEATS INSTALLED                                     |
| MAJOR METAL PANELS               | 3.8811                                 | SUB FRAME AND ENGINE INSTALLED                      |
| PAINT & MISC MTRL                | .0119                                  | TRANSMISSION INSTALLED                              |
| POWER & SIGNAL                   | .3944                                  | TIRES MOUNTED AND INSTALLED                         |
| ROOF                             | .9697                                  | VEHICLE TESTED AND INSPECTED                        |
| SEATS                            | 4.1878                                 | FINISHED VEHICLE SHIPPED                            |
| STEERING                         | .1371                                  |   |
| STEP PLT./EXT. ASST.             | 2.2197                                 |   |
| TRANSMISSION                     | 4.9816                                 |   |
| UNDER BODY                       | 4.4237                                 |   |
| WHEELS & TIRES                   | 1.8450                                 |   |
| WIPER & WASHER                   | .0653                                  |   |
| TOTAL US CONTENT                 | 57.0249                                |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 1AL69  
 CHEVY COBALT  
 CARLINE 3A  
 ASSEMBLY LOC: LORDSTOWN

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | .6755                                  | UNDERBODY FRAMING ASSEMBLED AND WELDED              |
| BATTERY & RELATED                | .2924                                  | FLOOR PANEL WELDED TO UNDERBODY                     |
| BELTS & RESTRAINTS               | .7883                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BRAKES                           | 1.2369                                 | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| CONVENIENCE                      | .1010                                  | HOOD, DOORS AND FENDERS INSTALLED                   |
| DOORS                            | 4.9112                                 | FRONT AND REAR DOORS INSTALLED                      |
| ENGINE                           | 12.7083                                | BODY PRIMED AND SEALED                              |
| EXHAUST                          | 3.6921                                 | EXTERIOR PAINT APPLIED                              |
| EXT. TRIM & ORNAM                | .1660                                  | ELECTRICAL WIRING INSTALLED                         |
| F. SHEET MET/PLASTIC             | 1.1184                                 | EXTERIOR MOLDINGS INSTALLED                         |
| FRONT & REAR SUSP.               | 2.3821                                 | INSTRUMENT PANEL INSTALLED                          |
| FUEL TANK/PUMP/LINES             | 1.4342                                 | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| HVAC                             | 3.3125                                 | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| INSTRUMENT PANEL                 | 2.3770                                 | SEATS INSTALLED                                     |
| MAJOR METAL PANELS               | 3.7331                                 | SUB FRAME AND ENGINE INSTALLED                      |
| PAINT & MIS C MTRL               | .0114                                  | TRANSMISSION INSTALLED                              |
| POWER & SIGNAL                   | .3930                                  | TIRES MOUNTED AND INSTALLED                         |
| ROOF                             | .9295                                  | VEHICLE TESTED AND INSPECTED                        |
| SEATS                            | 4.0580                                 | FINISHED VEHICLE SHIPPED                            |
| STEERING                         | .1385                                  |   |
| STEP PLT./EXT. ASST.             | 2.0622                                 |   |
| TRANSMISSION                     | 5.4022                                 |   |
| UNDER BODY                       | 4.3363                                 |   |
| WHEELS & TIRES                   | 1.8272                                 |   |
| WIPER & WASHER                   | .0824                                  |   |
| TOTAL US CONTENT                 | 58.1712                                |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 1AP37  
 CHEVY COBALT  
 CARLINE 3A  
 ASSEMBLY LOC: LORDSTOWN

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | .0100                                  | UNDERBODY FRAMING ASSEMBLED AND WELDED              |
| BATTERY & RELATED                | .2112                                  | FLOOR PANEL WELDED TO UNDERBODY                     |
| BELTS & RESTRAINTS               | .6420                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BRAKES                           | 1.7013                                 | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| CLUSTERS & GAGES                 | .0045                                  | HOOD, DOORS AND FENDERS INSTALLED                   |
| CONVENIENCE                      | .1439                                  | FRONT AND REAR DOORS INSTALLED                      |
| DOORS                            | 2.4549                                 | BODY PRIMED AND SEALED                              |
| ENGINE                           | 11.4437                                | EXTERIOR PAINT APPLIED                              |
| EXHAUST                          | 4.7239                                 | ELECTRICAL WIRING INSTALLED                         |
| EXT. TRIM & ORNAM                | .1522                                  | EXTERIOR MOLDINGS INSTALLED                         |
| F. SHEET MET/PLASTIC             | .8175                                  | AIR CONDITIONING AND HEATER INSTALLED               |
| FRONT & REAR LAMPS               | .0218                                  | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR SUSP.               | 3.1489                                 | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FUEL TANK/PUMP/LINES             | 1.1637                                 | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| HVAC                             | 3.6658                                 | SEATS INSTALLED                                     |
| INSTRUMENT PANEL                 | 1.8033                                 | SUB FRAME AND ENGINE INSTALLED                      |
| MAJOR METAL PANELS               | 2.8218                                 | TRANSMISSION INSTALLED                              |
| PAINT & MI SC MTRL               | .0084                                  | TIRES MOUNTED AND INSTALLED                         |
| POWER & SIGNAL                   | .3080                                  | VEHICLE TESTED AND INSPECTED                        |
| ROOF                             | 1.4764                                 | FINISHED VEHICLE SHIPPED                            |
| SEATS                            | 4.6002                                 |   |
| STEERING                         | .0997                                  |   |
| STEP PLT./EXT. ASST.             | 2.3049                                 |   |
| TRANSMISSION                     | .8058                                  |   |
| UNDER BODY                       | 3.4054                                 |   |
| WHEELS & TIRES                   | .0706                                  |   |
| WIPER & WASHER                   | .0471                                  |   |
| TOTAL US CONTENT                 | 48.0582                                |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 1AP69  
 CHEVY COBALT  
 CARLINE 3A  
 ASSEMBLY LOC: LORDSTOWN

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | .0099                                  | UNDERBODY FRAMING ASSEMBLED AND WELDED              |
| BATTERY & RELATED                | .2136                                  | FLOOR PANEL WELDED TO UNDERBODY                     |
| BELTS & RESTRAINTS               | .6336                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BRAKES                           | 1.6822                                 | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| CLUSTERS & GAGES                 | .0044                                  | HOOD, DOORS AND FENDERS INSTALLED                   |
| CONVENIENCE                      | .1414                                  | FRONT AND REAR DOORS INSTALLED                      |
| DOORS                            | 3.7057                                 | BODY PRIMED AND SEALED                              |
| ENGINE                           | 11.3341                                | EXTERIOR PAINT APPLIED                              |
| EXHAUST                          | 4.6703                                 | ELECTRICAL WIRING INSTALLED                         |
| EXT. TRIM & ORNAM                | .3100                                  | EXTERIOR MOLDINGS INSTALLED                         |
| F. SHEET MET/PLASTIC             | .7954                                  | AIR CONDITIONING AND HEATER INSTALLED               |
| FRONT & REAR LAMPS               | -.0029                                 | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR SUSP.               | 3.1158                                 | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FUEL TANK/PUMP/LINES             | 1.1497                                 | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| HVAC                             | 3.6392                                 | SEATS INSTALLED                                     |
| INSTRUMENT PANEL                 | 1.7897                                 | SUB FRAME AND ENGINE INSTALLED                      |
| MAJOR METAL PANELS               | 2.7185                                 | TRANSMISSION INSTALLED                              |
| PAINT & MI SC MTRL               | .0086                                  | TIRES MOUNTED AND INSTALLED                         |
| POWER & SIGNAL                   | .3065                                  | VEHICLE TESTED AND INSPECTED                        |
| ROOF                             | 1.3933                                 | FINISHED VEHICLE SHIPPED                            |
| SEATS                            | 4.5059                                 |   |
| STEERING                         | .1008                                  |   |
| STEP PLT./EXT. ASST.             | 1.8010                                 |   |
| TRANSMISSION                     | .7973                                  |   |
| UNDER BODY                       | 3.1038                                 |   |
| WHEELS & TIRES                   | .0694                                  |   |
| WIPER & WASHER                   | .0632                                  |   |
| TOTAL US CONTENT                 | 48.0616                                |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 1AS26  
 CHEVY HHR  
 CARLINE TA  
 ASSEMBLY LOC: RAMOS

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | . 5516                                 | UNDERBODY FRAMING ASSEMBLED AND WELDED              |
| BATTERY & RELATED                | . 0118                                 | FLOOR PANEL WELDED TO UNDERBODY                     |
| BELTS & RESTRAINTS               | . 9087                                 | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BRAKES                           | 1. 0520                                | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| CLUSTERS & GAGES                 | . 4580                                 | HOOD, DOORS AND FENDERS INSTALLED                   |
| CONVENIENCE                      | . 1605                                 | FRONT AND REAR DOORS INSTALLED                      |
| DOORS                            | 2. 2191                                | BODY PRIMED AND SEALED                              |
| ENGINE                           | 11. 9760                               | EXTERIOR PAINT APPLIED                              |
| EXHAUST                          | 2. 3069                                | ELECTRICAL WIRING INSTALLED                         |
| EXT. TRIM & ORNAM                | . 2352                                 | EXTERIOR MOLDINGS INSTALLED                         |
| F. SHEET MET/PLASTIC             | . 4123                                 | AIR CONDITIONING AND HEATER INSTALLED               |
| FRONT & REAR LAMPS               | . 0206                                 | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR SUSP.               | 2. 5657                                | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FUEL TANK/PUMP/LINES             | . 1918                                 | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| HVAC                             | . 9445                                 | SEATS INSTALLED                                     |
| INSTRUMENT PANEL                 | . 0309                                 | SUB FRAME AND ENGINE INSTALLED                      |
| MAJOR METAL PANELS               | . 3690                                 | TRANSMISSION INSTALLED                              |
| PAINT & MI SC MTRL               | . 0123                                 | TIRES MOUNTED AND INSTALLED                         |
| POWER & SIGNAL                   | . 1363                                 | VEHICLE TESTED AND INSPECTED                        |
| ROOF                             | . 4942                                 | FINISHED VEHICLE SHIPPED                            |
| SEATS                            | . 0030                                 |   |
| STEERING                         | . 0115                                 |   |
| STEP PLT./EXT. ASST.             | . 2703                                 |   |
| TRANSMISSION                     | 4. 5821                                |   |
| UNDER BODY                       | 1. 7615                                |   |
| WHEELS & TIRES                   | 3. 7883                                |   |
| WIPER & WASHER                   | . 1679                                 |   |
| TOTAL US CONTENT                 | 35. 6434                               |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 1AS46  
 CHEVY HHR  
 CARLINE TA  
 ASSEMBLY LOC: RAMOS

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | .5813                                  | UNDERBODY FRAMING ASSEMBLED AND WELDED              |
| BATTERY & RELATED                | .0113                                  | FLOOR PANEL WELDED TO UNDERBODY                     |
| BELTS & RESTRAINTS               | .8520                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BRAKES                           | 1.1097                                 | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| CLUSTERS & GAGES                 | .4707                                  | HOOD, DOORS AND FENDERS INSTALLED                   |
| CONVENIENCE                      | .1953                                  | FRONT AND REAR DOORS INSTALLED                      |
| DOORS                            | 2.8456                                 | BODY PRIMED AND SEALED                              |
| ENGINE                           | 13.1427                                | EXTERIOR PAINT APPLIED                              |
| EXHAUST                          | 2.4097                                 | ELECTRICAL WIRING INSTALLED                         |
| EXT. TRIM & ORNAM                | .1690                                  | EXTERIOR MOLDINGS INSTALLED                         |
| F. SHEET MET/PLASTIC             | .4506                                  | AIR CONDITIONING AND HEATER INSTALLED               |
| FRONT & REAR LAMPS               | .0325                                  | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR SUSP.               | 2.6658                                 | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FUEL TANK/PUMP/LINES             | .1955                                  | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| HVAC                             | .9965                                  | SEATS INSTALLED                                     |
| INSTRUMENT PANEL                 | .0246                                  | SUB FRAME AND ENGINE INSTALLED                      |
| MAJOR METAL PANELS               | .4574                                  | TRANSMISSION INSTALLED                              |
| PAINT & MI SC MTRL               | .0132                                  | TIRES MOUNTED AND INSTALLED                         |
| POWER & SIGNAL                   | .1281                                  | VEHICLE TESTED AND INSPECTED                        |
| ROOF                             | .4913                                  | FINISHED VEHICLE SHIPPED                            |
| SEATS                            | .0055                                  |   |
| STEERING                         | .0122                                  |   |
| STEP PLT./EXT. ASST.             | .2513                                  |   |
| TRANSMISSION                     | 5.0322                                 |   |
| UNDER BODY                       | .6781                                  |   |
| WHEELS & TIRES                   | 2.5791                                 |   |
| WIPER & WASHER                   | .1771                                  |   |
| TOTAL US CONTENT                 | 35.9796                                |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 1AT26  
 CHEVY HHR  
 CARLINE TA  
 ASSEMBLY LOC: RAMOS

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | .5946                                  | UNDERBODY FRAMING ASSEMBLED AND WELDED              |
| BATTERY & RELATED                | .0122                                  | FLOOR PANEL WELDED TO UNDERBODY                     |
| BELTS & RESTRAINTS               | .9043                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BRAKES                           | 1.1342                                 | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| CLUSTERS & GAGES                 | .4950                                  | HOOD, DOORS AND FENDERS INSTALLED                   |
| CONVENIENCE                      | .1697                                  | FRONT AND REAR DOORS INSTALLED                      |
| DOORS                            | 2.3874                                 | BODY PRIMED AND SEALED                              |
| ENGINE                           | 13.6804                                | EXTERIOR PAINT APPLIED                              |
| EXHAUST                          | 2.4622                                 | ELECTRICAL WIRING INSTALLED                         |
| EXT. TRIM & ORNAM                | .2384                                  | EXTERIOR MOLDINGS INSTALLED                         |
| F. SHEET MET/PLASTIC             | .4472                                  | AIR CONDITIONING AND HEATER INSTALLED               |
| FRONT & REAR LAMPS               | .0226                                  | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR SUSP.               | 2.7025                                 | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FUEL TANK/PUMP/LINES             | .2068                                  | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| HVAC                             | 1.0155                                 | SEATS INSTALLED                                     |
| INSTRUMENT PANEL                 | .0337                                  | SUB FRAME AND ENGINE INSTALLED                      |
| MAJOR METAL PANELS               | .3382                                  | TRANSMISSION INSTALLED                              |
| PAINT & MI SC MTRL               | .0133                                  | TIRES MOUNTED AND INSTALLED                         |
| POWER & SIGNAL                   | .1463                                  | VEHICLE TESTED AND INSPECTED                        |
| ROOF                             | .2774                                  | FINISHED VEHICLE SHIPPED                            |
| SEATS                            | .0032                                  |   |
| STEERING                         | .0124                                  |   |
| STEP PLT./EXT. ASST.             | .2591                                  |   |
| TRANSMISSION                     | 4.9681                                 |   |
| UNDER BODY                       | 1.9156                                 |   |
| WHEELS & TIRES                   | .2350                                  |   |
| WIPER & WASHER                   | .1810                                  |   |
| TOTAL US CONTENT                 | 34.8577                                |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 1AT46  
 CHEVY HHR  
 CARLINE TA  
 ASSEMBLY LOC: RAMOS

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | .6106                         | UNDERBODY FRAMING ASSEMBLED AND WELDED              |
| BATTERY & RELATED       | .0138                         | FLOOR PANEL WELDED TO UNDERBODY                     |
| BELTS & RESTRAINTS      | .9342                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BRAKES                  | 1.1633                        | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| CLUSTERS & GAGES        | .4979                         | HOOD, DOORS AND FENDERS INSTALLED                   |
| CONVENIENCE             | .2527                         | FRONT AND REAR DOORS INSTALLED                      |
| DOORS                   | 2.9801                        | BODY PRIMED AND SEALED                              |
| ENGINE                  | 13.9864                       | EXTERIOR PAINT APPLIED                              |
| EXHAUST                 | 2.5168                        | ELECTRICAL WIRING INSTALLED                         |
| EXT. TRIM & ORNAM       | .1803                         | EXTERIOR MOLDINGS INSTALLED                         |
| F. SHEET MET/PLASTIC    | .4760                         | AIR CONDITIONING AND HEATER INSTALLED               |
| FRONT & REAR LAMPS      | .0369                         | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR SUSP.      | 2.7690                        | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FUEL TANK/PUMP/LINES    | .2026                         | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| HVAC                    | 1.0431                        | SEATS INSTALLED                                     |
| INSTRUMENT PANEL        | .0226                         | SUB FRAME AND ENGINE INSTALLED                      |
| MAJOR METAL PANELS      | .4599                         | TRANSMISSION INSTALLED                              |
| PAINT & MI SC MTRL      | .0137                         | TIRES MOUNTED AND INSTALLED                         |
| POWER & SIGNAL          | .1329                         | VEHICLE TESTED AND INSPECTED                        |
| ROOF                    | .3055                         | FINISHED VEHICLE SHIPPED                            |
| SEATS                   | .0058                         |   |
| STEERING                | .0127                         |   |
| STEP PLT./EXT. ASST.    | .2675                         |   |
| TRANSMISSION            | 4.7924                        |   |
| UNDER BODY              | .7157                         |   |
| WHEELS & TIRES          | .2410                         |   |
| WI PER & WASHER         | .1856                         |   |
| TOTAL US CONTENT        | 34.8206                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 1AU26  
 CHEVY HHR  
 CARLINE TA  
 ASSEMBLY LOC: RAMOS

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | .3757                                  | UNDERBODY FRAMING ASSEMBLED AND WELDED              |
| BATTERY & RELATED                | .0080                                  | FLOOR PANEL WELDED TO UNDERBODY                     |
| BELTS & RESTRAINTS               | .7208                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BRAKES                           | 1.0175                                 | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| CLUSTERS & GAGES                 | .0378                                  | HOOD, DOORS AND FENDERS INSTALLED                   |
| CONVENIENCE                      | .1368                                  | FRONT AND REAR DOORS INSTALLED                      |
| DOORS                            | 1.7067                                 | BODY PRIMED AND SEALED                              |
| ENGINE                           | 13.6461                                | EXTERIOR PAINT APPLIED                              |
| EXHAUST                          | 2.9358                                 | ELECTRICAL WIRING INSTALLED                         |
| EXT. TRIM & ORNAM                | .4028                                  | EXTERIOR MOLDINGS INSTALLED                         |
| F. SHEET MET/PLASTIC             | .4285                                  | AIR CONDITIONING AND HEATER INSTALLED               |
| FRONT & REAR LAMPS               | .0165                                  | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR SUSP.               | 2.4665                                 | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FUEL TANK/PUMP/LINES             | .1406                                  | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| HVAC                             | 1.5559                                 | SEATS INSTALLED                                     |
| INSTRUMENT PANEL                 | .0261                                  | SUB FRAME AND ENGINE INSTALLED                      |
| MAJOR METAL PANELS               | .3783                                  | TRANSMISSION INSTALLED                              |
| PAINT & MI SC MTRL               | .0100                                  | TIRES MOUNTED AND INSTALLED                         |
| POWER & SIGNAL                   | .2291                                  | VEHICLE TESTED AND INSPECTED                        |
| ROOF                             | .9478                                  | FINISHED VEHICLE SHIPPED                            |
| SEATS                            | .0023                                  |   |
| STEERING                         | .0088                                  |   |
| STEP PLT./EXT. ASST.             | .1787                                  |   |
| TRANSMISSION                     | 2.5806                                 |   |
| UNDER BODY                       | 2.0893                                 |   |
| WHEELS & TIRES                   | 1.5663                                 |   |
| WIPER & WASHER                   | .1291                                  |   |
| TOTAL US CONTENT                 | 33.7436                                |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 1AU46  
 CHEVY HHR  
 CARLINE TA  
 ASSEMBLY LOC: RAMOS

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | .4051                                  | UNDERBODY FRAMING ASSEMBLED AND WELDED              |
| BATTERY & RELATED                | .0098                                  | FLOOR PANEL WELDED TO UNDERBODY                     |
| BELTS & RESTRAINTS               | .7752                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BRAKES                           | 1.0262                                 | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| CLUSTERS & GAGES                 | .4210                                  | HOOD, DOORS AND FENDERS INSTALLED                   |
| CONVENIENCE                      | .1991                                  | FRONT AND REAR DOORS INSTALLED                      |
| DOORS                            | 2.0904                                 | BODY PRIMED AND SEALED                              |
| ENGINE                           | 13.6830                                | EXTERIOR PAINT APPLIED                              |
| EXHAUST                          | 2.9983                                 | ELECTRICAL WIRING INSTALLED                         |
| EXT. TRIM & ORNAM                | .4058                                  | EXTERIOR MOLDINGS INSTALLED                         |
| F. SHEET MET/PLASTIC             | .4432                                  | AIR CONDITIONING AND HEATER INSTALLED               |
| FRONT & REAR LAMPS               | .0261                                  | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR SUSP.               | 2.4786                                 | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FUEL TANK/PUMP/LINES             | .1348                                  | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| HVAC                             | 1.5687                                 | SEATS INSTALLED                                     |
| INSTRUMENT PANEL                 | .0215                                  | SUB FRAME AND ENGINE INSTALLED                      |
| MAJOR METAL PANELS               | .3582                                  | TRANSMISSION INSTALLED                              |
| PAINT & MI SC MTRL               | .0097                                  | TIRES MOUNTED AND INSTALLED                         |
| POWER & SIGNAL                   | .2422                                  | VEHICLE TESTED AND INSPECTED                        |
| ROOF                             | 1.1670                                 | FINISHED VEHICLE SHIPPED                            |
| SEATS                            | .0040                                  |   |
| STEERING                         | .0089                                  |   |
| STEP PLT./EXT. ASST.             | .1769                                  |   |
| TRANSMISSION                     | 2.7365                                 |   |
| UNDER BODY                       | 1.0656                                 |   |
| WHEELS & TIRES                   | 1.5778                                 |   |
| WIPER & WASHER                   | .1301                                  |   |
| TOTAL US CONTENT                 | 34.1651                                |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 1TU69  
 CHEVY AVEO  
 CARLINE RT  
 ASSEMBLY LOC: SAN LUIS POTOSI

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|-------------------------------|---|
| AXLE & HALF SHAFT                | 1.2100                        | UNDERBODY FRAMING ASSEMBLED AND WELDED              |
| BRAKES                           | .0880                         | FLOOR PANEL WELDED TO UNDERBODY                     |
| DOORS                            | .2157                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| ENGINE                           | .0008                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| F. SHEET MET/PLASTIC             | .5465                         | HOOD, DOORS AND FENDERS INSTALLED                   |
| FRONT & REAR SUSP.               | .3516                         | FRONT AND REAR DOORS INSTALLED                      |
| MAJOR METAL PANELS               | .9845                         | BODY PRIMED AND SEALED                              |
| PAINT & MISC MTRL                | .0187                         | EXTERIOR PAINT APPLIED                              |
| POWER & SIGNAL                   | .0008                         | ELECTRICAL WIRING INSTALLED                         |
| ROOF                             | .0007                         | EXTERIOR MOLDINGS INSTALLED                         |
| UNDER BODY                       | .0455                         | AIR CONDITIONING AND HEATER INSTALLED               |
| WHEELS & TIRES                   | .0020                         | INSTRUMENT PANEL INSTALLED                          |
| TOTAL US CONTENT                 | 3.4655                        |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 1TV48  
 CHEVY AVEO  
 CARLINE RT  
 ASSEMBLY LOC: SAN LUIS POTOSI

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| BATTERY & RELATED                | 1.3636                                 | UNDERBODY FRAMING ASSEMBLED AND WELDED              |
| BRAKES                           | .2449                                  | FLOOR PANEL WELDED TO UNDERBODY                     |
| DOORS                            | .1393                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| ENGINE                           | .1232                                  | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| F. SHEET MET/PLASTIC             | .3695                                  | HOOD, DOORS AND FENDERS INSTALLED                   |
| FRONT & REAR SUSP.               | .2437                                  | FRONT AND REAR DOORS INSTALLED                      |
| MAJOR METAL PANELS               | .5749                                  | BODY PRIMED AND SEALED                              |
| PAINT & MISC MTRL                | .0115                                  | EXTERIOR PAINT APPLIED                              |
| ROOF                             | .0005                                  | ELECTRICAL WIRING INSTALLED                         |
| UNDER BODY                       | .0340                                  | EXTERIOR MOLDINGS INSTALLED                         |
| TOTAL US CONTENT                 | 3.1056                                 |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 1TV69  
 CHEVY AVEO  
 CARLINE RT  
 ASSEMBLY LOC: SAN LUIS POTOSI

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | 1.1076                                 | UNDERBODY FRAMING ASSEMBLED AND WELDED              |
| BRAKES                           | .0802                                  | FLOOR PANEL WELDED TO UNDERBODY                     |
| DOORS                            | .1995                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| ENGINE                           | .0008                                  | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| F. SHEET MET/PLASTIC             | .4981                                  | HOOD, DOORS AND FENDERS INSTALLED                   |
| FRONT & REAR SUSP.               | .3205                                  | FRONT AND REAR DOORS INSTALLED                      |
| MAJOR METAL PANELS               | .8992                                  | BODY PRIMED AND SEALED                              |
| PAINT & MISC MTRL                | .0224                                  | EXTERIOR PAINT APPLIED                              |
| POWER & SIGNAL                   | .0007                                  | ELECTRICAL WIRING INSTALLED                         |
| ROOF                             | .0006                                  | EXTERIOR MOLDINGS INSTALLED                         |
| UNDER BODY                       | .0415                                  | AIR CONDITIONING AND HEATER INSTALLED               |
| TOTAL US CONTENT                 | 3.1717                                 |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAIL CODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 1TX69  
 CHEVY AVEO  
 CARLINE RT  
 ASSEMBLY LOC: SAN LUIS POTOSI

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | .8055                                  | UNDERBODY FRAMING ASSEMBLED AND WELDED              |
| BATTERY & RELATED                | .0027                                  | FLOOR PANEL WELDED TO UNDERBODY                     |
| BRAKES                           | .0947                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| DOORS                            | .1877                                  | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| ENGINE                           | .0009                                  | HOOD, DOORS AND FENDERS INSTALLED                   |
| F. SHEET MET/PLASTIC             | .4688                                  | FRONT AND REAR DOORS INSTALLED                      |
| FRONT & REAR SUSP.               | .3016                                  | BODY PRIMED AND SEALED                              |
| FUEL TANK/PUMP/LINES             | .0004                                  | EXTERIOR PAINT APPLIED                              |
| MAJOR METAL PANELS               | .8445                                  | ELECTRICAL WIRING INSTALLED                         |
| PAINT & MISC MTRL                | .0167                                  | EXTERIOR MOLDINGS INSTALLED                         |
| ROOF                             | .0006                                  | AIR CONDITIONING AND HEATER INSTALLED               |
| UNDER BODY                       | .2576                                  | INSTRUMENT PANEL INSTALLED                          |
| WHEELS & TIRES                   | .0017                                  | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| TOTAL US CONTENT                 | 2.9841                                 |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 1WB19  
 CHEVY IMPALA  
 CARLINE W  
 ASSEMBLY LOC: OSHAWA CAR 2

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | .6666                                  | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED                | .2756                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS               | .5372                                  | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                           | 1.0088                                 | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES                 | .6475                                  | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE                      | .0602                                  | BODY PRIMED AND SEALED                              |
| DOORS                            | 2.4521                                 | EXTERIOR PAINT APPLIED                              |
| ENGINE                           | 14.5041                                | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                          | 3.3487                                 | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM                | .0226                                  | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC             | .8783                                  | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS               | .9106                                  | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.               | 5.9278                                 | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES             | 1.5542                                 | SEATS INSTALLED                                     |
| HVAC                             | 2.5402                                 | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL                 | 1.2725                                 | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS               | 4.0273                                 | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL               | .0107                                  | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL                   | .0726                                  | FINISHED VEHICLE SHIPPED                            |
| ROOF                             | 1.2525                                 |   |
| SEATS                            | .0063                                  |   |
| STEERING                         | 2.3995                                 |   |
| STEP PLT./EXT. ASST.             | .4654                                  |   |
| TRANSMISSION                     | 9.2437                                 |   |
| UNDER BODY                       | 4.4230                                 |   |
| WHEELS & TIRES                   | 1.3152                                 |   |
| WIPER & WASHER                   | .1622                                  |   |
| TOTAL US CONTENT                 | 59.9867                                |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 1WC19  
 CHEVY IMPALA  
 CARLINE W  
 ASSEMBLY LOC: OSHAWA CAR 2

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | .6053                                  | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED                | .2611                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS               | .6039                                  | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                           | 1.1820                                 | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES                 | .6254                                  | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE                      | .2248                                  | BODY PRIMED AND SEALED                              |
| DOORS                            | 2.3018                                 | EXTERIOR PAINT APPLIED                              |
| ENGINE                           | 13.5141                                | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                          | 3.5175                                 | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM                | .0237                                  | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC             | .8124                                  | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS               | .8474                                  | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.               | 5.5335                                 | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES             | 1.4002                                 | SEATS INSTALLED                                     |
| HVAC                             | 2.3874                                 | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL                 | 1.1930                                 | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS               | 3.7456                                 | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL               | .0107                                  | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL                   | .0633                                  | FINISHED VEHICLE SHIPPED                            |
| ROOF                             | 1.8349                                 |   |
| SEATS                            | .0055                                  |   |
| STEERING                         | 2.5279                                 |   |
| STEP PLT./EXT. ASST.             | .4320                                  |   |
| TRANSMISSION                     | 8.5805                                 |   |
| UNDER BODY                       | 4.1821                                 |   |
| WHEELS & TIRES                   | 2.2331                                 |   |
| WIPER & WASHER                   | .1498                                  |   |
| TOTAL US CONTENT                 | 58.8001                                |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 1WD19  
 CHEVY IMPALA  
 CARLINE W  
 ASSEMBLY LOC: OSHAWA CAR 2

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | .6219                         | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED       | .2469                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS      | .5729                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                  | 1.1468                        | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES        | .5938                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE             | .1101                         | BODY PRIMED AND SEALED                              |
| DOORS                   | 2.1763                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                  | 11.0312                       | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                 | 4.4826                        | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM       | .0156                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC    | .7770                         | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS      | .8054                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.      | 5.2688                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES    | 1.1189                        | SEATS INSTALLED                                     |
| HVAC                    | 1.4292                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL        | 1.1206                        | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS      | 3.5621                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL      | .0100                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL          | .0631                         | FINISHED VEHICLE SHIPPED                            |
| ROOF                    | 2.0252                        |   |
| SEATS                   | .0052                         |   |
| STEERING                | 2.4627                        |   |
| STEP PLT./EXT. ASST.    | .4114                         |   |
| TRANSMISSION            | 8.5847                        |   |
| UNDER BODY              | 3.9622                        |   |
| WHEELS & TIRES          | 1.2712                        |   |
| WIPER & WASHER          | .1432                         |   |
| TOTAL US CONTENT        | 54.0201                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 1YY07  
 CHEVY CORVETTE  
 CARLINE Y  
 ASSEMBLY LOC: BOWLING GREEN

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | .8346                                  | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED                | .1408                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS               | 1.5732                                 | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                           | 1.3523                                 | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES                 | .0128                                  | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE                      | .7227                                  | BODY PRIMED AND SEALED                              |
| DOORS                            | 5.0183                                 | EXTERIOR PAINT APPLIED                              |
| ENGINE                           | 5.8871                                 | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                          | 3.2382                                 | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM                | .0165                                  | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC             | 1.1244                                 | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS               | .2362                                  | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.               | 4.4912                                 | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES             | 1.7254                                 | SEATS INSTALLED                                     |
| HVAC                             | 1.7952                                 | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL                 | 2.6558                                 | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS               | 2.1037                                 | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL               | .0359                                  | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL                   | .2324                                  | FINISHED VEHICLE SHIPPED                            |
| ROOF                             | 2.2959                                 |   |
| SEATS                            | 3.6839                                 |   |
| STEERING                         | 2.4879                                 |   |
| STEP PLT./EXT. ASST.             | 1.6287                                 |   |
| TRANSMISSION                     | 8.5813                                 |   |
| UNDER BODY                       | 6.0628                                 |   |
| WHEELS & TIRES                   | 2.1426                                 |   |
| WIPER & WASHER                   | .1511                                  |   |
| TOTAL US CONTENT                 | 60.2324                                |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 1YY67  
 CHEVY CORVETTE  
 CARLINE Y  
 ASSEMBLY LOC: BOWLING GREEN

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|-------------------------------|---|
| AXLE & HALF SHAFT                | .6065                         | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED                | .1335                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS               | 1.4958                        | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                           | 1.2695                        | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES                 | .0024                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE                      | .5613                         | BODY PRIMED AND SEALED                              |
| DOORS                            | 4.0598                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                           | 5.5820                        | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                          | 3.2085                        | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM                | .0156                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC             | 1.0478                        | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS               | .2147                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.               | 4.2640                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES             | 1.6342                        | SEATS INSTALLED                                     |
| HVAC                             | 1.6962                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL                 | 2.5421                        | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS               | 2.8343                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL               | .0297                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL                   | .2325                         | FINISHED VEHICLE SHIPPED                            |
| ROOF                             | 6.4998                        |   |
| SEATS                            | 3.7087                        |   |
| STEERING                         | 2.4156                        |   |
| STEP PLT./EXT. ASST.             | 1.5425                        |   |
| TRANSMISSION                     | 7.8176                        |   |
| UNDER BODY                       | 5.6545                        |   |
| WHEELS & TIRES                   | 1.7974                        |   |
| WIPER & WASHER                   | .1466                         |   |
| TOTAL US CONTENT                 | 61.0144                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 1YY87  
 CHEVY CORVETTE  
 CARLINE Y  
 ASSEMBLY LOC: BOWLING GREEN

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|-------------------------------|---|
| AXLE & HALF SHAFT                | .6783                         | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED                | .1977                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS               | .8975                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                           | 3.0923                        | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES                 | .0075                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE                      | .7343                         | BODY PRIMED AND SEALED                              |
| DOORS                            | 3.4829                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                           | 16.0581                       | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                          | 2.6255                        | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM                | .0347                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC             | 3.6791                        | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS               | .1005                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.               | 3.8061                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES             | 1.6519                        | SEATS INSTALLED                                     |
| HVAC                             | 1.3436                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL                 | 1.9962                        | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS               | 9.4240                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL               | .0103                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL                   | .1274                         | FINISHED VEHICLE SHIPPED                            |
| ROOF                             | 1.8550                        |   |
| SEATS                            | 3.6407                        |   |
| STEERING                         | 1.5335                        |   |
| STEP PLT./EXT. ASST.             | 1.1895                        |   |
| TRANSMISSION                     | 6.1554                        |   |
| UNDER BODY                       | 3.0147                        |   |
| WHEELS & TIRES                   | 1.2778                        |   |
| WIPER & WASHER                   | .0936                         |   |
| TOTAL US CONTENT                 | 68.7094                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 1ZF69  
 CHEVY MALIBU  
 CARLINE 3Z  
 ASSEMBLY LOC: FAIRFAX

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | .4872                                  | UNDERBODY FRAMING ASSEMBLED AND WELDED              |
| BATTERY & RELATED                | 8.4028                                 | FLOOR PANEL WELDED TO UNDERBODY                     |
| BELTS & RESTRAINTS               | .6641                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BRAKES                           | 1.4616                                 | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| CLUSTERS & GAGES                 | .0052                                  | HOOD, DOORS AND FENDERS INSTALLED                   |
| CONVENIENCE                      | 1.6004                                 | FRONT AND REAR DOORS INSTALLED                      |
| DOORS                            | 4.2169                                 | BODY PRIMED AND SEALED                              |
| ENGINE                           | 9.4864                                 | EXTERIOR PAINT APPLIED                              |
| EXHAUST                          | 3.4891                                 | ELECTRICAL WIRING INSTALLED                         |
| F. SHEET MET/PLASTIC             | .9777                                  | EXTERIOR MOLDINGS INSTALLED                         |
| FRONT & REAR LAMPS               | .0189                                  | AIR CONDITIONING AND HEATER INSTALLED               |
| FRONT & REAR SUSP.               | 4.0930                                 | INSTRUMENT PANEL INSTALLED                          |
| FUEL TANK/PUMP/LINES             | 1.3262                                 | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| HVAC                             | 2.3663                                 | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| INSTRUMENT PANEL                 | 3.9415                                 | SEATS INSTALLED                                     |
| MAJOR METAL PANELS               | 4.0287                                 | SUB FRAME AND ENGINE INSTALLED                      |
| PAINT & MISC MTRL                | .0081                                  | TRANSMISSION INSTALLED                              |
| POWER & SIGNAL                   | .0504                                  | TIRES MOUNTED AND INSTALLED                         |
| ROOF                             | 1.6098                                 | VEHICLE TESTED AND INSPECTED                        |
| SEATS                            | 4.1106                                 | FINISHED VEHICLE SHIPPED                            |
| STEERING                         | 1.3345                                 |   |
| STEP PLT./EXT. ASST.             | 1.6108                                 |   |
| TRANSMISSION                     | 4.2003                                 |   |
| UNDER BODY                       | 6.2244                                 |   |
| WHEELS & TIRES                   | 2.6899                                 |   |
| WIPER & WASHER                   | .1361                                  |   |
| TOTAL US CONTENT                 | 68.5424                                |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 1ZG69  
 CHEVY MALIBU 386  
 CARLINE 3Z  
 ASSEMBLY LOC: ORION

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|-------------------------------|---|
| AXLE & HALF SHAFT                | 1.4967                        | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED                | .2291                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS               | .6198                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                           | 1.5698                        | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES                 | .0069                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE                      | 1.3730                        | BODY PRIMED AND SEALED                              |
| DOORS                            | 5.0399                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                           | 10.5307                       | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                          | 2.7360                        | EXTERIOR MOLDINGS INSTALLED                         |
| F. SHEET MET/PLASTIC             | 1.2053                        | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS               | .0235                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.               | 4.3259                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES             | 1.3356                        | SEATS INSTALLED                                     |
| HVAC                             | 2.6902                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL                 | 4.0443                        | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS               | 4.8808                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MISC MTRL                | .0082                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL                   | .0487                         | FINISHED VEHICLE SHIPPED                            |
| ROOF                             | 1.7429                        |   |
| SEATS                            | 4.9581                        |   |
| STEERING                         | 1.5787                        |   |
| STEP PLT./EXT. ASST.             | 1.9964                        |   |
| TRANSMISSION                     | 4.3963                        |   |
| UNDER BODY                       | 7.6845                        |   |
| WHEELS & TIRES                   | 2.3666                        |   |
| WIPER & WASHER                   | .1692                         |   |
| TOTAL US CONTENT                 | 67.0582                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 1ZH69  
 CHEVY MALIBU 386  
 CARLINE 3Z  
 ASSEMBLY LOC: ORION

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | 1.4897                        | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED       | .2141                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS      | .7589                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                  | 1.4605                        | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES        | .0062                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE             | 1.5951                        | BODY PRIMED AND SEALED                              |
| DOORS                   | 4.7124                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                  | 9.1098                        | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                 | 5.6529                        | EXTERIOR MOLDINGS INSTALLED                         |
| F. SHEET MET/PLASTIC    | 1.1281                        | AIR CONDITIONING AND HEATER INSTALLED               |
| FRONT & REAR LAMPS      | .0219                         | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR SUSP.      | 4.0408                        | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FUEL TANK/PUMP/LINES    | 1.2464                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| HVAC                    | 2.5113                        | SEATS INSTALLED                                     |
| INSTRUMENT PANEL        | 3.7654                        | SUB FRAME AND ENGINE INSTALLED                      |
| MAJOR METAL PANELS      | 4.6390                        | TRANSMISSION INSTALLED                              |
| PAINT & MISC MTRL       | .0079                         | TIRES MOUNTED AND INSTALLED                         |
| POWER & SIGNAL          | .1244                         | VEHICLE TESTED AND INSPECTED                        |
| ROOF                    | 2.2094                        | FINISHED VEHICLE SHIPPED                            |
| SEATS                   | 5.1144                        |   |
| STEERING                | 1.5472                        |   |
| STEP PLT./EXT. ASST.    | 1.8658                        |   |
| TRANSMISSION            | 2.9400                        |   |
| UNDER BODY              | 7.3374                        |   |
| WHEELS & TIRES          | 2.7134                        |   |
| WIPER & WASHER          | .1579                         |   |
| TOTAL US CONTENT        | 66.3717                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 1ZK69  
 CHEVY MALIBU 386  
 CARLINE 3Z  
 ASSEMBLY LOC: ORION

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|-------------------------------|---|
| AXLE & HALF SHAFT                | 1.3914                        | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED                | .1869                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS               | .8787                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                           | 1.2679                        | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES                 | .0052                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE                      | 2.0595                        | BODY PRIMED AND SEALED                              |
| DOORS                            | 4.1167                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                           | 6.6928                        | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                          | 8.3908                        | EXTERIOR MOLDINGS INSTALLED                         |
| F. SHEET MET/PLASTIC             | .9774                         | AIR CONDITIONING AND HEATER INSTALLED               |
| FRONT & REAR LAMPS               | .0190                         | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR SUSP.               | 3.5286                        | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FUEL TANK/PUMP/LINES             | 1.0654                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| HVAC                             | 2.3463                        | SEATS INSTALLED                                     |
| INSTRUMENT PANEL                 | 3.2036                        | SUB FRAME AND ENGINE INSTALLED                      |
| MAJOR METAL PANELS               | 4.0790                        | TRANSMISSION INSTALLED                              |
| PAINT & MISC MTRL                | .0072                         | TIRES MOUNTED AND INSTALLED                         |
| POWER & SIGNAL                   | .0487                         | VEHICLE TESTED AND INSPECTED                        |
| ROOF                             | 2.7166                        | FINISHED VEHICLE SHIPPED                            |
| SEATS                            | 6.9256                        |   |
| STEERING                         | 1.1763                        |   |
| STEP PLT./EXT. ASST.             | 1.8711                        |   |
| TRANSMISSION                     | 3.6315                        |   |
| UNDER BODY                       | 6.6318                        |   |
| WHEELS & TIRES                   | 2.9528                        |   |
| WIPER & WASHER                   | .1372                         |   |
| TOTAL US CONTENT                 | 66.3095                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 2AJ37  
 PONTIAC G5  
 CARLINE 3A  
 ASSEMBLY LOC: LORDSTOWN

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | .7559                                  | UNDERBODY FRAMING ASSEMBLED AND WELDED              |
| BATTERY & RELATED                | .3161                                  | FLOOR PANEL WELDED TO UNDERBODY                     |
| BELTS & RESTRAINTS               | .6395                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BRAKES                           | 1.3290                                 | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| CONVENIENCE                      | .8156                                  | HOOD, DOORS AND FENDERS INSTALLED                   |
| DOORS                            | 3.4161                                 | FRONT AND REAR DOORS INSTALLED                      |
| ENGINE                           | 13.7634                                | BODY PRIMED AND SEALED                              |
| EXHAUST                          | 4.0399                                 | EXTERIOR PAINT APPLIED                              |
| EXT. TRIM & ORNAM                | .4299                                  | ELECTRICAL WIRING INSTALLED                         |
| F. SHEET MET/PLASTIC             | 1.2298                                 | EXTERIOR MOLDINGS INSTALLED                         |
| FRONT & REAR LAMPS               | .0205                                  | AIR CONDITIONING AND HEATER INSTALLED               |
| FRONT & REAR SUSP.               | 2.5688                                 | INSTRUMENT PANEL INSTALLED                          |
| FUEL TANK/PUMP/LINES             | 1.2845                                 | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| HVAC                             | 3.2423                                 | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| INSTRUMENT PANEL                 | 2.6482                                 | SEATS INSTALLED                                     |
| MAJOR METAL PANELS               | 4.2094                                 | SUB FRAME AND ENGINE INSTALLED                      |
| PAINT & MISC MTRL                | .0049                                  | TRANSMISSION INSTALLED                              |
| POWER & SIGNAL                   | .4986                                  | TIRES MOUNTED AND INSTALLED                         |
| ROOF                             | .7821                                  | VEHICLE TESTED AND INSPECTED                        |
| SEATS                            | 4.4155                                 | FINISHED VEHICLE SHIPPED                            |
| STEERING                         | .1493                                  |   |
| STEP PLT./EXT. ASST.             | 3.1189                                 |   |
| TRANSMISSION                     | 4.8515                                 |   |
| UNDER BODY                       | 4.2035                                 |   |
| WHEELS & TIRES                   | 2.0963                                 |   |
| WIPER & WASHER                   | .0722                                  |   |
| TOTAL US CONTENT                 | 60.9028                                |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 2AJ69  
 PONTIAC G5  
 CARLINE 3A  
 ASSEMBLY LOC: LORDSTOWN

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | . 7436                                 | UNDERBODY FRAMING ASSEMBLED AND WELDED              |
| BATTERY & RELATED                | . 3178                                 | FLOOR PANEL WELDED TO UNDERBODY                     |
| BELTS & RESTRAINTS               | . 6381                                 | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BRAKES                           | 1. 3017                                | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| CONVENIENCE                      | . 8420                                 | HOOD, DOORS AND FENDERS INSTALLED                   |
| DOORS                            | 5. 4814                                | FRONT AND REAR DOORS INSTALLED                      |
| ENGINE                           | 13. 6378                               | BODY PRIMED AND SEALED                              |
| EXHAUST                          | 3. 9980                                | EXTERIOR PAINT APPLIED                              |
| EXT. TRIM & ORNAM                | . 4263                                 | ELECTRICAL WIRING INSTALLED                         |
| F. SHEET MET/PLASTIC             | 1. 2087                                | EXTERIOR MOLDINGS INSTALLED                         |
| FRONT & REAR LAMPS               | . 0063                                 | AIR CONDITIONING AND HEATER INSTALLED               |
| FRONT & REAR SUSP.               | 2. 5465                                | INSTRUMENT PANEL INSTALLED                          |
| FUEL TANK/PUMP/LINES             | 1. 2708                                | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| HVAC                             | 3. 4431                                | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| INSTRUMENT PANEL                 | 2. 5443                                | SEATS INSTALLED                                     |
| MAJOR METAL PANELS               | 4. 0741                                | SUB FRAME AND ENGINE INSTALLED                      |
| PAINT & MISC MTRL                | . 0047                                 | TRANSMISSION INSTALLED                              |
| POWER & SIGNAL                   | . 4766                                 | TIRES MOUNTED AND INSTALLED                         |
| ROOF                             | . 8332                                 | VEHICLE TESTED AND INSPECTED                        |
| SEATS                            | 4. 3192                                | FINISHED VEHICLE SHIPPED                            |
| STEERING                         | . 1511                                 |   |
| STEP PLT./EXT. ASST.             | 2. 5310                                |   |
| TRANSMISSION                     | 5. 3173                                |   |
| UNDER BODY                       | 4. 2893                                |   |
| WHEELS & TIRES                   | 2. 0765                                |   |
| WIPER & WASHER                   | . 0832                                 |   |
| TOTAL US CONTENT                 | 62. 5639                               |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 2AL37  
 PONTIAC G5  
 CARLINE 3A  
 ASSEMBLY LOC: LORDSTOWN

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | .6787                                  | UNDERBODY FRAMING ASSEMBLED AND WELDED              |
| BATTERY & RELATED                | .2877                                  | FLOOR PANEL WELDED TO UNDERBODY                     |
| BELTS & RESTRAINTS               | .7760                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BRAKES                           | 1.2469                                 | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| CONVENIENCE                      | .1054                                  | HOOD, DOORS AND FENDERS INSTALLED                   |
| DOORS                            | 3.2616                                 | FRONT AND REAR DOORS INSTALLED                      |
| ENGINE                           | 12.7596                                | BODY PRIMED AND SEALED                              |
| EXHAUST                          | 3.7107                                 | EXTERIOR PAINT APPLIED                              |
| EXT. TRIM & ORNAM                | .3903                                  | ELECTRICAL WIRING INSTALLED                         |
| F. SHEET MET/PLASTIC             | 1.1256                                 | EXTERIOR MOLDINGS INSTALLED                         |
| FRONT & REAR LAMPS               | .0313                                  | AIR CONDITIONING AND HEATER INSTALLED               |
| FRONT & REAR SUSP.               | 2.3808                                 | INSTRUMENT PANEL INSTALLED                          |
| FUEL TANK/PUMP/LINES             | 1.4638                                 | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| HVAC                             | 3.3038                                 | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| INSTRUMENT PANEL                 | 2.5258                                 | SEATS INSTALLED                                     |
| MAJOR METAL PANELS               | 3.8412                                 | SUB FRAME AND ENGINE INSTALLED                      |
| PAINT & MISC MTRL                | .0130                                  | TRANSMISSION INSTALLED                              |
| POWER & SIGNAL                   | .3897                                  | TIRES MOUNTED AND INSTALLED                         |
| ROOF                             | .9699                                  | VEHICLE TESTED AND INSPECTED                        |
| SEATS                            | 4.0535                                 | FINISHED VEHICLE SHIPPED                            |
| STEERING                         | .1359                                  |   |
| STEP PLT./EXT. ASST.             | 2.6296                                 |   |
| TRANSMISSION                     | 5.2856                                 |   |
| UNDER BODY                       | 4.3597                                 |   |
| WHEELS & TIRES                   | 1.8707                                 |   |
| WIPER & WASHER                   | .0633                                  |   |
| TOTAL US CONTENT                 | 57.6614                                |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 2AL69  
 PONTIAC G5  
 CARLINE 3A  
 ASSEMBLY LOC: LORDSTOWN

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | . 6585                                 | UNDERBODY FRAMING ASSEMBLED AND WELDED              |
| BATTERY & RELATED                | . 2875                                 | FLOOR PANEL WELDED TO UNDERBODY                     |
| BELTS & RESTRAINTS               | . 6937                                 | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BRAKES                           | 1. 2116                                | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| CONVENIENCE                      | . 1026                                 | HOOD, DOORS AND FENDERS INSTALLED                   |
| DOORS                            | 4. 8367                                | FRONT AND REAR DOORS INSTALLED                      |
| ENGINE                           | 12. 1953                               | BODY PRIMED AND SEALED                              |
| EXHAUST                          | 3. 5856                                | EXTERIOR PAINT APPLIED                              |
| EXT. TRIM & ORNAM                | . 3806                                 | ELECTRICAL WIRING INSTALLED                         |
| F. SHEET MET/PLASTIC             | 1. 0709                                | EXTERIOR MOLDINGS INSTALLED                         |
| FRONT & REAR LAMPS               | . 0107                                 | AIR CONDITIONING AND HEATER INSTALLED               |
| FRONT & REAR SUSP.               | 2. 4216                                | INSTRUMENT PANEL INSTALLED                          |
| FUEL TANK/PUMP/LINES             | 1. 1358                                | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| HVAC                             | 3. 2515                                | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| INSTRUMENT PANEL                 | 2. 3310                                | SEATS INSTALLED                                     |
| MAJOR METAL PANELS               | 3. 6471                                | SUB FRAME AND ENGINE INSTALLED                      |
| PAINT & MISC MTRL                | . 0052                                 | TRANSMISSION INSTALLED                              |
| POWER & SIGNAL                   | . 3788                                 | TIRES MOUNTED AND INSTALLED                         |
| ROOF                             | 1. 2429                                | VEHICLE TESTED AND INSPECTED                        |
| SEATS                            | 3. 8744                                | FINISHED VEHICLE SHIPPED                            |
| STEERING                         | . 1351                                 |   |
| STEP PLT./EXT. ASST.             | 2. 4175                                |   |
| TRANSMISSION                     | 5. 1628                                |   |
| UNDER BODY                       | 4. 2617                                |   |
| WHEELS & TIRES                   | 1. 7241                                |   |
| WIPER & WASHER                   | . 0918                                 |   |
| TOTAL US CONTENT                 | 57. 0947                               |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 2AN37  
 PONTIAC G5  
 CARLINE 3A  
 ASSEMBLY LOC: LORDSTOWN

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | .6416                                  | UNDERBODY FRAMING ASSEMBLED AND WELDED              |
| BATTERY & RELATED                | .2714                                  | FLOOR PANEL WELDED TO UNDERBODY                     |
| BELTS & RESTRAINTS               | .7783                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BRAKES                           | 1.1348                                 | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| CONVENIENCE                      | .1472                                  | HOOD, DOORS AND FENDERS INSTALLED                   |
| DOORS                            | 3.1073                                 | FRONT AND REAR DOORS INSTALLED                      |
| ENGINE                           | 11.9595                                | BODY PRIMED AND SEALED                              |
| EXHAUST                          | 3.5521                                 | EXTERIOR PAINT APPLIED                              |
| EXT. TRIM & ORNAM                | .3684                                  | ELECTRICAL WIRING INSTALLED                         |
| F. SHEET MET/PLASTIC             | 1.0613                                 | EXTERIOR MOLDINGS INSTALLED                         |
| FRONT & REAR LAMPS               | .0290                                  | AIR CONDITIONING AND HEATER INSTALLED               |
| FRONT & REAR SUSP.               | 2.7437                                 | INSTRUMENT PANEL INSTALLED                          |
| FUEL TANK/PUMP/LINES             | 1.2849                                 | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| HVAC                             | 3.0860                                 | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| INSTRUMENT PANEL                 | 2.4246                                 | SEATS INSTALLED                                     |
| MAJOR METAL PANELS               | 3.6253                                 | SUB FRAME AND ENGINE INSTALLED                      |
| PAINT & MISC MTRL                | .0081                                  | TRANSMISSION INSTALLED                              |
| POWER & SIGNAL                   | .3666                                  | TIRES MOUNTED AND INSTALLED                         |
| ROOF                             | 1.8666                                 | VEHICLE TESTED AND INSPECTED                        |
| SEATS                            | 5.2038                                 | FINISHED VEHICLE SHIPPED                            |
| STEERING                         | .1282                                  |   |
| STEP PLT./EXT. ASST.             | 2.7867                                 |   |
| TRANSMISSION                     | 3.4027                                 |   |
| UNDER BODY                       | 4.2597                                 |   |
| WHEELS & TIRES                   | 4.6222                                 |   |
| WIPER & WASHER                   | .0598                                  |   |
| TOTAL US CONTENT                 | 58.9212                                |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 2TU48  
 PONTIAC G3  
 CARLINE RT  
 ASSEMBLY LOC: SAN LUIS POTOSI

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | .9925                                  | UNDERBODY FRAMING ASSEMBLED AND WELDED              |
| BRAKES                           | .2667                                  | FLOOR PANEL WELDED TO UNDERBODY                     |
| DOORS                            | .1649                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| ENGINE                           | .1458                                  | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| F. SHEET MET/PLASTIC             | .4374                                  | HOOD, DOORS AND FENDERS INSTALLED                   |
| FRONT & REAR SUSP.               | .2884                                  | FRONT AND REAR DOORS INSTALLED                      |
| MAJOR METAL PANELS               | .6804                                  | BODY PRIMED AND SEALED                              |
| PAINT & MISC MTRL                | .0333                                  | EXTERIOR PAINT APPLIED                              |
| POWER & SIGNAL                   | .0006                                  | ELECTRICAL WIRING INSTALLED                         |
| ROOF                             | .0006                                  | EXTERIOR MOLDINGS INSTALLED                         |
| UNDER BODY                       | .0402                                  | AIR CONDITIONING AND HEATER INSTALLED               |
| TOTAL US CONTENT                 | 3.0514                                 |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAIL CODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 2TU69  
 PONTIAC G3  
 CARLINE RT  
 ASSEMBLY LOC: SAN LUIS POTOSI

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|-------------------------------|---|
| AXLE & HALF SHAFT                | 1.0510                        | UNDERBODY FRAMING ASSEMBLED AND WELDED              |
| BRAKES                           | .2877                         | FLOOR PANEL WELDED TO UNDERBODY                     |
| DOORS                            | .1779                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| ENGINE                           | .1445                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| F. SHEET MET/PLASTIC             | .4443                         | HOOD, DOORS AND FENDERS INSTALLED                   |
| FRONT & REAR SUSP.               | .2859                         | FRONT AND REAR DOORS INSTALLED                      |
| FUEL TANK/PUMP/LINES             | .2769                         | BODY PRIMED AND SEALED                              |
| MAJOR METAL PANELS               | .8005                         | EXTERIOR PAINT APPLIED                              |
| PAINT & MI SC MTRL               | .0021                         | ELECTRICAL WIRING INSTALLED                         |
| ROOF                             | .0006                         | EXTERIOR MOLDINGS INSTALLED                         |
| UNDER BODY                       | .2442                         | AIR CONDITIONING AND HEATER INSTALLED               |
| WHEELS & TIRES                   | .0016                         | INSTRUMENT PANEL INSTALLED                          |
| TOTAL US CONTENT                 | 3.7179                        |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 2TV48  
 PONTIAC G3  
 CARLINE RT  
 ASSEMBLY LOC: SAN LUIS POTOSI

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | .9281                                  | UNDERBODY FRAMING ASSEMBLED AND WELDED              |
| BATTERY & RELATED                | .0642                                  | FLOOR PANEL WELDED TO UNDERBODY                     |
| BRAKES                           | .2652                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| DOORS                            | .1509                                  | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| ENGINE                           | .1334                                  | HOOD, DOORS AND FENDERS INSTALLED                   |
| F. SHEET MET/PLASTIC             | .4002                                  | FRONT AND REAR DOORS INSTALLED                      |
| FRONT & REAR SUSP.               | .2639                                  | BODY PRIMED AND SEALED                              |
| MAJOR METAL PANELS               | .6236                                  | EXTERIOR PAINT APPLIED                              |
| PAINT & MI SC MTRL               | .0298                                  | ELECTRICAL WIRING INSTALLED                         |
| ROOF                             | .0005                                  | EXTERIOR MOLDINGS INSTALLED                         |
| UNDER BODY                       | .2198                                  | AIR CONDITIONING AND HEATER INSTALLED               |
| WHEELS & TIRES                   | -.0009                                 | INSTRUMENT PANEL INSTALLED                          |
| TOTAL US CONTENT                 | 3.0793                                 |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 2TV69  
 PONTIAC G3  
 CARLINE RT  
 ASSEMBLY LOC: SAN LUIS POTOSI

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | .9857                                  | UNDERBODY FRAMING ASSEMBLED AND WELDED              |
| BRAKES                           | .2698                                  | FLOOR PANEL WELDED TO UNDERBODY                     |
| DOORS                            | .1669                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| ENGINE                           | .1355                                  | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| F. SHEET MET/PLASTIC             | .4167                                  | HOOD, DOORS AND FENDERS INSTALLED                   |
| FRONT & REAR SUSP.               | .2681                                  | FRONT AND REAR DOORS INSTALLED                      |
| FUEL TANK/PUMP/LINES             | .2597                                  | BODY PRIMED AND SEALED                              |
| MAJOR METAL PANELS               | .7506                                  | EXTERIOR PAINT APPLIED                              |
| PAINT & MI SC MTRL               | .0309                                  | ELECTRICAL WIRING INSTALLED                         |
| ROOF                             | .0005                                  | EXTERIOR MOLDINGS INSTALLED                         |
| UNDER BODY                       | .2290                                  | AIR CONDITIONING AND HEATER INSTALLED               |
| WHEELS & TIRES                   | .0017                                  | INSTRUMENT PANEL INSTALLED                          |
| TOTAL US CONTENT                 | 3.5158                                 |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 2TX48  
 PONTIAC G3  
 CARLINE RT  
 ASSEMBLY LOC: SAN LUIS POTOSI

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| BRAKES                           | .2506                                  | UNDERBODY FRAMING ASSEMBLED AND WELDED              |
| DOORS                            | .1426                                  | FLOOR PANEL WELDED TO UNDERBODY                     |
| ENGINE                           | .1261                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| F. SHEET MET/PLASTIC             | .3782                                  | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| FRONT & REAR SUSP.               | .2494                                  | HOOD, DOORS AND FENDERS INSTALLED                   |
| MAJOR METAL PANELS               | .5885                                  | FRONT AND REAR DOORS INSTALLED                      |
| PAINT & MISC MTRL                | .0288                                  | BODY PRIMED AND SEALED                              |
| ROOF                             | .0005                                  | EXTERIOR PAINT APPLIED                              |
| UNDER BODY                       | .2155                                  | ELECTRICAL WIRING INSTALLED                         |
| TOTAL US CONTENT                 | 1.9808                                 |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 2TX69  
 PONTIAC G3  
 CARLINE RT  
 ASSEMBLY LOC: SAN LUIS POTOSI

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | .0026                                  | UNDERBODY FRAMING ASSEMBLED AND WELDED              |
| BATTERY & RELATED                | .0080                                  | FLOOR PANEL WELDED TO UNDERBODY                     |
| BRAKES                           | .2533                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| DOORS                            | .1566                                  | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| ENGINE                           | .1272                                  | HOOD, DOORS AND FENDERS INSTALLED                   |
| F. SHEET MET/PLASTIC             | .3911                                  | FRONT AND REAR DOORS INSTALLED                      |
| FRONT & REAR SUSP.               | .2516                                  | BODY PRIMED AND SEALED                              |
| FUEL TANK/PUMP/LINES             | .2437                                  | EXTERIOR PAINT APPLIED                              |
| MAJOR METAL PANELS               | .7046                                  | ELECTRICAL WIRING INSTALLED                         |
| PAINT & MISC MTRL                | .0289                                  | EXTERIOR MOLDINGS INSTALLED                         |
| ROOF                             | .0005                                  | AIR CONDITIONING AND HEATER INSTALLED               |
| UNDER BODY                       | .2149                                  | INSTRUMENT PANEL INSTALLED                          |
| WHEELS & TIRES                   | .0014                                  | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| TOTAL US CONTENT                 | 2.3852                                 |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 2ZG37  
 PONTIAC G6  
 CARLINE 3Z  
 ASSEMBLY LOC: ORION

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|-------------------------------|---|
| AXLE & HALF SHAFT                | 1.2740                        | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED                | .2366                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS               | .6880                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                           | 1.5123                        | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES                 | .0067                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE                      | 2.5854                        | BODY PRIMED AND SEALED                              |
| DOORS                            | 2.4239                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                           | 9.3558                        | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                          | 6.2059                        | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM                | .0150                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC             | 1.2404                        | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS               | .3303                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.               | 3.6946                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES             | 1.3731                        | SEATS INSTALLED                                     |
| HVAC                             | 2.8480                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL                 | 1.3806                        | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS               | 5.7993                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL               | .0116                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL                   | .0917                         | FINISHED VEHICLE SHIPPED                            |
| ROOF                             | 2.4885                        |   |
| SEATS                            | 6.5389                        |   |
| STEERING                         | 1.4958                        |   |
| STEP PLT./EXT. ASST.             | .9802                         |   |
| TRANSMISSION                     | .4670                         |   |
| UNDER BODY                       | 7.6672                        |   |
| WHEELS & TIRES                   | 3.7967                        |   |
| WIPER & WASHER                   | .1652                         |   |
| TOTAL US CONTENT                 | 64.6742                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 2ZG69  
 PONTIAC G6  
 CARLINE 3Z  
 ASSEMBLY LOC: ORION

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | 2.5629                                 | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED                | .2348                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS               | .8612                                  | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                           | 1.3407                                 | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES                 | .0076                                  | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE                      | 1.7753                                 | BODY PRIMED AND SEALED                              |
| DOORS                            | 6.2088                                 | EXTERIOR PAINT APPLIED                              |
| ENGINE                           | 10.2009                                | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                          | 2.4839                                 | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM                | .1111                                  | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC             | 1.2274                                 | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS               | .2749                                  | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.               | 3.6725                                 | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES             | 1.3899                                 | SEATS INSTALLED                                     |
| HVAC                             | 2.8307                                 | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL                 | 1.3636                                 | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS               | 5.6965                                 | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL               | .0107                                  | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL                   | .1767                                  | FINISHED VEHICLE SHIPPED                            |
| ROOF                             | 1.3134                                 |   |
| SEATS                            | 4.8529                                 |   |
| STEERING                         | 1.4046                                 |   |
| STEP PLT./EXT. ASST.             | .2638                                  |   |
| TRANSMISSION                     | 3.9268                                 |   |
| UNDER BODY                       | 6.5829                                 |   |
| WHEELS & TIRES                   | 2.3004                                 |   |
| WIPER & WASHER                   | .1641                                  |   |
| TOTAL US CONTENT                 | 63.2403                                |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 2ZH37  
 PONTIAC G6  
 CARLINE 3Z  
 ASSEMBLY LOC: ORION

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | 2.2668                                 | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED                | .2133                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS               | .6181                                  | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                           | 1.1916                                 | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES                 | .0144                                  | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE                      | 2.0989                                 | BODY PRIMED AND SEALED                              |
| DOORS                            | 2.1829                                 | EXTERIOR PAINT APPLIED                              |
| ENGINE                           | 5.1093                                 | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                          | 7.2806                                 | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM                | .0136                                  | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC             | 1.1188                                 | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS               | .2987                                  | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.               | 3.3794                                 | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES             | 1.2554                                 | SEATS INSTALLED                                     |
| HVAC                             | 2.6025                                 | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL                 | 1.2404                                 | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS               | 5.2555                                 | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL               | .0098                                  | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL                   | .0564                                  | FINISHED VEHICLE SHIPPED                            |
| ROOF                             | 1.7779                                 |   |
| SEATS                            | 5.9402                                 |   |
| STEERING                         | .6767                                  |   |
| STEP PLT./EXT. ASST.             | .4364                                  |   |
| TRANSMISSION                     | 4.3663                                 |   |
| UNDER BODY                       | 7.1497                                 |   |
| WHEELS & TIRES                   | 1.8996                                 |   |
| WIPER & WASHER                   | .1491                                  |   |
| TOTAL US CONTENT                 | 58.6037                                |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 2ZH67  
 PONTIAC G6  
 CARLINE 3Z  
 ASSEMBLY LOC: ORION

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | 1.9239                        | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED       | .1827                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS      | .5477                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                  | 1.1555                        | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES        | .0123                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE             | 1.9374                        | BODY PRIMED AND SEALED                              |
| DOORS                   | 2.2406                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                  | 6.3382                        | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                 | .1064                         | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM       | .0456                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC    | .9628                         | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS      | .2295                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.      | 3.1936                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES    | 1.0588                        | SEATS INSTALLED                                     |
| HVAC                    | 2.2943                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL        | 1.0624                        | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS      | 4.8062                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL      | .0084                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL          | .0500                         | FINISHED VEHICLE SHIPPED                            |
| ROOF                    | 14.5045                       |   |
| SEATS                   | 5.1271                        |   |
| STEERING                | .5795                         |   |
| STEP PLT./EXT. ASST.    | .2382                         |   |
| TRANSMISSION            | 4.5520                        |   |
| UNDER BODY              | 7.6686                        |   |
| WHEELS & TIRES          | 3.2493                        |   |
| WI PER & WASHER         | .1277                         |   |
| TOTAL US CONTENT        | 64.2046                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 2ZH69  
 PONTIAC G6  
 CARLINE 3Z  
 ASSEMBLY LOC: ORION

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | 2.2622                                 | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED                | .2108                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS               | .8848                                  | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                           | 1.1706                                 | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES                 | .0142                                  | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE                      | 1.9906                                 | BODY PRIMED AND SEALED                              |
| DOORS                            | 5.6521                                 | EXTERIOR PAINT APPLIED                              |
| ENGINE                           | 5.2916                                 | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                          | 6.0111                                 | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM                | .3033                                  | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC             | 1.1057                                 | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS               | .2502                                  | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.               | 3.3395                                 | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES             | 1.2715                                 | SEATS INSTALLED                                     |
| HVAC                             | 2.5722                                 | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL                 | 1.2242                                 | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS               | 5.1191                                 | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL               | .0100                                  | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL                   | .0485                                  | FINISHED VEHICLE SHIPPED                            |
| ROOF                             | .9678                                  |   |
| SEATS                            | 4.3470                                 |   |
| STEERING                         | .6688                                  |   |
| STEP PLT./EXT. ASST.             | .2487                                  |   |
| TRANSMISSION                     | 4.3763                                 |   |
| UNDER BODY                       | 6.3025                                 |   |
| WHEELS & TIRES                   | 1.4522                                 |   |
| WIPER & WASHER                   | .1473                                  |   |
| TOTAL US CONTENT                 | 57.2441                                |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 2ZM37  
 PONTIAC G6  
 CARLINE 3Z  
 ASSEMBLY LOC: ORION

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | 2.0961                        | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED       | .1818                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS      | .5206                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                  | 1.1365                        | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES        | .0051                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE             | 1.7735                        | BODY PRIMED AND SEALED                              |
| DOORS                   | 1.8691                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                  | 5.8718                        | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                 | 10.1483                       | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM       | .8556                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC    | 1.1810                        | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS      | .2488                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.      | 2.8507                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES    | 1.0429                        | SEATS INSTALLED                                     |
| HVAC                    | 2.3410                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL        | 1.0464                        | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS      | 4.4325                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL      | .0082                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL          | .0530                         | FINISHED VEHICLE SHIPPED                            |
| ROOF                    | 1.8742                        |   |
| SEATS                   | 5.6234                        |   |
| STEERING                | .5420                         |   |
| STEP PLT./EXT. ASST.    | 4.4059                        |   |
| TRANSMISSION            | 6.5508                        |   |
| UNDER BODY              | 6.9594                        |   |
| WHEELS & TIRES          | 3.8055                        |   |
| WIPER & WASHER          | .1257                         |   |
| TOTAL US CONTENT        | 67.5512                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 2ZM69  
 PONTIAC G6  
 CARLINE 3Z  
 ASSEMBLY LOC: ORION

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | 2.0640                                 | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED                | .1771                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS               | .7342                                  | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                           | 1.1093                                 | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES                 | .0049                                  | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE                      | 1.6112                                 | BODY PRIMED AND SEALED                              |
| DOORS                            | 4.5213                                 | EXTERIOR PAINT APPLIED                              |
| ENGINE                           | 5.7120                                 | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                          | 9.8881                                 | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM                | .2978                                  | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC             | .9370                                  | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS               | .2080                                  | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.               | 2.7372                                 | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES             | 1.0163                                 | SEATS INSTALLED                                     |
| HVAC                             | 2.2812                                 | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL                 | 1.0182                                 | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS               | 4.2589                                 | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL               | .0082                                  | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL                   | .0476                                  | FINISHED VEHICLE SHIPPED                            |
| ROOF                             | 1.8003                                 |   |
| SEATS                            | 5.2576                                 |   |
| STEERING                         | .5293                                  |   |
| STEP PLT./EXT. ASST.             | 4.2625                                 |   |
| TRANSMISSION                     | 6.3599                                 |   |
| UNDER BODY                       | 6.1764                                 |   |
| WHEELS & TIRES                   | 3.7106                                 |   |
| WIPER & WASHER                   | .1225                                  |   |
| TOTAL US CONTENT                 | 66.8531                                |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 4HP69  
 BUICK LUCERNE  
 CARLINE H  
 ASSEMBLY LOC: HAMTRAMCK

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | 1.1582                                 | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED                | .0278                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS               | .8876                                  | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                           | 1.8782                                 | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES                 | .5981                                  | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE                      | .1144                                  | BODY PRIMED AND SEALED                              |
| DOORS                            | 5.2505                                 | EXTERIOR PAINT APPLIED                              |
| ENGINE                           | 9.3868                                 | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                          | 3.0378                                 | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM                | .1114                                  | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC             | 1.4755                                 | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS               | .0548                                  | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.               | 3.7952                                 | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES             | 1.2966                                 | SEATS INSTALLED                                     |
| HVAC                             | 3.2809                                 | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL                 | 2.3544                                 | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS               | 3.0939                                 | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL               | .0095                                  | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL                   | 4.4898                                 | FINISHED VEHICLE SHIPPED                            |
| ROOF                             | 1.6129                                 |   |
| SEATS                            | 5.4602                                 |   |
| STEERING                         | 2.3039                                 |   |
| STEP PLT./EXT. ASST.             | 1.8829                                 |   |
| TRANSMISSION                     | 6.5903                                 |   |
| UNDER BODY                       | 5.7199                                 |   |
| WHEELS & TIRES                   | 1.8121                                 |   |
| WIPER & WASHER                   | .1247                                  |   |
| TOTAL US CONTENT                 | 67.8096                                |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 4HR69  
 BUICK LUCERNE  
 CARLINE H  
 ASSEMBLY LOC: HAMTRAMCK

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|-------------------------------|---|
| AXLE & HALF SHAFT                | 2.8280                        | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED                | .0095                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS               | .7955                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                           | 2.0260                        | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES                 | .4203                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE                      | .3814                         | BODY PRIMED AND SEALED                              |
| DOORS                            | 4.2412                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                           | 14.6975                       | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                          | 2.7260                        | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM                | .1057                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC             | 1.1262                        | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS               | .0133                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.               | 2.7003                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES             | 1.0462                        | SEATS INSTALLED                                     |
| HVAC                             | 2.0130                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL                 | 3.5616                        | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS               | 2.4401                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL               | .0127                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL                   | 1.9010                        | FINISHED VEHICLE SHIPPED                            |
| ROOF                             | 1.8054                        |   |
| SEATS                            | .7661                         |   |
| STEERING                         | 1.4031                        |   |
| STEP PLT./EXT. ASST.             | 2.9257                        |   |
| TRANSMISSION                     | 7.9864                        |   |
| UNDER BODY                       | 4.8233                        |   |
| WHEELS & TIRES                   | .5622                         |   |
| WIPER & WASHER                   | .1135                         |   |
| TOTAL US CONTENT                 | 63.4324                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 6DM35  
 CADILLAC CTS  
 CARLINE D  
 ASSEMBLY LOC: LANSING LGR

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | 3.2125                                 | UNDERBODY FRAMING ASSEMBLED AND WELDED              |
| BATTERY & RELATED                | .1739                                  | FLOOR PANEL WELDED TO UNDERBODY                     |
| BELTS & RESTRAINTS               | .4956                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BRAKES                           | .4984                                  | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| CLUSTERS & GAGES                 | .0022                                  | HOOD, DOORS AND FENDERS INSTALLED                   |
| CONVENIENCE                      | .1257                                  | FRONT AND REAR DOORS INSTALLED                      |
| DOORS                            | 5.6269                                 | BODY PRIMED AND SEALED                              |
| ENGINE                           | 8.1077                                 | EXTERIOR PAINT APPLIED                              |
| EXHAUST                          | 3.1676                                 | ELECTRICAL WIRING INSTALLED                         |
| EXT. TRIM & ORNAM                | .1966                                  | EXTERIOR MOLDINGS INSTALLED                         |
| F. SHEET MET/PLASTIC             | 1.1200                                 | AIR CONDITIONING AND HEATER INSTALLED               |
| FRONT & REAR LAMPS               | 1.3991                                 | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR SUSP.               | 4.8206                                 | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FUEL TANK/PUMP/LINES             | .9941                                  | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| HVAC                             | 1.4588                                 | SEATS INSTALLED                                     |
| INSTRUMENT PANEL                 | .9527                                  | SUB FRAME AND ENGINE INSTALLED                      |
| MAJOR METAL PANELS               | 2.4605                                 | TRANSMISSION INSTALLED                              |
| PAINT & MI SC MTRL               | .0043                                  | TIRES MOUNTED AND INSTALLED                         |
| POWER & SIGNAL                   | .0612                                  | VEHICLE TESTED AND INSPECTED                        |
| ROOF                             | 2.0815                                 | FINISHED VEHICLE SHIPPED                            |
| SEATS                            | 1.0818                                 |   |
| STEERING                         | 1.9259                                 |   |
| STEP PLT./EXT. ASST.             | 2.1666                                 |   |
| TRANSMISSION                     | 1.6557                                 |   |
| UNDER BODY                       | 5.7041                                 |   |
| WHEELS & TIRES                   | 1.2069                                 |   |
| WI PER & WASHER                  | .3429                                  |   |
| TOTAL US CONTENT                 | 51.0450                                |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 6DM69  
 CADILLAC CTS  
 CARLINE D  
 ASSEMBLY LOC: LANSING LGR

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | 3.1454                                 | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED                | .1838                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS               | .9767                                  | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                           | .5679                                  | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES                 | -.0015                                 | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE                      | .8731                                  | BODY PRIMED AND SEALED                              |
| DOORS                            | 5.4116                                 | EXTERIOR PAINT APPLIED                              |
| ENGINE                           | 7.8198                                 | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                          | 3.4048                                 | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM                | .2946                                  | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC             | 1.2134                                 | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS               | .1412                                  | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.               | 5.8187                                 | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES             | 1.0695                                 | SEATS INSTALLED                                     |
| HVAC                             | 1.7867                                 | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL                 | 1.0973                                 | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS               | 1.8530                                 | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL               | .0217                                  | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL                   | .2434                                  | FINISHED VEHICLE SHIPPED                            |
| ROOF                             | 2.5253                                 |   |
| SEATS                            | .9986                                  |   |
| STEERING                         | 1.8575                                 |   |
| STEP PLT./EXT. ASST.             | 2.2266                                 |   |
| TRANSMISSION                     | 1.4752                                 |   |
| UNDER BODY                       | 6.0421                                 |   |
| WHEELS & TIRES                   | 2.2157                                 |   |
| WIPER & WASHER                   | .3052                                  |   |
| TOTAL US CONTENT                 | 53.5686                                |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 6DN69  
 CADILLAC CTS V  
 CARLINE D  
 ASSEMBLY LOC: LANSING LGR

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|-------------------------------|---|
| AXLE & HALF SHAFT                | 3.7517                        | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED                | .1373                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS               | .7410                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                           | .1933                         | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES                 | .0067                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE                      | 1.8277                        | BODY PRIMED AND SEALED                              |
| DOORS                            | 3.5610                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                           | 7.9365                        | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                          | 4.0625                        | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM                | .1760                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC             | .8992                         | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS               | .0090                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.               | 6.7411                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES             | 1.1239                        | SEATS INSTALLED                                     |
| HVAC                             | 2.0322                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL                 | .8463                         | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS               | 1.3517                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL               | .0245                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL                   | .1994                         | FINISHED VEHICLE SHIPPED                            |
| ROOF                             | 1.8504                        |   |
| SEATS                            | 4.8226                        |   |
| STEERING                         | 1.9515                        |   |
| STEP PLT./EXT. ASST.             | 2.7930                        |   |
| TRANSMISSION                     | 3.5637                        |   |
| UNDER BODY                       | 4.5377                        |   |
| WHEELS & TIRES                   | 1.8077                        |   |
| WIPER & WASHER                   | .3567                         |   |
| TOTAL US CONTENT                 | 57.3055                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 6DR69  
 CADILLAC CTS  
 CARLINE D  
 ASSEMBLY LOC: LANSING LGR

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|-------------------------------|---|
| AXLE & HALF SHAFT                | 2.1664                        | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED                | .1344                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS               | .8720                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                           | .6281                         | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES                 | .0031                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE                      | 3.7698                        | BODY PRIMED AND SEALED                              |
| DOORS                            | 4.1892                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                           | 5.5535                        | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                          | 2.6877                        | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM                | .2513                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC             | .9758                         | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS               | .1141                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.               | 4.9719                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES             | .8765                         | SEATS INSTALLED                                     |
| HVAC                             | 1.6558                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL                 | .9008                         | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS               | 1.5379                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL               | .0410                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL                   | .2219                         | FINISHED VEHICLE SHIPPED                            |
| ROOF                             | 2.4437                        |   |
| SEATS                            | .3310                         |   |
| STEERING                         | 2.1154                        |   |
| STEP PLT./EXT. ASST.             | 2.8677                        |   |
| TRANSMISSION                     | .5001                         |   |
| UNDER BODY                       | 5.1910                        |   |
| WHEELS & TIRES                   | 2.2570                        |   |
| WIPER & WASHER                   | .3719                         |   |
| TOTAL US CONTENT                 | 47.6241                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 6DW29  
 CADILLAC STS  
 CARLINE D  
 ASSEMBLY LOC: LANSING LGR

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | 2.8587                        | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED       | .1746                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS      | .8270                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                  | .4875                         | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES        | .0005                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE             | .2227                         | BODY PRIMED AND SEALED                              |
| DOORS                   | 5.7171                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                  | 8.8395                        | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                 | 2.8527                        | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM       | .1336                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC    | 1.0953                        | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS      | .0158                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.      | 4.6916                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES    | .8882                         | SEATS INSTALLED                                     |
| HVAC                    | 1.5676                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL        | 1.8075                        | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS      | 1.6167                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL      | .0138                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL          | .2227                         | FINISHED VEHICLE SHIPPED                            |
| ROOF                    | 1.5232                        |   |
| SEATS                   | .0543                         |   |
| STEERING                | 2.3056                        |   |
| STEP PLT./EXT. ASST.    | 2.5133                        |   |
| TRANSMISSION            | 6.3856                        |   |
| UNDER BODY              | 5.6755                        |   |
| WHEELS & TIRES          | 1.8602                        |   |
| WIPER & WASHER          | .0521                         |   |
| TOTAL US CONTENT        | 54.4042                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 6DX29  
 CADILLAC STS  
 CARLINE D  
 ASSEMBLY LOC: LANSING LGR

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | 1.8126                        | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED       | .1178                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS      | .7234                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                  | .3778                         | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES        | .0058                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE             | .2339                         | BODY PRIMED AND SEALED                              |
| DOORS                   | 7.4914                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                  | 15.7514                       | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                 | 1.5705                        | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM       | .1831                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC    | 2.1466                        | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS      | .0094                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.      | 5.1934                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES    | 1.2531                        | SEATS INSTALLED                                     |
| HVAC                    | .7749                         | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL        | 2.3319                        | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS      | 1.0714                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL      | .0088                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL          | .1586                         | FINISHED VEHICLE SHIPPED                            |
| ROOF                    | 1.0494                        |   |
| SEATS                   | .0329                         |   |
| STEERING                | 1.8735                        |   |
| STEP PLT./EXT. ASST.    | 3.4134                        |   |
| TRANSMISSION            | 3.6816                        |   |
| UNDER BODY              | 4.5063                        |   |
| WHEELS & TIRES          | .1275                         |   |
| WIPER & WASHER          | .0333                         |   |
| TOTAL US CONTENT        | 55.9350                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 6KD69  
 CADILLAC DTS  
 CARLINE K  
 ASSEMBLY LOC: HAMTRAMCK

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | 1.5531                                 | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED                | .0248                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS               | .9300                                  | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                           | 2.0146                                 | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES                 | .5488                                  | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE                      | .2896                                  | BODY PRIMED AND SEALED                              |
| DOORS                            | 5.2653                                 | EXTERIOR PAINT APPLIED                              |
| ENGINE                           | 14.7520                                | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                          | 2.7531                                 | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM                | .1020                                  | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC             | 1.0970                                 | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS               | .0067                                  | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.               | 3.3424                                 | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES             | 1.0188                                 | SEATS INSTALLED                                     |
| HVAC                             | 1.6672                                 | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL                 | 2.3297                                 | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS               | 2.5937                                 | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL               | .0203                                  | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL                   | 3.6255                                 | FINISHED VEHICLE SHIPPED                            |
| ROOF                             | 1.9585                                 |   |
| SEATS                            | 8.0346                                 |   |
| STEERING                         | 1.7947                                 |   |
| STEP PLT./EXT. ASST.             | 2.9799                                 |   |
| TRANSMISSION                     | 7.6946                                 |   |
| UNDER BODY                       | 4.8821                                 |   |
| WHEELS & TIRES                   | 1.8793                                 |   |
| WIPER & WASHER                   | .2181                                  |   |
| TOTAL US CONTENT                 | 73.3781                                |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 6NG26  
 CADILLAC GMT166  
 CARLINE N  
 ASSEMBLY LOC: RAMOS

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | .1966                         | UNDERBODY FRAMING ASSEMBLED AND WELDED              |
| BATTERY & RELATED       | .1715                         | FLOOR PANEL WELDED TO UNDERBODY                     |
| BELTS & RESTRAINTS      | .5710                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BRAKES                  | .2394                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| CLUSTERS & GAGES        | .5213                         | HOOD, DOORS AND FENDERS INSTALLED                   |
| CONVENIENCE             | .5499                         | FRONT AND REAR DOORS INSTALLED                      |
| DOORS                   | 2.1371                        | BODY PRIMED AND SEALED                              |
| ENGINE                  | 5.5222                        | EXTERIOR PAINT APPLIED                              |
| EXHAUST                 | .7110                         | ELECTRICAL WIRING INSTALLED                         |
| EXT. TRIM & ORNAM       | .2535                         | EXTERIOR MOLDINGS INSTALLED                         |
| F. SHEET MET/PLASTIC    | .3997                         | AIR CONDITIONING AND HEATER INSTALLED               |
| FRONT & REAR LAMPS      | 1.7691                        | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR SUSP.      | 5.4898                        | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FUEL TANK/PUMP/LINES    | 1.1890                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| HVAC                    | .3577                         | SEATS INSTALLED                                     |
| INSTRUMENT PANEL        | .1166                         | SUB FRAME AND ENGINE INSTALLED                      |
| MAJOR METAL PANELS      | .9023                         | TRANSMISSION INSTALLED                              |
| PAINT & MI SC MTRL      | .0158                         | TIRES MOUNTED AND INSTALLED                         |
| POWER & SIGNAL          | .2686                         | VEHICLE TESTED AND INSPECTED                        |
| ROOF                    | .1675                         | FINISHED VEHICLE SHIPPED                            |
| SEATS                   | .0065                         |   |
| STEERING                | 1.3079                        |   |
| STEP PLT./EXT. ASST.    | .1453                         |   |
| TRANSMISSION            | 4.5458                        |   |
| UNDER BODY              | 1.1491                        |   |
| WHEELS & TIRES          | 3.0671                        |   |
| WIPER & WASHER          | .2663                         |   |
| TOTAL US CONTENT        | 32.0389                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 6YV67  
 CADILLAC XLR  
 CARLINE Y  
 ASSEMBLY LOC: BOWLING GREEN

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|-------------------------------|---|
| AXLE & HALF SHAFT                | 1.6815                        | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED                | .0995                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS               | .5126                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                           | .8271                         | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES                 | .0426                         | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE                      | 1.3729                        | BODY PRIMED AND SEALED                              |
| DOORS                            | 5.2484                        | EXTERIOR PAINT APPLIED                              |
| ENGINE                           | 10.9503                       | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                          | 1.1467                        | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM                | .0247                         | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC             | 1.8962                        | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS               | .3159                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.               | 2.9310                        | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES             | 1.1516                        | SEATS INSTALLED                                     |
| HVAC                             | 2.2794                        | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL                 | 1.8999                        | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS               | 3.1580                        | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL               | .0220                         | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL                   | .4982                         | FINISHED VEHICLE SHIPPED                            |
| ROOF                             | 10.8507                       |   |
| SEATS                            | 3.6255                        |   |
| STEERING                         | 2.5386                        |   |
| STEP PLT./EXT. ASST.             | 2.4352                        |   |
| TRANSMISSION                     | 5.3954                        |   |
| UNDER BODY                       | 5.2906                        |   |
| WHEELS & TIRES                   | 1.3117                        |   |
| WIPER & WASHER                   | .1233                         |   |
| TOTAL US CONTENT                 | 67.6308                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 6YX67  
 CADILLAC XLR  
 CARLINE Y  
 ASSEMBLY LOC: BOWLING GREEN

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | .3531                                  | FLOOR PANEL WELDED TO UNDERBODY                     |
| BATTERY & RELATED                | .0869                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BELTS & RESTRAINTS               | .4413                                  | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| BRAKES                           | .7251                                  | HOOD, DOORS AND FENDERS INSTALLED                   |
| CLUSTERS & GAGES                 | .0344                                  | FRONT AND REAR DOORS INSTALLED                      |
| CONVENIENCE                      | 1.2168                                 | BODY PRIMED AND SEALED                              |
| DOORS                            | 4.3126                                 | EXTERIOR PAINT APPLIED                              |
| ENGINE                           | 15.1745                                | ELECTRICAL WIRING INSTALLED                         |
| EXHAUST                          | 2.7434                                 | EXTERIOR MOLDINGS INSTALLED                         |
| EXT. TRIM & ORNAM                | .0405                                  | AIR CONDITIONING AND HEATER INSTALLED               |
| F. SHEET MET/PLASTIC             | 1.6851                                 | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR LAMPS               | .2756                                  | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FRONT & REAR SUSP.               | 2.8292                                 | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| FUEL TANK/PUMP/LINES             | 1.2384                                 | SEATS INSTALLED                                     |
| HVAC                             | 2.6099                                 | SUB FRAME AND ENGINE INSTALLED                      |
| INSTRUMENT PANEL                 | 2.0488                                 | TRANSMISSION INSTALLED                              |
| MAJOR METAL PANELS               | 2.7591                                 | TIRES MOUNTED AND INSTALLED                         |
| PAINT & MI SC MTRL               | .0194                                  | VEHICLE TESTED AND INSPECTED                        |
| POWER & SIGNAL                   | .4631                                  | FINISHED VEHICLE SHIPPED                            |
| ROOF                             | 9.4831                                 |   |
| SEATS                            | 4.3643                                 |   |
| STEERING                         | 2.3823                                 |   |
| STEP PLT./EXT. ASST.             | 1.1907                                 |   |
| TRANSMISSION                     | 4.8226                                 |   |
| UNDER BODY                       | 5.1148                                 |   |
| WHEELS & TIRES                   | .2577                                  |   |
| WIPER & WASHER                   | .1129                                  |   |
| TOTAL US CONTENT                 | 66.7869                                |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 1EE37  
 CHEVY CAMARO  
 CARLINE 8E  
 ASSEMBLY LOC: OSHAWA CAR 1

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | .7580                                  | UNDERBODY FRAMING ASSEMBLED AND WELDED              |
| BATTERY & RELATED                | .0093                                  | FLOOR PANEL WELDED TO UNDERBODY                     |
| BELTS & RESTRAINTS               | 1.0760                                 | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BRAKES                           | 1.4970                                 | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| CLUSTERS & GAGES                 | .0005                                  | HOOD, DOORS AND FENDERS INSTALLED                   |
| CONVENIENCE                      | .0298                                  | FRONT AND REAR DOORS INSTALLED                      |
| DOORS                            | 2.0757                                 | BODY PRIMED AND SEALED                              |
| ENGINE                           | 8.4487                                 | EXTERIOR PAINT APPLIED                              |
| EXHAUST                          | 2.9953                                 | ELECTRICAL WIRING INSTALLED                         |
| EXT. TRIM & ORNAM                | .0038                                  | EXTERIOR MOLDINGS INSTALLED                         |
| F. SHEET MET/PLASTIC             | .3050                                  | AIR CONDITIONING AND HEATER INSTALLED               |
| FRONT & REAR LAMPS               | .0597                                  | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR SUSP.               | 2.1776                                 | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FUEL TANK/PUMP/LINES             | 1.7249                                 | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| HVAC                             | 2.5627                                 | SEATS INSTALLED                                     |
| INSTRUMENT PANEL                 | .8165                                  | SUB FRAME AND ENGINE INSTALLED                      |
| MAJOR METAL PANELS               | 1.0283                                 | TRANSMISSION INSTALLED                              |
| PAINT & MI SC MTRL               | .0023                                  | TIRES MOUNTED AND INSTALLED                         |
| POWER & SIGNAL                   | .0238                                  | VEHICLE TESTED AND INSPECTED                        |
| ROOF                             | .5225                                  | FINISHED VEHICLE SHIPPED                            |
| SEATS                            | 5.2751                                 |   |
| STEERING                         | 1.9197                                 |   |
| STEP PLT./EXT. ASST.             | .5526                                  |   |
| TRANSMISSION                     | 5.2686                                 |   |
| UNDER BODY                       | 2.0605                                 |   |
| WHEELS & TIRES                   | 2.0962                                 |   |
| WIPER & WASHER                   | .2139                                  |   |
| TOTAL US CONTENT                 | 43.5054                                |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 1EF37  
 CHEVY CAMARO  
 CARLINE 8E  
 ASSEMBLY LOC: OSHAWA CAR 1

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | .7434                                  | UNDERBODY FRAMING ASSEMBLED AND WELDED              |
| BATTERY & RELATED                | .0066                                  | FLOOR PANEL WELDED TO UNDERBODY                     |
| BELTS & RESTRAINTS               | 1.2389                                 | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BRAKES                           | 1.3852                                 | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| CLUSTERS & GAGES                 | .0004                                  | HOOD, DOORS AND FENDERS INSTALLED                   |
| CONVENIENCE                      | .0654                                  | FRONT AND REAR DOORS INSTALLED                      |
| DOORS                            | 2.2187                                 | BODY PRIMED AND SEALED                              |
| ENGINE                           | 8.2585                                 | EXTERIOR PAINT APPLIED                              |
| EXHAUST                          | 2.7664                                 | ELECTRICAL WIRING INSTALLED                         |
| EXT. TRIM & ORNAM                | .0035                                  | EXTERIOR MOLDINGS INSTALLED                         |
| F. SHEET MET/PLASTIC             | .2868                                  | AIR CONDITIONING AND HEATER INSTALLED               |
| FRONT & REAR LAMPS               | .0025                                  | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR SUSP.               | 2.0120                                 | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FUEL TANK/PUMP/LINES             | 1.5899                                 | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| HVAC                             | 2.3067                                 | SEATS INSTALLED                                     |
| INSTRUMENT PANEL                 | .9170                                  | SUB FRAME AND ENGINE INSTALLED                      |
| MAJOR METAL PANELS               | .9477                                  | TRANSMISSION INSTALLED                              |
| PAINT & MI SC MTRL               | .0021                                  | TIRES MOUNTED AND INSTALLED                         |
| POWER & SIGNAL                   | .0242                                  | VEHICLE TESTED AND INSPECTED                        |
| ROOF                             | .9033                                  | FINISHED VEHICLE SHIPPED                            |
| SEATS                            | 2.1580                                 |   |
| STEERING                         | 1.8684                                 |   |
| STEP PLT./EXT. ASST.             | .3793                                  |   |
| TRANSMISSION                     | 3.2564                                 |   |
| UNDER BODY                       | 2.5927                                 |   |
| WHEELS & TIRES                   | .0633                                  |   |
| WIPER & WASHER                   | .1954                                  |   |
| TOTAL US CONTENT                 | 36.1940                                |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 1ES37  
 CHEVY CAMARO  
 CARLINE 8E  
 ASSEMBLY LOC: OSHAWA CAR 1

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | .8034                                  | UNDERBODY FRAMING ASSEMBLED AND WELDED              |
| BATTERY & RELATED                | .0092                                  | FLOOR PANEL WELDED TO UNDERBODY                     |
| BELTS & RESTRAINTS               | 1.3175                                 | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BRAKES                           | .9919                                  | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| CLUSTERS & GAGES                 | .0004                                  | HOOD, DOORS AND FENDERS INSTALLED                   |
| CONVENIENCE                      | .0844                                  | FRONT AND REAR DOORS INSTALLED                      |
| DOORS                            | 2.2589                                 | BODY PRIMED AND SEALED                              |
| ENGINE                           | 9.9308                                 | EXTERIOR PAINT APPLIED                              |
| EXHAUST                          | 2.8739                                 | ELECTRICAL WIRING INSTALLED                         |
| EXT. TRIM & ORNAM                | .0034                                  | EXTERIOR MOLDINGS INSTALLED                         |
| F. SHEET MET/PLASTIC             | .2598                                  | AIR CONDITIONING AND HEATER INSTALLED               |
| FRONT & REAR LAMPS               | .0024                                  | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR SUSP.               | 1.9407                                 | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FUEL TANK/PUMP/LINES             | 1.5286                                 | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| HVAC                             | 2.5224                                 | SEATS INSTALLED                                     |
| INSTRUMENT PANEL                 | .9314                                  | SUB FRAME AND ENGINE INSTALLED                      |
| MAJOR METAL PANELS               | .9184                                  | TRANSMISSION INSTALLED                              |
| PAINT & MI SC MTRL               | .0020                                  | TIRES MOUNTED AND INSTALLED                         |
| POWER & SIGNAL                   | .0219                                  | VEHICLE TESTED AND INSPECTED                        |
| ROOF                             | 1.2313                                 | FINISHED VEHICLE SHIPPED                            |
| SEATS                            | .8527                                  |   |
| STEERING                         | 1.8827                                 |   |
| STEP PLT./EXT. ASST.             | .4945                                  |   |
| TRANSMISSION                     | 2.3225                                 |   |
| UNDER BODY                       | 2.9893                                 |   |
| WHEELS & TIRES                   | .0613                                  |   |
| WIPER & WASHER                   | .1914                                  |   |
| TOTAL US CONTENT                 | 36.4286                                |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 4GB69  
 BUICK LACROSSE  
 CARLINE OG  
 ASSEMBLY LOC: FAIRFAX

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | .8399                                  | UNDERBODY FRAMING ASSEMBLED AND WELDED              |
| BATTERY & RELATED                | .0154                                  | FLOOR PANEL WELDED TO UNDERBODY                     |
| BELTS & RESTRAINTS               | .5521                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BRAKES                           | .2873                                  | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| CLUSTERS & GAGES                 | .5429                                  | HOOD, DOORS AND FENDERS INSTALLED                   |
| CONVENIENCE                      | .8645                                  | FRONT AND REAR DOORS INSTALLED                      |
| DOORS                            | 2.4848                                 | BODY PRIMED AND SEALED                              |
| ENGINE                           | 6.1344                                 | EXTERIOR PAINT APPLIED                              |
| EXHAUST                          | 1.2684                                 | ELECTRICAL WIRING INSTALLED                         |
| EXT. TRIM & ORNAM                | .2044                                  | EXTERIOR MOLDINGS INSTALLED                         |
| F. SHEET MET/PLASTIC             | 1.2627                                 | AIR CONDITIONING AND HEATER INSTALLED               |
| FRONT & REAR LAMPS               | .0402                                  | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR SUSP.               | .5678                                  | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FUEL TANK/PUMP/LINES             | 1.1179                                 | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| HVAC                             | 2.0747                                 | SEATS INSTALLED                                     |
| INSTRUMENT PANEL                 | 2.3128                                 | SUB FRAME AND ENGINE INSTALLED                      |
| MAJOR METAL PANELS               | 2.3087                                 | TRANSMISSION INSTALLED                              |
| PAINT & MI SC MTRL               | .0028                                  | TIRES MOUNTED AND INSTALLED                         |
| POWER & SIGNAL                   | .0664                                  | VEHICLE TESTED AND INSPECTED                        |
| ROOF                             | 1.2912                                 | FINISHED VEHICLE SHIPPED                            |
| SEATS                            | 5.5778                                 |   |
| STEERING                         | .6850                                  |   |
| STEP PLT./EXT. ASST.             | 1.7476                                 |   |
| TRANSMISSION                     | 7.3788                                 |   |
| UNDER BODY                       | 6.7610                                 |   |
| WHEELS & TIRES                   | 2.3234                                 |   |
| WIPER & WASHER                   | .0116                                  |   |
| TOTAL US CONTENT                 | 48.7258                                |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 4GM69  
 BUICK LACROSSE  
 CARLINE OG  
 ASSEMBLY LOC: FAIRFAX

| US<br>CONTENT BY SYSTEM | PERCENTAGE OF<br>VEHICLE COST | DESCRIPTION OF ASSEMBLY OPERATIONS                  |
|-------------------------|-------------------------------|---|
| AXLE & HALF SHAFT       | 1.4461                        | UNDERBODY FRAMING ASSEMBLED AND WELDED              |
| BATTERY & RELATED       | .0151                         | FLOOR PANEL WELDED TO UNDERBODY                     |
| BELTS & RESTRAINTS      | .5751                         | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BRAKES                  | .2496                         | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| CLUSTERS & GAGES        | .4850                         | HOOD, DOORS AND FENDERS INSTALLED                   |
| CONVENIENCE             | .4837                         | FRONT AND REAR DOORS INSTALLED                      |
| DOORS                   | 2.2100                        | BODY PRIMED AND SEALED                              |
| ENGINE                  | 5.4355                        | EXTERIOR PAINT APPLIED                              |
| EXHAUST                 | 1.0886                        | ELECTRICAL WIRING INSTALLED                         |
| EXT. TRIM & ORNAM       | .1431                         | EXTERIOR MOLDINGS INSTALLED                         |
| F. SHEET MET/PLASTIC    | 1.1055                        | AIR CONDITIONING AND HEATER INSTALLED               |
| FRONT & REAR LAMPS      | .0359                         | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR SUSP.      | .7790                         | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FUEL TANK/PUMP/LINES    | .4664                         | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| HVAC                    | 1.9103                        | SEATS INSTALLED                                     |
| INSTRUMENT PANEL        | 2.0226                        | SUB FRAME AND ENGINE INSTALLED                      |
| MAJOR METAL PANELS      | 1.8432                        | TRANSMISSION INSTALLED                              |
| PAINT & MI SC MTRL      | .0026                         | TIRES MOUNTED AND INSTALLED                         |
| POWER & SIGNAL          | .1485                         | VEHICLE TESTED AND INSPECTED                        |
| ROOF                    | 1.4803                        | FINISHED VEHICLE SHIPPED                            |
| SEATS                   | 4.7823                        |   |
| STEERING                | 1.4864                        |   |
| STEP PLT./EXT. ASST.    | 1.9664                        |   |
| TRANSMISSION            | 6.4846                        |   |
| UNDER BODY              | 5.9099                        |   |
| WHEELS & TIRES          | 1.5630                        |   |
| WIPER & WASHER          | .1292                         |   |
| TOTAL US CONTENT        | 44.2493                       |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663

GENERAL MOTORS COMPANY - NORTH AMERICAN OPERATIONS  
 BUY AMERICAN CERTIFICATION  
 2010 MODEL YEAR

MODEL 4GT69  
 BUICK LACROSSE  
 CARLINE OG  
 ASSEMBLY LOC: FAIRFAX

| US<br>CONTENT BY SYSTEM<br>----- | PERCENTAGE OF<br>VEHICLE COST<br>----- | DESCRIPTION OF ASSEMBLY OPERATIONS<br>-----         |
|----------------------------------|--|---|
| AXLE & HALF SHAFT                | .7469                                  | UNDERBODY FRAMING ASSEMBLED AND WELDED              |
| BATTERY & RELATED                | .0358                                  | FLOOR PANEL WELDED TO UNDERBODY                     |
| BELTS & RESTRAINTS               | .6329                                  | SIDE AND OUTER PANELS WELDED TO FRAMING             |
| BRAKES                           | .2599                                  | WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED |
| CLUSTERS & GAGES                 | .5097                                  | HOOD, DOORS AND FENDERS INSTALLED                   |
| CONVENIENCE                      | .7890                                  | FRONT AND REAR DOORS INSTALLED                      |
| DOORS                            | 2.2648                                 | BODY PRIMED AND SEALED                              |
| ENGINE                           | 6.3077                                 | EXTERIOR PAINT APPLIED                              |
| EXHAUST                          | 1.0859                                 | ELECTRICAL WIRING INSTALLED                         |
| EXT. TRIM & ORNAM                | .0727                                  | EXTERIOR MOLDINGS INSTALLED                         |
| F. SHEET MET/PLASTIC             | 1.1342                                 | AIR CONDITIONING AND HEATER INSTALLED               |
| FRONT & REAR LAMPS               | .0358                                  | INSTRUMENT PANEL INSTALLED                          |
| FRONT & REAR SUSP.               | .8565                                  | DOOR HARDWARE AND WINDOWS INSTALLED                 |
| FUEL TANK/PUMP/LINES             | .9950                                  | INTERIOR TRIM & FLOOR COVERING INSTALLED            |
| HVAC                             | 1.9395                                 | SEATS INSTALLED                                     |
| INSTRUMENT PANEL                 | 2.0875                                 | SUB FRAME AND ENGINE INSTALLED                      |
| MAJOR METAL PANELS               | 1.7749                                 | TRANSMISSION INSTALLED                              |
| PAINT & MI SC MTRL               | .0022                                  | TIRES MOUNTED AND INSTALLED                         |
| POWER & SIGNAL                   | .0590                                  | VEHICLE TESTED AND INSPECTED                        |
| ROOF                             | 1.4177                                 | FINISHED VEHICLE SHIPPED                            |
| SEATS                            | 2.2553                                 |   |
| STEERING                         | .6092                                  |   |
| STEP PLT./EXT. ASST.             | 2.8125                                 |   |
| TRANSMISSION                     | 6.5620                                 |   |
| UNDER BODY                       | 5.8098                                 |   |
| WHEELS & TIRES                   | 4.3813                                 |   |
| WIPER & WASHER                   | .2115                                  |   |
| TOTAL US CONTENT                 | 45.6502                                |   |

PREPARED BY:  
 GENERAL MOTORS COMPANY  
 GMNA PRODUCT COST DEVELOPMENT  
 MAILCODE 480-108-315  
 30400 MOUND RD  
 WARREN, MI. 48090-9065  
 TEL: (586)986-8155,  
 UMTAR1 ZZ6W54 20090803

REGULATORY PROVISION:  
 FEDERAL TRANSIT ADMINISTRATION  
 DEPARTMENT OF TRANSPORTATION  
 BUY AMERICAN PROGRAM  
 CFR CH. VI, PART 663