

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 6KH69
 CADILLAC CT6
 CARLINE K

ASSEMBLY LOC: HAMTRAMCK, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.9305	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	.9014	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.8460	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	.4308	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.6894	FRONT AND REAR DOORS INSTALLED
DOORS	2.3314	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	1.3961	EXTERIOR PAINT APPLIED
ENGINE	12.4814	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	.6489	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	.5728	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	2.7081	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.4866	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	.6074	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	1.0913	SEATS INSTALLED
SEATS	.0053	SUB FRAME AND ENGINE INSTALLED
STEERING	.1864	TRANSMISSION INSTALLED
TRANSMISSION	5.4709	TIRES MOUNTED AND INSTALLED
UNDER BODY	7.0639	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	.4302	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	43.2797	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 6KJ69
 CADILLAC CT6
 CARLINE K

ASSEMBLY LOC: HAMTRAMCK, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.7463	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	1.4663	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.7603	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	.3846	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.1994	FRONT AND REAR DOORS INSTALLED
DOORS	2.0703	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	1.5908	EXTERIOR PAINT APPLIED
ENGINE	12.0333	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	.6808	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	.5288	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	2.4443	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.5971	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	.6559	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	.9834	SEATS INSTALLED
SEATS	.0047	SUB FRAME AND ENGINE INSTALLED
STEERING	.1679	TRANSMISSION INSTALLED
TRANSMISSION	6.3652	TIRES MOUNTED AND INSTALLED
UNDER BODY	6.5288	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	.2643	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	41.4735	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 6KL69
 CADILLAC CT6
 CARLINE K

ASSEMBLY LOC: HAMTRAMCK, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.8230	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	1.4256	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.5586	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	.3592	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.1904	FRONT AND REAR DOORS INSTALLED
DOORS	1.9470	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	2.6783	EXTERIOR PAINT APPLIED
ENGINE	12.7620	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	.6883	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	.4898	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	2.2939	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.6911	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	.6666	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	.9586	SEATS INSTALLED
SEATS	.0044	SUB FRAME AND ENGINE INSTALLED
STEERING	.1581	TRANSMISSION INSTALLED
TRANSMISSION	5.5964	TIRES MOUNTED AND INSTALLED
UNDER BODY	6.1119	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	.4542	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	41.8584	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 6KM69
 CADILLAC CT6
 CARLINE K

ASSEMBLY LOC: HAMTRAMCK, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.5927	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	1.6590	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.2628	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	.2866	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.1581	FRONT AND REAR DOORS INSTALLED
DOORS	1.5445	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	3.2534	EXTERIOR PAINT APPLIED
ENGINE	11.5442	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	.5522	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	.3887	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	1.8501	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.6045	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	.5164	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	1.1471	SEATS INSTALLED
SEATS	.0060	SUB FRAME AND ENGINE INSTALLED
STEERING	.1273	TRANSMISSION INSTALLED
TRANSMISSION	2.9899	TIRES MOUNTED AND INSTALLED
UNDER BODY	4.9165	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	1.0633	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	36.4643	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL C15543
 K2XX LD SILVERADO/SIERRA - CREW CAB
 CARLINE 06
 ASSEMBLY LOC: SILAO, GJ MEXICO

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	.4856	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	1.5461	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	.4111	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	2.1539	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.8116	FRONT AND REAR DOORS INSTALLED
COMM. BODY EQUIP	.0081	BODY PRIMED AND SEALED
DOORS	1.0562	EXTERIOR PAINT APPLIED
ELECT SYS & INST PNL	3.5938	ELECTRICAL WIRING INSTALLED
ENGINE	.3944	EXTERIOR MOLDINGS INSTALLED
FRAME	.2813	AIR CONDITIONING AND HEATER INSTALLED
FRT AXLE/SUSPENSION	.0845	INSTRUMENT PANEL INSTALLED
FUEL TANK / EXHAUST	.3936	DOOR HARDWARE AND WINDOWS INSTALLED
HOOD/FRONT END COMP.	.4483	INTERIOR TRIM & FLOOR COVERING INSTALLED
RADIATOR & GRILLE	.3187	SEATS INSTALLED
REAR AXLE/SUSPENSION	.3488	SUB FRAME AND ENGINE INSTALLED
ROOF	.2279	TRANSMISSION INSTALLED
SEATS	.1442	TIRES MOUNTED AND INSTALLED
STEERING	1.2674	VEHICLE TESTED AND INSPECTED
TRANSMISSION	7.5979	FINISHED VEHICLE SHIPPED
UNDER BODY	.7583	
WHEELS & TIRES	1.5626	
TOTAL US CONTENT	24.8955	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL C15703
 K2XX LD SILVERADO/SIERRA - REG CAB
 CARLINE 06
 ASSEMBLY LOC: FORT WAYNE, INDIANA U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.7075	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	2.7577	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.8979	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	2.9899	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	2.4488	FRONT AND REAR DOORS INSTALLED
COMM. BODY EQUIP	.0087	BODY PRIMED AND SEALED
DOORS	3.2687	EXTERIOR PAINT APPLIED
ELECT SYS & INST PNL	4.3792	ELECTRICAL WIRING INSTALLED
ENGINE	16.7194	EXTERIOR MOLDINGS INSTALLED
FRAME	.2935	AIR CONDITIONING AND HEATER INSTALLED
FRT AXLE/SUSPENSION	.1091	INSTRUMENT PANEL INSTALLED
FUEL TANK / EXHAUST	1.4415	DOOR HARDWARE AND WINDOWS INSTALLED
HOOD/FRONT END COMP.	2.5749	INTERIOR TRIM & FLOOR COVERING INSTALLED
RADIATOR & GRILLE	1.7648	SEATS INSTALLED
REAR AXLE/SUSPENSION	.4171	SUB FRAME AND ENGINE INSTALLED
ROOF	.3831	TRANSMISSION INSTALLED
SEATS	.1525	TIRES MOUNTED AND INSTALLED
STEERING	1.1774	VEHICLE TESTED AND INSPECTED
TRANSMISSION	8.1038	FINISHED VEHICLE SHIPPED
UNDER BODY	1.3725	
WHEELS & TIRES	3.2316	
TOTAL US CONTENT	58.2007	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL C15706
 CHEVROLET TAHOE/GMC YUKON/CADILLAC ESCALADE
 CARLINE 06
 ASSEMBLY LOC: ARLINGTON, TEXAS U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	.8460	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	2.1274	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.1494	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.8528	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	2.7658	FRONT AND REAR DOORS INSTALLED
DOORS	4.4497	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	2.8603	EXTERIOR PAINT APPLIED
ENGINE	2.9567	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	.0616	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	.1269	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	1.6904	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.0990	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	.3495	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	.7430	SEATS INSTALLED
SEATS	.1887	SUB FRAME AND ENGINE INSTALLED
STEERING	.4130	TRANSMISSION INSTALLED
TRANSMISSION	8.2815	TIRES MOUNTED AND INSTALLED
UNDER BODY	2.3067	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	2.3501	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	36.6194	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL C15743
 K2XX LD SILVERADO/SIERRA - CREW CAB
 CARLINE 06
 ASSEMBLY LOC: SILAO, GJ MEXICO

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.1148	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	1.9467	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	1.6211	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	2.2783	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	2.1740	FRONT AND REAR DOORS INSTALLED
COMM. BODY EQUIP	.0078	BODY PRIMED AND SEALED
DOORS	3.1035	EXTERIOR PAINT APPLIED
ELECT SYS & INST PNL	4.1566	ELECTRICAL WIRING INSTALLED
ENGINE	8.4347	EXTERIOR MOLDINGS INSTALLED
FRAME	.2612	AIR CONDITIONING AND HEATER INSTALLED
FRT AXLE/SUSPENSION	.0833	INSTRUMENT PANEL INSTALLED
FUEL TANK / EXHAUST	1.1490	DOOR HARDWARE AND WINDOWS INSTALLED
HOOD/FRONT END COMP.	1.3243	INTERIOR TRIM & FLOOR COVERING INSTALLED
RADIATOR & GRILLE	.6814	SEATS INSTALLED
REAR AXLE/SUSPENSION	.3419	SUB FRAME AND ENGINE INSTALLED
ROOF	.6101	TRANSMISSION INSTALLED
SEATS	3.4808	TIRES MOUNTED AND INSTALLED
STEERING	1.1865	VEHICLE TESTED AND INSPECTED
TRANSMISSION	7.1903	FINISHED VEHICLE SHIPPED
UNDER BODY	2.3133	
WHEELS & TIRES	2.1842	
TOTAL US CONTENT	45.6448	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL C15753
 K2XX LD SILVERADO/SIERRA - EXT CAB
 CARLINE 06
 ASSEMBLY LOC: FORT WAYNE, INDIANA U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.7973	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	2.6352	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	3.0873	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	2.6662	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	2.4328	FRONT AND REAR DOORS INSTALLED
COMM. BODY EQUIP	.0079	BODY PRIMED AND SEALED
DOORS	4.9112	EXTERIOR PAINT APPLIED
ELECT SYS & INST PNL	3.7040	ELECTRICAL WIRING INSTALLED
ENGINE	13.1509	EXTERIOR MOLDINGS INSTALLED
FRAME	.2618	AIR CONDITIONING AND HEATER INSTALLED
FRT AXLE/SUSPENSION	.0984	INSTRUMENT PANEL INSTALLED
FUEL TANK / EXHAUST	2.1914	DOOR HARDWARE AND WINDOWS INSTALLED
HOOD/FRONT END COMP.	2.3491	INTERIOR TRIM & FLOOR COVERING INSTALLED
RADIATOR & GRILLE	1.5636	SEATS INSTALLED
REAR AXLE/SUSPENSION	.3562	SUB FRAME AND ENGINE INSTALLED
ROOF	.5527	TRANSMISSION INSTALLED
SEATS	.1493	TIRES MOUNTED AND INSTALLED
STEERING	1.1395	VEHICLE TESTED AND INSPECTED
TRANSMISSION	7.3180	FINISHED VEHICLE SHIPPED
UNDER BODY	2.0681	
WHEELS & TIRES	2.6146	
TOTAL US CONTENT	55.0564	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL C15903
 K2XX LD SILVERADO/SIERRA - REG CAB
 CARLINE 06
 ASSEMBLY LOC: FORT WAYNE, INDIANA U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.7204	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	2.7034	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	3.0542	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	2.9781	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	2.3849	FRONT AND REAR DOORS INSTALLED
COMM. BODY EQUIP	.0088	BODY PRIMED AND SEALED
DOORS	3.1643	EXTERIOR PAINT APPLIED
ELECT SYS & INST PNL	4.3372	ELECTRICAL WIRING INSTALLED
ENGINE	17.3979	EXTERIOR MOLDINGS INSTALLED
FRAME	.2967	AIR CONDITIONING AND HEATER INSTALLED
FRT AXLE/SUSPENSION	.1030	INSTRUMENT PANEL INSTALLED
FUEL TANK / EXHAUST	1.5812	DOOR HARDWARE AND WINDOWS INSTALLED
HOOD/FRONT END COMP.	2.5985	INTERIOR TRIM & FLOOR COVERING INSTALLED
RADIATOR & GRILLE	1.7751	SEATS INSTALLED
REAR AXLE/SUSPENSION	.3971	SUB FRAME AND ENGINE INSTALLED
ROOF	.3860	TRANSMISSION INSTALLED
SEATS	.1521	TIRES MOUNTED AND INSTALLED
STEERING	1.1553	VEHICLE TESTED AND INSPECTED
TRANSMISSION	8.1712	FINISHED VEHICLE SHIPPED
UNDER BODY	1.3782	
WHEELS & TIRES	3.1788	
TOTAL US CONTENT	58.9236	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL C15906
 CHEV SUBURB/GMC YKN XL/CADILLAC ESC ESV
 CARLINE 06
 ASSEMBLY LOC: ARLINGTON, TEXAS U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	.8044	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	2.7196	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.3199	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.7815	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	3.0707	FRONT AND REAR DOORS INSTALLED
DOORS	4.3324	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	3.2696	EXTERIOR PAINT APPLIED
ENGINE	4.0665	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	.0595	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	.5448	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	1.6536	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.0949	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	.3808	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	.9949	SEATS INSTALLED
SEATS	.1609	SUB FRAME AND ENGINE INSTALLED
STEERING	.4266	TRANSMISSION INSTALLED
TRANSMISSION	7.9338	TIRES MOUNTED AND INSTALLED
UNDER BODY	2.6413	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	2.2048	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	39.4613	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL C36003
 K2XX HD SILVERADO/SIERRA - CHASSIS CAB
 CARLINE 06
 ASSEMBLY LOC: FLINT, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	.2140	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	1.6573	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	.5882	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	4.4981	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.1899	FRONT AND REAR DOORS INSTALLED
DOORS	.7314	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	3.2693	EXTERIOR PAINT APPLIED
ENGINE	.3916	ELECTRICAL WIRING INSTALLED
FRAME	.2009	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	1.6935	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	5.0605	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	.8913	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	1.4336	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	11.1844	SEATS INSTALLED
ROOF	.0576	SUB FRAME AND ENGINE INSTALLED
SEATS	.1479	TRANSMISSION INSTALLED
STEERING	2.5852	TIRES MOUNTED AND INSTALLED
TRANSMISSION	1.1711	VEHICLE TESTED AND INSPECTED
UNDER BODY	.6645	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	.4473	
TOTAL US CONTENT	37.0787	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL G23405
 CHEVROLET EXPRESS / GMC SAVANA
 CARLINE 08
 ASSEMBLY LOC: WENTZVILLE, MISSOURI U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.5031	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	4.0085	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.6013	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	3.0031	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.5364	FRONT AND REAR DOORS INSTALLED
DOORS	4.9337	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	1.9273	EXTERIOR PAINT APPLIED
ENGINE	1.2824	ELECTRICAL WIRING INSTALLED
FRAME	3.8253	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	1.5287	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	5.7901	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	1.1911	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	1.0003	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	6.3890	SEATS INSTALLED
ROOF	1.1637	SUB FRAME AND ENGINE INSTALLED
SEATS	.0932	TRANSMISSION INSTALLED
STEERING	2.0095	TIRES MOUNTED AND INSTALLED
TRANSMISSION	8.5796	VEHICLE TESTED AND INSPECTED
UNDER BODY	3.3504	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	4.1003	
TOTAL US CONTENT	59.8180	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL G23406
 CHEVROLET EXPRESS / GMC SAVANA
 CARLINE 08
 ASSEMBLY LOC: WENTZVILLE, MISSOURI U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.2852	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	3.7044	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	3.8501	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	2.4952	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.3324	FRONT AND REAR DOORS INSTALLED
DOORS	4.5453	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	1.6626	EXTERIOR PAINT APPLIED
ENGINE	1.3618	ELECTRICAL WIRING INSTALLED
FRAME	3.1906	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	1.2765	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	4.9432	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	1.0354	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	.9885	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	5.2605	SEATS INSTALLED
ROOF	2.3762	SUB FRAME AND ENGINE INSTALLED
SEATS	3.3799	TRANSMISSION INSTALLED
STEERING	1.6746	TIRES MOUNTED AND INSTALLED
TRANSMISSION	7.0298	VEHICLE TESTED AND INSPECTED
UNDER BODY	3.1191	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	3.3277	
TOTAL US CONTENT	57.8401	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL G23705
 CHEVROLET EXPRESS / GMC SAVANA
 CARLINE 08
 ASSEMBLY LOC: WENTZVILLE, MISSOURI U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.4975	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	3.9200	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.7857	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	2.9468	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.5409	FRONT AND REAR DOORS INSTALLED
DOORS	4.7911	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	1.8690	EXTERIOR PAINT APPLIED
ENGINE	1.2473	ELECTRICAL WIRING INSTALLED
FRAME	3.8806	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	1.5022	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	5.7367	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	1.1761	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	1.0158	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	6.2592	SEATS INSTALLED
ROOF	1.3726	SUB FRAME AND ENGINE INSTALLED
SEATS	.0968	TRANSMISSION INSTALLED
STEERING	1.9637	TIRES MOUNTED AND INSTALLED
TRANSMISSION	8.3857	VEHICLE TESTED AND INSPECTED
UNDER BODY	3.4284	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	4.0640	
TOTAL US CONTENT	59.4812	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL G33405
 CHEVROLET EXPRESS / GMC SAVANA
 CARLINE 08
 ASSEMBLY LOC: WENTZVILLE, MISSOURI U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.4736	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	3.9254	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.5132	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	2.9487	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.6160	FRONT AND REAR DOORS INSTALLED
DOORS	4.8827	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	1.9169	EXTERIOR PAINT APPLIED
ENGINE	1.2675	ELECTRICAL WIRING INSTALLED
FRAME	3.7520	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	1.5070	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	5.6948	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	1.2273	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	1.0668	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	6.3931	SEATS INSTALLED
ROOF	1.1225	SUB FRAME AND ENGINE INSTALLED
SEATS	.1388	TRANSMISSION INSTALLED
STEERING	1.9702	TIRES MOUNTED AND INSTALLED
TRANSMISSION	8.3983	VEHICLE TESTED AND INSPECTED
UNDER BODY	3.3143	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	3.9513	
TOTAL US CONTENT	59.0815	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL G33406
 CHEVROLET EXPRESS / GMC SAVANA
 CARLINE 08
 ASSEMBLY LOC: WENTZVILLE, MISSOURI U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.2746	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	3.7191	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	3.8181	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	2.4954	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.5391	FRONT AND REAR DOORS INSTALLED
DOORS	4.5702	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	1.5819	EXTERIOR PAINT APPLIED
ENGINE	1.3614	ELECTRICAL WIRING INSTALLED
FRAME	3.1657	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	1.2718	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	4.9122	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	1.0376	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	.9453	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	5.1537	SEATS INSTALLED
ROOF	2.3597	SUB FRAME AND ENGINE INSTALLED
SEATS	3.9886	TRANSMISSION INSTALLED
STEERING	1.6620	TIRES MOUNTED AND INSTALLED
TRANSMISSION	6.9686	VEHICLE TESTED AND INSPECTED
UNDER BODY	3.0257	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	1.8619	
TOTAL US CONTENT	56.7137	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL G33503
 CHEVROLET EXPRESS / GMC SAVANA
 CARLINE 08
 ASSEMBLY LOC: WENTZVILLE, MISSOURI U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.5480	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	4.0331	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	.8752	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	3.2932	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.8058	FRONT AND REAR DOORS INSTALLED
DOORS	2.2786	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	2.0345	EXTERIOR PAINT APPLIED
ENGINE	1.8728	ELECTRICAL WIRING INSTALLED
FRAME	4.5499	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	1.6834	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	6.3452	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	1.3646	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	1.2281	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	6.8653	SEATS INSTALLED
ROOF	.5926	SUB FRAME AND ENGINE INSTALLED
SEATS	.2525	TRANSMISSION INSTALLED
STEERING	2.2164	TIRES MOUNTED AND INSTALLED
TRANSMISSION	9.4320	VEHICLE TESTED AND INSPECTED
UNDER BODY	1.9097	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	4.0950	
TOTAL US CONTENT	57.2773	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL G33705
 CHEVROLET EXPRESS / GMC SAVANA
 CARLINE 08
 ASSEMBLY LOC: WENTZVILLE, MISSOURI U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.4723	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	3.8976	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.6839	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	2.9104	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.5982	FRONT AND REAR DOORS INSTALLED
DOORS	4.7623	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	1.8378	EXTERIOR PAINT APPLIED
ENGINE	1.2506	ELECTRICAL WIRING INSTALLED
FRAME	3.8197	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	1.4780	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	5.6583	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	1.2098	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	1.0541	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	6.3023	SEATS INSTALLED
ROOF	1.2771	SUB FRAME AND ENGINE INSTALLED
SEATS	.0920	TRANSMISSION INSTALLED
STEERING	1.9328	TIRES MOUNTED AND INSTALLED
TRANSMISSION	8.2414	VEHICLE TESTED AND INSPECTED
UNDER BODY	3.3984	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	4.0217	
TOTAL US CONTENT	58.8998	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL G33706
 CHEVROLET EXPRESS / GMC SAVANA
 CARLINE 08
 ASSEMBLY LOC: WENTZVILLE, MISSOURI U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.2528	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	3.7919	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	4.3264	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	2.4086	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.2749	FRONT AND REAR DOORS INSTALLED
DOORS	4.3371	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	1.5593	EXTERIOR PAINT APPLIED
ENGINE	1.2828	ELECTRICAL WIRING INSTALLED
FRAME	3.1697	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	1.2367	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	4.7050	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	1.0024	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	.9799	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	4.9473	SEATS INSTALLED
ROOF	2.4001	SUB FRAME AND ENGINE INSTALLED
SEATS	3.9495	TRANSMISSION INSTALLED
STEERING	1.6032	TIRES MOUNTED AND INSTALLED
TRANSMISSION	6.8291	VEHICLE TESTED AND INSPECTED
UNDER BODY	3.3082	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	3.1512	
TOTAL US CONTENT	57.5172	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL G33803
 CHEVROLET EXPRESS / GMC SAVANA
 CARLINE 08
 ASSEMBLY LOC: WENTZVILLE, MISSOURI U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.5255	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	3.9186	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	.8334	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	2.7657	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.7622	FRONT AND REAR DOORS INSTALLED
DOORS	1.9517	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	1.9046	EXTERIOR PAINT APPLIED
ENGINE	1.9655	ELECTRICAL WIRING INSTALLED
FRAME	4.9705	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	1.6479	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	7.4804	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	1.3417	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	1.1631	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	7.4069	SEATS INSTALLED
ROOF	.4685	SUB FRAME AND ENGINE INSTALLED
SEATS	.7047	TRANSMISSION INSTALLED
STEERING	2.1352	TIRES MOUNTED AND INSTALLED
TRANSMISSION	9.1378	VEHICLE TESTED AND INSPECTED
UNDER BODY	1.8393	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	4.8904	
TOTAL US CONTENT	58.8146	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL G33903
 CHEVROLET EXPRESS / GMC SAVANA
 CARLINE 08
 ASSEMBLY LOC: SPRINGFIELD, OHIO U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.4541	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	3.8064	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	.8387	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	2.6540	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.7441	FRONT AND REAR DOORS INSTALLED
DOORS	2.3396	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	1.6945	EXTERIOR PAINT APPLIED
ENGINE	1.7696	ELECTRICAL WIRING INSTALLED
FRAME	4.9250	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	1.6187	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	7.9751	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	1.3269	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	1.1818	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	7.5618	SEATS INSTALLED
ROOF	.5676	SUB FRAME AND ENGINE INSTALLED
SEATS	1.1936	TRANSMISSION INSTALLED
STEERING	2.0950	TIRES MOUNTED AND INSTALLED
TRANSMISSION	8.9663	VEHICLE TESTED AND INSPECTED
UNDER BODY	1.8268	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	4.9328	
TOTAL US CONTENT	59.4734	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL K15543
 K2XX LD SILVERADO/SIERRA - CREW CAB
 CARLINE 06
 ASSEMBLY LOC: SILAO, GJ MEXICO

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	.4342	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	1.3627	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	.3866	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.8841	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	2.0924	FRONT AND REAR DOORS INSTALLED
COMM. BODY EQUIP	.0071	BODY PRIMED AND SEALED
DOORS	.9853	EXTERIOR PAINT APPLIED
ELECT SYS & INST PNL	3.2998	ELECTRICAL WIRING INSTALLED
ENGINE	.3947	EXTERIOR MOLDINGS INSTALLED
FRAME	.1840	AIR CONDITIONING AND HEATER INSTALLED
FRT AXLE/SUSPENSION	.5989	INSTRUMENT PANEL INSTALLED
FUEL TANK / EXHAUST	.3510	DOOR HARDWARE AND WINDOWS INSTALLED
HOOD/FRONT END COMP.	.4087	INTERIOR TRIM & FLOOR COVERING INSTALLED
RADIATOR & GRILLE	.6001	SEATS INSTALLED
REAR AXLE/SUSPENSION	.2323	SUB FRAME AND ENGINE INSTALLED
ROOF	.3686	TRANSMISSION INSTALLED
SEATS	.1239	TIRES MOUNTED AND INSTALLED
STEERING	1.1803	VEHICLE TESTED AND INSPECTED
TRANSMISSION	8.2521	FINISHED VEHICLE SHIPPED
UNDER BODY	1.2077	
WHEELS & TIRES	.8556	
TOTAL US CONTENT	25.2111	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL K15703
 K2XX LD SILVERADO/SIERRA - REG CAB
 CARLINE 06
 ASSEMBLY LOC: FORT WAYNE, INDIANA U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.5290	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	2.6378	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.6517	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	2.6359	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	2.3851	FRONT AND REAR DOORS INSTALLED
COMM. BODY EQUIP	.0078	BODY PRIMED AND SEALED
DOORS	3.2058	EXTERIOR PAINT APPLIED
ELECT SYS & INST PNL	3.6168	ELECTRICAL WIRING INSTALLED
ENGINE	11.6339	EXTERIOR MOLDINGS INSTALLED
FRAME	.1888	AIR CONDITIONING AND HEATER INSTALLED
FRT AXLE/SUSPENSION	2.9968	INSTRUMENT PANEL INSTALLED
FUEL TANK / EXHAUST	1.2623	DOOR HARDWARE AND WINDOWS INSTALLED
HOOD/FRONT END COMP.	2.3306	INTERIOR TRIM & FLOOR COVERING INSTALLED
RADIATOR & GRILLE	1.5857	SEATS INSTALLED
REAR AXLE/SUSPENSION	.2972	SUB FRAME AND ENGINE INSTALLED
ROOF	.3417	TRANSMISSION INSTALLED
SEATS	.1430	TIRES MOUNTED AND INSTALLED
STEERING	1.1739	VEHICLE TESTED AND INSPECTED
TRANSMISSION	8.7547	FINISHED VEHICLE SHIPPED
UNDER BODY	1.3652	
WHEELS & TIRES	1.4638	
TOTAL US CONTENT	52.2085	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL K15706
 CHEVROLET TAHOE/GMC YUKON/CADILLAC ESCALADE
 CARLINE 06
 ASSEMBLY LOC: ARLINGTON, TEXAS U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	.7292	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	2.0166	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	1.9700	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.7236	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	2.9174	FRONT AND REAR DOORS INSTALLED
DOORS	4.0305	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	3.0916	EXTERIOR PAINT APPLIED
ENGINE	4.2928	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	.9506	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	.1140	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	1.5281	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.0888	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	.3561	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	.8261	SEATS INSTALLED
SEATS	.3074	SUB FRAME AND ENGINE INSTALLED
STEERING	.2400	TRANSMISSION INSTALLED
TRANSMISSION	7.8960	TIRES MOUNTED AND INSTALLED
UNDER BODY	2.1238	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	2.1254	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	37.3287	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL K15743
 K2XX LD SILVERADO/SIERRA - CREW CAB
 CARLINE 06
 ASSEMBLY LOC: SILAO, GJ MEXICO

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.0322	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	1.8363	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	1.5239	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	2.1293	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	2.1769	FRONT AND REAR DOORS INSTALLED
COMM. BODY EQUIP	.0071	BODY PRIMED AND SEALED
DOORS	2.8876	EXTERIOR PAINT APPLIED
ELECT SYS & INST PNL	3.5966	ELECTRICAL WIRING INSTALLED
ENGINE	7.8104	EXTERIOR MOLDINGS INSTALLED
FRAME	.1783	AIR CONDITIONING AND HEATER INSTALLED
FRT AXLE/SUSPENSION	.8048	INSTRUMENT PANEL INSTALLED
FUEL TANK / EXHAUST	1.0586	DOOR HARDWARE AND WINDOWS INSTALLED
HOOD/FRONT END COMP.	1.2307	INTERIOR TRIM & FLOOR COVERING INSTALLED
RADIATOR & GRILLE	.8331	SEATS INSTALLED
REAR AXLE/SUSPENSION	.2768	SUB FRAME AND ENGINE INSTALLED
ROOF	.6407	TRANSMISSION INSTALLED
SEATS	3.1889	TIRES MOUNTED AND INSTALLED
STEERING	1.1206	VEHICLE TESTED AND INSPECTED
TRANSMISSION	7.9757	FINISHED VEHICLE SHIPPED
UNDER BODY	2.0517	
WHEELS & TIRES	1.9430	
TOTAL US CONTENT	44.3043	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL K15753
 K2XX HD SILVERADO/SIERRA - EXT CAB
 CARLINE 06
 ASSEMBLY LOC: FORT WAYNE, INDIANA U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.6149	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	2.4454	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.8013	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	2.3931	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	2.5065	FRONT AND REAR DOORS INSTALLED
COMM. BODY EQUIP	.0071	BODY PRIMED AND SEALED
DOORS	4.5881	EXTERIOR PAINT APPLIED
ELECT SYS & INST PNL	3.3767	ELECTRICAL WIRING INSTALLED
ENGINE	10.7526	EXTERIOR MOLDINGS INSTALLED
FRAME	.1787	AIR CONDITIONING AND HEATER INSTALLED
FRT AXLE/SUSPENSION	2.7209	INSTRUMENT PANEL INSTALLED
FUEL TANK / EXHAUST	1.9459	DOOR HARDWARE AND WINDOWS INSTALLED
HOOD/FRONT END COMP.	2.1247	INTERIOR TRIM & FLOOR COVERING INSTALLED
RADIATOR & GRILLE	1.4232	SEATS INSTALLED
REAR AXLE/SUSPENSION	.2589	SUB FRAME AND ENGINE INSTALLED
ROOF	.4965	TRANSMISSION INSTALLED
SEATS	.1399	TIRES MOUNTED AND INSTALLED
STEERING	1.1499	VEHICLE TESTED AND INSPECTED
TRANSMISSION	8.2389	FINISHED VEHICLE SHIPPED
UNDER BODY	2.4742	
WHEELS & TIRES	1.3859	
TOTAL US CONTENT	53.0246	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL K15903
 K2XX HD SILVERADO/SIERRA - REG CAB
 CARLINE 06
 ASSEMBLY LOC: FORT WAYNE, INDIANA U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.5902	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	2.5966	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.8608	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	2.7516	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	2.2706	FRONT AND REAR DOORS INSTALLED
COMM. BODY EQUIP	.0081	BODY PRIMED AND SEALED
DOORS	3.1123	EXTERIOR PAINT APPLIED
ELECT SYS & INST PNL	4.0240	ELECTRICAL WIRING INSTALLED
ENGINE	12.9378	EXTERIOR MOLDINGS INSTALLED
FRAME	.1949	AIR CONDITIONING AND HEATER INSTALLED
FRT AXLE/SUSPENSION	3.1323	INSTRUMENT PANEL INSTALLED
FUEL TANK / EXHAUST	1.4037	DOOR HARDWARE AND WINDOWS INSTALLED
HOOD/FRONT END COMP.	2.3992	INTERIOR TRIM & FLOOR COVERING INSTALLED
RADIATOR & GRILLE	1.5966	SEATS INSTALLED
REAR AXLE/SUSPENSION	.3577	SUB FRAME AND ENGINE INSTALLED
ROOF	.3555	TRANSMISSION INSTALLED
SEATS	.1411	TIRES MOUNTED AND INSTALLED
STEERING	1.0913	VEHICLE TESTED AND INSPECTED
TRANSMISSION	7.9364	FINISHED VEHICLE SHIPPED
UNDER BODY	1.4188	
WHEELS & TIRES	2.8717	
TOTAL US CONTENT	55.0521	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL K15906
 CHEV SUBURB/GMC YKN XL/CADILLAC ESC ESV
 CARLINE 06
 ASSEMBLY LOC: ARLINGTON, TEXAS U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	.7362	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	2.4323	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.1705	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.7013	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	2.9326	FRONT AND REAR DOORS INSTALLED
DOORS	4.0134	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	3.0192	EXTERIOR PAINT APPLIED
ENGINE	4.0666	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	.9535	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	.4890	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	1.5188	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.0878	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	.3571	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	.9597	SEATS INSTALLED
SEATS	.3325	SUB FRAME AND ENGINE INSTALLED
STEERING	.2358	TRANSMISSION INSTALLED
TRANSMISSION	7.7131	TIRES MOUNTED AND INSTALLED
UNDER BODY	2.4439	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	2.1996	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	38.3640	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL K25743
 K2XX HD SILVERADO/SIERRA - CREW CAB
 CARLINE 06
 ASSEMBLY LOC: FLINT, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.1061	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	2.4485	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	1.7699	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	2.3197	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.4435	FRONT AND REAR DOORS INSTALLED
COMM. BODY EQUIP	.0047	BODY PRIMED AND SEALED
DOORS	3.3583	EXTERIOR PAINT APPLIED
ELECT SYS & INST PNL	3.1827	ELECTRICAL WIRING INSTALLED
ENGINE	22.4584	EXTERIOR MOLDINGS INSTALLED
FRAME	.0715	AIR CONDITIONING AND HEATER INSTALLED
FRT AXLE/SUSPENSION	3.3001	INSTRUMENT PANEL INSTALLED
FUEL TANK / EXHAUST	6.1786	DOOR HARDWARE AND WINDOWS INSTALLED
HOOD/FRONT END COMP.	1.4081	INTERIOR TRIM & FLOOR COVERING INSTALLED
RADIATOR & GRILLE	1.4214	SEATS INSTALLED
REAR AXLE/SUSPENSION	5.7146	SUB FRAME AND ENGINE INSTALLED
ROOF	.5277	TRANSMISSION INSTALLED
SEATS	4.7789	TIRES MOUNTED AND INSTALLED
STEERING	2.8014	VEHICLE TESTED AND INSPECTED
TRANSMISSION	5.7774	FINISHED VEHICLE SHIPPED
UNDER BODY	2.7689	
WHEELS & TIRES	1.6697	
TOTAL US CONTENT	74.5110	

COST OF FINAL ASSEMBLY: \$3,367.00

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL K25753
 K2XX HD SILVERADO/SIERRA - EXT CAB
 CARLINE 06
 ASSEMBLY LOC: FORT WAYNE, INDIANA U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.0985	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	1.9449	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	1.7758	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	2.2427	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.1190	FRONT AND REAR DOORS INSTALLED
COMM. BODY EQUIP	.0046	BODY PRIMED AND SEALED
DOORS	3.0376	EXTERIOR PAINT APPLIED
ELECT SYS & INST PNL	3.2453	ELECTRICAL WIRING INSTALLED
ENGINE	25.6278	EXTERIOR MOLDINGS INSTALLED
FRAME	.0704	AIR CONDITIONING AND HEATER INSTALLED
FRT AXLE/SUSPENSION	3.3723	INSTRUMENT PANEL INSTALLED
FUEL TANK / EXHAUST	6.6657	DOOR HARDWARE AND WINDOWS INSTALLED
HOOD/FRONT END COMP.	1.5077	INTERIOR TRIM & FLOOR COVERING INSTALLED
RADIATOR & GRILLE	1.4540	SEATS INSTALLED
REAR AXLE/SUSPENSION	5.7992	SUB FRAME AND ENGINE INSTALLED
ROOF	.3232	TRANSMISSION INSTALLED
SEATS	.0898	TIRES MOUNTED AND INSTALLED
STEERING	2.9998	VEHICLE TESTED AND INSPECTED
TRANSMISSION	5.8148	FINISHED VEHICLE SHIPPED
UNDER BODY	2.0567	
WHEELS & TIRES	.6720	
TOTAL US CONTENT	70.9231	

COST OF FINAL ASSEMBLY: \$2,675.00

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL K25953
 K2XX HD SILVERADO/SIERRA - EXT CAB
 CARLINE 06
 ASSEMBLY LOC: FORT WAYNE, INDIANA U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.0795	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	2.6618	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	1.8320	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	2.2076	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.1169	FRONT AND REAR DOORS INSTALLED
COMM. BODY EQUIP	.0045	BODY PRIMED AND SEALED
DOORS	3.1673	EXTERIOR PAINT APPLIED
ELECT SYS & INST PNL	3.1773	ELECTRICAL WIRING INSTALLED
ENGINE	25.1740	EXTERIOR MOLDINGS INSTALLED
FRAME	.0692	AIR CONDITIONING AND HEATER INSTALLED
FRT AXLE/SUSPENSION	3.3125	INSTRUMENT PANEL INSTALLED
FUEL TANK / EXHAUST	6.5553	DOOR HARDWARE AND WINDOWS INSTALLED
HOOD/FRONT END COMP.	1.4810	INTERIOR TRIM & FLOOR COVERING INSTALLED
RADIATOR & GRILLE	1.4282	SEATS INSTALLED
REAR AXLE/SUSPENSION	5.6963	SUB FRAME AND ENGINE INSTALLED
ROOF	.3175	TRANSMISSION INSTALLED
SEATS	.0935	TIRES MOUNTED AND INSTALLED
STEERING	2.9465	VEHICLE TESTED AND INSPECTED
TRANSMISSION	5.7116	FINISHED VEHICLE SHIPPED
UNDER BODY	2.0532	
WHEELS & TIRES	.6601	
TOTAL US CONTENT	70.7468	

COST OF FINAL ASSEMBLY: \$2,688.00

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL K35743
 K2XX HD SILVERADO/SIERRA - CREW CAB
 CARLINE 06
 ASSEMBLY LOC: FLINT, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.0886	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	2.5296	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	1.7277	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	2.2167	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.0217	FRONT AND REAR DOORS INSTALLED
COMM. BODY EQUIP	.0045	BODY PRIMED AND SEALED
DOORS	3.2872	EXTERIOR PAINT APPLIED
ELECT SYS & INST PNL	3.2337	ELECTRICAL WIRING INSTALLED
ENGINE	25.0368	EXTERIOR MOLDINGS INSTALLED
FRAME	.0692	AIR CONDITIONING AND HEATER INSTALLED
FRT AXLE/SUSPENSION	3.1985	INSTRUMENT PANEL INSTALLED
FUEL TANK / EXHAUST	6.5114	DOOR HARDWARE AND WINDOWS INSTALLED
HOOD/FRONT END COMP.	1.4025	INTERIOR TRIM & FLOOR COVERING INSTALLED
RADIATOR & GRILLE	1.4301	SEATS INSTALLED
REAR AXLE/SUSPENSION	5.8011	SUB FRAME AND ENGINE INSTALLED
ROOF	.3901	TRANSMISSION INSTALLED
SEATS	4.2782	TIRES MOUNTED AND INSTALLED
STEERING	2.8312	VEHICLE TESTED AND INSPECTED
TRANSMISSION	5.7159	FINISHED VEHICLE SHIPPED
UNDER BODY	2.5686	
WHEELS & TIRES	.6606	
TOTAL US CONTENT	75.0050	

COST OF FINAL ASSEMBLY: \$3,388.00

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL K35943
 K2XX HD SILVERADO/SIERRA - CREW CAB
 CARLINE 06
 ASSEMBLY LOC: FLINT, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.0026	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	2.5485	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	1.4679	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	2.2618	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.4644	FRONT AND REAR DOORS INSTALLED
COMM. BODY EQUIP	.0043	BODY PRIMED AND SEALED
DOORS	3.2039	EXTERIOR PAINT APPLIED
ELECT SYS & INST PNL	3.1236	ELECTRICAL WIRING INSTALLED
ENGINE	23.5591	EXTERIOR MOLDINGS INSTALLED
FRAME	.0654	AIR CONDITIONING AND HEATER INSTALLED
FRT AXLE/SUSPENSION	3.0138	INSTRUMENT PANEL INSTALLED
FUEL TANK / EXHAUST	6.2028	DOOR HARDWARE AND WINDOWS INSTALLED
HOOD/FRONT END COMP.	1.3079	INTERIOR TRIM & FLOOR COVERING INSTALLED
RADIATOR & GRILLE	1.4068	SEATS INSTALLED
REAR AXLE/SUSPENSION	5.7589	SUB FRAME AND ENGINE INSTALLED
ROOF	.5055	TRANSMISSION INSTALLED
SEATS	4.9233	TIRES MOUNTED AND INSTALLED
STEERING	2.7306	VEHICLE TESTED AND INSPECTED
TRANSMISSION	5.4023	FINISHED VEHICLE SHIPPED
UNDER BODY	2.9897	
WHEELS & TIRES	1.8006	
TOTAL US CONTENT	74.7448	

COST OF FINAL ASSEMBLY: \$3,426.00

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1BG69
 CHEVROLET CRUZE D2
 CARLINE B
 ASSEMBLY LOC: RAMOS ARIZPE, CZ MEXICO

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	.1417	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	.1487	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.2534	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	.2140	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.3525	FRONT AND REAR DOORS INSTALLED
DOORS	.6082	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	2.0621	EXTERIOR PAINT APPLIED
ENGINE	6.2953	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	1.2157	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	1.4023	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	.3815	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.0548	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	.1308	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	.0646	SEATS INSTALLED
SEATS	.1648	SUB FRAME AND ENGINE INSTALLED
STEERING	2.5861	TRANSMISSION INSTALLED
TRANSMISSION	4.3484	TIRES MOUNTED AND INSTALLED
UNDER BODY	.4050	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	.1590	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	22.9901	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1BH68
 CHEVROLET CRUZE D2
 CARLINE B
 ASSEMBLY LOC: RAMOS ARIZPE, CZ MEXICO

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	.1234	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	.2674	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	.8528	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	.2018	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.2475	FRONT AND REAR DOORS INSTALLED
DOORS	1.2337	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	1.5335	EXTERIOR PAINT APPLIED
ENGINE	1.4668	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	.6754	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	1.2988	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	.3978	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.0484	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	.1273	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	.0437	SEATS INSTALLED
SEATS	.1984	SUB FRAME AND ENGINE INSTALLED
STEERING	2.4153	TRANSMISSION INSTALLED
TRANSMISSION	10.2983	TIRES MOUNTED AND INSTALLED
UNDER BODY	.2257	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	.1471	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	21.8040	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1BH69
 CHEVROLET CRUZE D2
 CARLINE B
 ASSEMBLY LOC: RAMOS ARIZPE, CZ MEXICO

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	.1150	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	.1462	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.0148	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	.1929	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.2906	FRONT AND REAR DOORS INSTALLED
DOORS	.7587	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	2.6899	EXTERIOR PAINT APPLIED
ENGINE	14.0188	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	.5786	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	1.2638	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	.4277	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.0494	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	.1185	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	.0579	SEATS INSTALLED
SEATS	.1841	SUB FRAME AND ENGINE INSTALLED
STEERING	2.3306	TRANSMISSION INSTALLED
TRANSMISSION	11.3549	TIRES MOUNTED AND INSTALLED
UNDER BODY	.3311	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	2.3040	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	39.2285	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1BJ68
 CHEVROLET CRUZE D2
 CARLINE B
 ASSEMBLY LOC: RAMOS ARIZPE, CZ MEXICO

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	.2055	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	.2273	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	.7100	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	.1722	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.0686	FRONT AND REAR DOORS INSTALLED
DOORS	1.1673	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	2.1019	EXTERIOR PAINT APPLIED
ENGINE	1.3757	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	.4339	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	1.1228	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	.5668	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.0418	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	.1100	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	.0838	SEATS INSTALLED
SEATS	.1777	SUB FRAME AND ENGINE INSTALLED
STEERING	2.0881	TRANSMISSION INSTALLED
TRANSMISSION	9.8398	TIRES MOUNTED AND INSTALLED
UNDER BODY	.1780	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	.1271	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	20.7994	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1BJ69
 CHEVROLET CRUZE D2
 CARLINE B
 ASSEMBLY LOC: RAMOS ARIZPE, CZ MEXICO

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	.1129	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	.2249	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	1.7796	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	.1691	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.2798	FRONT AND REAR DOORS INSTALLED
DOORS	.7878	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	2.9727	EXTERIOR PAINT APPLIED
ENGINE	11.3108	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	.5070	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	1.1080	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	.2925	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.0433	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	.1073	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	.1155	SEATS INSTALLED
SEATS	.1676	SUB FRAME AND ENGINE INSTALLED
STEERING	2.0434	TRANSMISSION INSTALLED
TRANSMISSION	9.9267	TIRES MOUNTED AND INSTALLED
UNDER BODY	.3270	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	2.3773	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	34.6542	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1BR69
 CHEVROLET CRUZE D2
 CARLINE B
 ASSEMBLY LOC: LORDSTOWN, OHIO U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	.6681	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	.7789	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.4155	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	.7879	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.4923	FRONT AND REAR DOORS INSTALLED
DOORS	2.2414	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	2.3147	EXTERIOR PAINT APPLIED
ENGINE	15.2880	ELECTRICAL WIRING INSTALLED
FRAME	.0189	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	.6649	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	1.6854	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	1.0228	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	.0570	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	.1601	SEATS INSTALLED
ROOF	.6319	SUB FRAME AND ENGINE INSTALLED
SEATS	1.3022	TRANSMISSION INSTALLED
STEERING	2.3080	TIRES MOUNTED AND INSTALLED
TRANSMISSION	10.5969	VEHICLE TESTED AND INSPECTED
UNDER BODY	2.0727	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	.5820	
TOTAL US CONTENT	47.0907	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1BS68
 CHEVROLET CRUZE D2
 CARLINE B
 ASSEMBLY LOC: RAMOS ARIZPE, CZ MEXICO

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	.0985	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	.1974	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	.6796	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	.5881	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.4551	FRONT AND REAR DOORS INSTALLED
DOORS	.8624	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	3.8809	EXTERIOR PAINT APPLIED
ENGINE	11.6556	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	.4752	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	1.1733	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	.3089	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.0453	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	.1245	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	.1066	SEATS INSTALLED
SEATS	.1822	SUB FRAME AND ENGINE INSTALLED
STEERING	1.9160	TRANSMISSION INSTALLED
TRANSMISSION	9.5742	TIRES MOUNTED AND INSTALLED
UNDER BODY	.1894	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	2.3347	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	34.8488	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1BS69
 CHEVROLET CRUZE D2
 CARLINE B
 ASSEMBLY LOC: LORDSTOWN, OHIO U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	.5666	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	.7691	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.1266	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	.6882	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.4584	FRONT AND REAR DOORS INSTALLED
DOORS	2.5181	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	3.4826	EXTERIOR PAINT APPLIED
ENGINE	13.5853	ELECTRICAL WIRING INSTALLED
FRAME	.0165	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	.5449	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	2.5792	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	.8852	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	.0514	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	.1548	SEATS INSTALLED
ROOF	.5857	SUB FRAME AND ENGINE INSTALLED
SEATS	1.4930	TRANSMISSION INSTALLED
STEERING	2.0446	TIRES MOUNTED AND INSTALLED
TRANSMISSION	9.6991	VEHICLE TESTED AND INSPECTED
UNDER BODY	2.0389	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	2.1924	
TOTAL US CONTENT	47.4817	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1BT68
 CHEVROLET CRUZE D2
 CARLINE B
 ASSEMBLY LOC: RAMOS ARIZPE, CZ MEXICO

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	.1095	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	.1323	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	.7588	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	.6561	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.4931	FRONT AND REAR DOORS INSTALLED
DOORS	.9082	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	3.0611	EXTERIOR PAINT APPLIED
ENGINE	12.5675	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	.5529	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	1.3092	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	.3475	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.0477	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	.1335	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	.0971	SEATS INSTALLED
SEATS	.1972	SUB FRAME AND ENGINE INSTALLED
STEERING	2.1380	TRANSMISSION INSTALLED
TRANSMISSION	10.2909	TIRES MOUNTED AND INSTALLED
UNDER BODY	.2216	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	1.7221	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	35.7454	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1BT69
 CHEVROLET CRUZE D2
 CARLINE B
 ASSEMBLY LOC: LORDSTOWN, OHIO U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	.6317	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	.7426	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.2988	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	.7458	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.4321	FRONT AND REAR DOORS INSTALLED
DOORS	2.3495	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	3.3251	EXTERIOR PAINT APPLIED
ENGINE	14.6632	ELECTRICAL WIRING INSTALLED
FRAME	.0180	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	.6142	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	2.8043	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	.9794	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	.0549	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	.1574	SEATS INSTALLED
ROOF	.6108	SUB FRAME AND ENGINE INSTALLED
SEATS	1.4594	TRANSMISSION INSTALLED
STEERING	2.2232	TIRES MOUNTED AND INSTALLED
TRANSMISSION	10.3478	VEHICLE TESTED AND INSPECTED
UNDER BODY	1.9933	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	1.4358	
TOTAL US CONTENT	48.8882	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1JB76
 CHEVROLET TRAX
 CARLINE J
 ASSEMBLY LOC: SAN LUIS POTOSI, MEXICO

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	.0264	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	.2868	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	.0297	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	.4291	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.3827	FRONT AND REAR DOORS INSTALLED
DOORS	1.1887	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	.7119	EXTERIOR PAINT APPLIED
ENGINE	.0874	ELECTRICAL WIRING INSTALLED
FRAME	.0016	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	.7727	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	.5418	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	.0692	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	.0028	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	.4587	SEATS INSTALLED
ROOF	.0623	SUB FRAME AND ENGINE INSTALLED
SEATS	.0195	TRANSMISSION INSTALLED
STEERING	.2032	TIRES MOUNTED AND INSTALLED
TRANSMISSION	.0147	VEHICLE TESTED AND INSPECTED
UNDER BODY	.1001	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	.0562	
TOTAL US CONTENT	5.4465	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1JC76
 CHEVROLET TRAX
 CARLINE J
 ASSEMBLY LOC: SAN LUIS POTOSI, MEXICO

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	.0237	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	.2728	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	.0267	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	.5333	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.3284	FRONT AND REAR DOORS INSTALLED
DOORS	1.0788	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	.9614	EXTERIOR PAINT APPLIED
ENGINE	.0430	ELECTRICAL WIRING INSTALLED
FRAME	.0005	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	.6920	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	.2128	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	.0700	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	.0039	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	.4200	SEATS INSTALLED
ROOF	.0512	SUB FRAME AND ENGINE INSTALLED
SEATS	.0175	TRANSMISSION INSTALLED
STEERING	.2399	TIRES MOUNTED AND INSTALLED
TRANSMISSION	.0172	VEHICLE TESTED AND INSPECTED
UNDER BODY	.0686	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	.0505	
TOTAL US CONTENT	5.1134	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1JD48
 CHEVROLET SONIC
 CARLINE J
 ASSEMBLY LOC: RAMOS ARIZPE, CZ MEXICO

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	.1058	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	1.3080	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	.7435	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	.0807	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.0995	FRONT AND REAR DOORS INSTALLED
DOORS	1.9255	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	5.2606	EXTERIOR PAINT APPLIED
ENGINE	.3000	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	.3318	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	.1353	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	.3699	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.0991	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	1.0467	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	.5760	SEATS INSTALLED
SEATS	.0236	SUB FRAME AND ENGINE INSTALLED
STEERING	.3434	TRANSMISSION INSTALLED
TRANSMISSION	8.8358	TIRES MOUNTED AND INSTALLED
UNDER BODY	.1122	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	.0429	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	21.7413	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1JD69
 CHEVROLET SONIC
 CARLINE J
 ASSEMBLY LOC: RAMOS ARIZPE, CZ MEXICO

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	.1048	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	1.3062	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	.8193	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	.0807	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.1041	FRONT AND REAR DOORS INSTALLED
DOORS	.5673	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	5.1249	EXTERIOR PAINT APPLIED
ENGINE	.2994	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	.3314	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	.1315	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	.3759	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.0990	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	1.0454	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	.5816	SEATS INSTALLED
SEATS	.0236	SUB FRAME AND ENGINE INSTALLED
STEERING	.3430	TRANSMISSION INSTALLED
TRANSMISSION	10.0538	TIRES MOUNTED AND INSTALLED
UNDER BODY	.1091	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	.0429	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	21.5449	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1JR69
 CHEVROLET SONIC
 CARLINE J
 ASSEMBLY LOC: RAMOS ARIZPE, CZ MEXICO

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	.1246	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	.9568	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	.9762	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	.0948	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.1297	FRONT AND REAR DOORS INSTALLED
DOORS	.6911	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	4.5372	EXTERIOR PAINT APPLIED
ENGINE	.3603	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	.3962	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	.1599	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	.4448	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.1633	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	1.2499	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	.4843	SEATS INSTALLED
SEATS	.0259	SUB FRAME AND ENGINE INSTALLED
STEERING	.0089	TRANSMISSION INSTALLED
TRANSMISSION	.0187	TIRES MOUNTED AND INSTALLED
UNDER BODY	.1217	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	.0346	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	10.9799	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1JS48
 CHEVROLET SONIC
 CARLINE J
 ASSEMBLY LOC: RAMOS ARIZPE, CZ MEXICO

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	.1163	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	.8791	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	.8081	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	.0878	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.1011	FRONT AND REAR DOORS INSTALLED
DOORS	2.1012	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	3.2641	EXTERIOR PAINT APPLIED
ENGINE	.3263	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	.3610	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	.1472	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	.4045	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.1488	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	1.1386	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	.6020	SEATS INSTALLED
SEATS	.0257	SUB FRAME AND ENGINE INSTALLED
STEERING	.0081	TRANSMISSION INSTALLED
TRANSMISSION	9.7226	TIRES MOUNTED AND INSTALLED
UNDER BODY	.1133	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	.0467	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	20.4035	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1JS69
 CHEVROLET SONIC
 CARLINE J
 ASSEMBLY LOC: RAMOS ARIZPE, CZ MEXICO

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	.1177	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	.9082	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	.9254	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	.0904	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.1124	FRONT AND REAR DOORS INSTALLED
DOORS	.6853	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	2.7285	EXTERIOR PAINT APPLIED
ENGINE	.3395	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	.3745	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	.1506	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	.4384	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.1544	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	1.1813	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	.4755	SEATS INSTALLED
SEATS	.0267	SUB FRAME AND ENGINE INSTALLED
STEERING	.0084	TRANSMISSION INSTALLED
TRANSMISSION	5.3701	TIRES MOUNTED AND INSTALLED
UNDER BODY	.1150	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	.0484	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	14.2517	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1JT69
 CHEVROLET SONIC
 CARLINE J
 ASSEMBLY LOC: RAMOS ARIZPE, CZ MEXICO

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	.1016	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	1.1535	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	.7963	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	.0795	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.1086	FRONT AND REAR DOORS INSTALLED
DOORS	.6290	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	3.0806	EXTERIOR PAINT APPLIED
ENGINE	.2911	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	.3232	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	.1304	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	.3622	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.1332	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	1.0195	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	.5666	SEATS INSTALLED
SEATS	.0230	SUB FRAME AND ENGINE INSTALLED
STEERING	.0072	TRANSMISSION INSTALLED
TRANSMISSION	14.0529	TIRES MOUNTED AND INSTALLED
UNDER BODY	.0999	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	.0418	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	23.0010	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1JU69
 CHEVROLET SONIC
 CARLINE J

ASSEMBLY LOC: LAKE ORION, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	2.1751	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	3.1672	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.9668	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.4245	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	2.9824	FRONT AND REAR DOORS INSTALLED
DOORS	2.9838	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	4.4823	EXTERIOR PAINT APPLIED
ENGINE	.2782	ELECTRICAL WIRING INSTALLED
FRAME	.0042	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	.3182	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	.2736	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	1.2177	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	.1120	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	.9349	SEATS INSTALLED
ROOF	.6768	SUB FRAME AND ENGINE INSTALLED
SEATS	7.5052	TRANSMISSION INSTALLED
STEERING	2.1178	TIRES MOUNTED AND INSTALLED
TRANSMISSION	10.5266	VEHICLE TESTED AND INSPECTED
UNDER BODY	2.0988	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	.2267	
TOTAL US CONTENT	46.4738	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1JU76
 CHEVROLET TRAX
 CARLINE J
 ASSEMBLY LOC: SAN LUIS POTOSI, MEXICO

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	.0384	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	.4994	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	.0290	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	.9718	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.2620	FRONT AND REAR DOORS INSTALLED
DOORS	1.1896	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	.5828	EXTERIOR PAINT APPLIED
ENGINE	.2290	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	.4664	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	.0852	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	.0548	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.0027	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	.2340	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	.0890	SEATS INSTALLED
SEATS	.0167	SUB FRAME AND ENGINE INSTALLED
STEERING	.0950	TRANSMISSION INSTALLED
TRANSMISSION	.0190	TIRES MOUNTED AND INSTALLED
UNDER BODY	.0999	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	.0412	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	5.0070	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1JV48
 CHEVROLET SONIC
 CARLINE J

ASSEMBLY LOC: LAKE ORION, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.9879	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	3.0865	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.6584	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.3166	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.7995	FRONT AND REAR DOORS INSTALLED
DOORS	4.1248	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	4.4612	EXTERIOR PAINT APPLIED
ENGINE	.3885	ELECTRICAL WIRING INSTALLED
FRAME	.0035	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	.4095	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	.2013	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	1.1548	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	.1234	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	.8519	SEATS INSTALLED
ROOF	.8441	SUB FRAME AND ENGINE INSTALLED
SEATS	7.6897	TRANSMISSION INSTALLED
STEERING	1.9596	TIRES MOUNTED AND INSTALLED
TRANSMISSION	9.8192	VEHICLE TESTED AND INSPECTED
UNDER BODY	1.9681	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	.0403	
TOTAL US CONTENT	43.8901	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1JV69
 CHEVROLET SONIC
 CARLINE J

ASSEMBLY LOC: LAKE ORION, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	2.1076	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	3.0921	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.8675	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.3761	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	2.7614	FRONT AND REAR DOORS INSTALLED
DOORS	3.2334	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	4.6318	EXTERIOR PAINT APPLIED
ENGINE	.2725	ELECTRICAL WIRING INSTALLED
FRAME	.0040	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	.3281	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	.2586	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	1.1644	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	.1111	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	.9029	SEATS INSTALLED
ROOF	.6541	SUB FRAME AND ENGINE INSTALLED
SEATS	7.5531	TRANSMISSION INSTALLED
STEERING	2.0580	TIRES MOUNTED AND INSTALLED
TRANSMISSION	10.6538	VEHICLE TESTED AND INSPECTED
UNDER BODY	2.2147	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	.0428	
TOTAL US CONTENT	46.2891	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1JV76
 CHEVROLET TRAX
 CARLINE J
 ASSEMBLY LOC: SAN LUIS POTOSI, MEXICO

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	.0347	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	.5288	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	.0218	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.0327	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.2259	FRONT AND REAR DOORS INSTALLED
DOORS	1.0760	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	.6656	EXTERIOR PAINT APPLIED
ENGINE	.2337	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	.3610	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	.0816	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	.0525	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.0037	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	.1652	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	.0929	SEATS INSTALLED
SEATS	.0148	SUB FRAME AND ENGINE INSTALLED
STEERING	.0563	TRANSMISSION INSTALLED
TRANSMISSION	.0187	TIRES MOUNTED AND INSTALLED
UNDER BODY	.0722	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	.0498	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	4.7888	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1JW48
 CHEVROLET SONIC
 CARLINE J

ASSEMBLY LOC: LAKE ORION, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.9095	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	2.9646	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.5430	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.2938	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.4312	FRONT AND REAR DOORS INSTALLED
DOORS	3.9522	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	5.1793	EXTERIOR PAINT APPLIED
ENGINE	.4538	ELECTRICAL WIRING INSTALLED
FRAME	.0029	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	.5724	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	.1147	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	1.0908	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	.1391	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	.8027	SEATS INSTALLED
ROOF	.9286	SUB FRAME AND ENGINE INSTALLED
SEATS	9.1166	TRANSMISSION INSTALLED
STEERING	1.8967	TIRES MOUNTED AND INSTALLED
TRANSMISSION	8.3775	VEHICLE TESTED AND INSPECTED
UNDER BODY	1.9394	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	.0386	
TOTAL US CONTENT	43.7484	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1JW69
 CHEVROLET SONIC
 CARLINE J

ASSEMBLY LOC: LAKE ORION, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.9834	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	3.0889	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.7018	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.3456	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	2.7793	FRONT AND REAR DOORS INSTALLED
DOORS	2.9711	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	4.4848	EXTERIOR PAINT APPLIED
ENGINE	.4650	ELECTRICAL WIRING INSTALLED
FRAME	.0031	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	.5987	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	.1108	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	1.0987	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	.1483	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	.8513	SEATS INSTALLED
ROOF	.6204	SUB FRAME AND ENGINE INSTALLED
SEATS	8.9547	TRANSMISSION INSTALLED
STEERING	1.9790	TIRES MOUNTED AND INSTALLED
TRANSMISSION	10.0370	VEHICLE TESTED AND INSPECTED
UNDER BODY	2.0776	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	.0403	
TOTAL US CONTENT	46.3409	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1JW76
 CHEVROLET TRAX
 CARLINE J
 ASSEMBLY LOC: SAN LUIS POTOSI, MEXICO

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	.0280	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	.2578	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	.0272	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	.7238	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.3444	FRONT AND REAR DOORS INSTALLED
DOORS	1.1103	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	.9168	EXTERIOR PAINT APPLIED
ENGINE	.0994	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	.6656	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	.0865	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	.0523	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.0026	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	.4014	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	.0625	SEATS INSTALLED
SEATS	.0119	SUB FRAME AND ENGINE INSTALLED
STEERING	.2058	TRANSMISSION INSTALLED
TRANSMISSION	.0159	TIRES MOUNTED AND INSTALLED
UNDER BODY	.0984	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	.0520	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	5.1635	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1RF68
 CHEVROLET VOLT
 CARLINE R
 ASSEMBLY LOC: HAMTRAMCK, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	.6010	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	1.5697	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	1.6530	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	.9849	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.1807	FRONT AND REAR DOORS INSTALLED
DOORS	3.4608	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	26.0603	EXTERIOR PAINT APPLIED
ENGINE	7.2111	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	.6510	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	1.3753	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	.8796	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.8968	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	.0629	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	.6641	SEATS INSTALLED
SEATS	2.2867	SUB FRAME AND ENGINE INSTALLED
STEERING	.0053	TRANSMISSION INSTALLED
TRANSMISSION	15.3099	TIRES MOUNTED AND INSTALLED
UNDER BODY	2.5034	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	1.2951	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	67.6527	

COST OF FINAL ASSEMBLY: \$4,041.00

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1RG68
 CHEVROLET VOLT
 CARLINE R

ASSEMBLY LOC: HAMTRAMCK, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	.5732	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	1.7162	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	1.6034	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	.9440	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.4337	FRONT AND REAR DOORS INSTALLED
DOORS	3.3649	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	25.5556	EXTERIOR PAINT APPLIED
ENGINE	6.8987	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	.6226	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	1.3060	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	.8397	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.8577	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	.0601	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	.6363	SEATS INSTALLED
SEATS	2.3026	SUB FRAME AND ENGINE INSTALLED
STEERING	.0051	TRANSMISSION INSTALLED
TRANSMISSION	14.6436	TIRES MOUNTED AND INSTALLED
UNDER BODY	2.6828	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	1.2388	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	67.2860	

COST OF FINAL ASSEMBLY: \$4,090.00

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1YY07
 CHEVROLET CORVETTE
 CARLINE Y

ASSEMBLY LOC: BOWLING GREEN, KENTUCKY U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	3.1771	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	3.6607	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	3.5344	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	.2402	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.1098	FRONT AND REAR DOORS INSTALLED
DOORS	3.9516	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	6.1864	EXTERIOR PAINT APPLIED
ENGINE	11.7233	ELECTRICAL WIRING INSTALLED
FRAME	.0106	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	.7401	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	4.7777	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	5.1142	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	.5812	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	2.0244	SEATS INSTALLED
ROOF	2.7051	SUB FRAME AND ENGINE INSTALLED
SEATS	5.1254	TRANSMISSION INSTALLED
STEERING	1.0013	TIRES MOUNTED AND INSTALLED
TRANSMISSION	4.0364	VEHICLE TESTED AND INSPECTED
UNDER BODY	6.2192	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	2.7509	
TOTAL US CONTENT	68.6711	

COST OF FINAL ASSEMBLY: \$5,213.00

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1YY67
 CHEVROLET CORVETTE
 CARLINE Y

ASSEMBLY LOC: BOWLING GREEN, KENTUCKY U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	3.0112	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	3.5376	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	4.0575	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	.2287	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.0777	FRONT AND REAR DOORS INSTALLED
DOORS	3.6872	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	6.3976	EXTERIOR PAINT APPLIED
ENGINE	11.3129	ELECTRICAL WIRING INSTALLED
FRAME	.0099	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	.7138	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	4.5351	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	4.8391	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	.5819	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	1.9453	SEATS INSTALLED
ROOF	5.8189	SUB FRAME AND ENGINE INSTALLED
SEATS	5.0868	TRANSMISSION INSTALLED
STEERING	.9419	TIRES MOUNTED AND INSTALLED
TRANSMISSION	4.2941	VEHICLE TESTED AND INSPECTED
UNDER BODY	5.9159	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	2.6540	
TOTAL US CONTENT	70.6484	

COST OF FINAL ASSEMBLY: \$5,269.00

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1YZ07
 CHEVROLET CORVETTE
 CARLINE Y

ASSEMBLY LOC: BOWLING GREEN, KENTUCKY U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	2.5391	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	2.9648	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.6613	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	.2870	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.6924	FRONT AND REAR DOORS INSTALLED
DOORS	3.4441	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	5.3489	EXTERIOR PAINT APPLIED
ENGINE	18.9403	ELECTRICAL WIRING INSTALLED
FRAME	.0083	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	.5807	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	3.5392	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	4.9296	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	.4887	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	1.9235	SEATS INSTALLED
ROOF	2.6149	SUB FRAME AND ENGINE INSTALLED
SEATS	4.2716	TRANSMISSION INSTALLED
STEERING	.7857	TIRES MOUNTED AND INSTALLED
TRANSMISSION	2.9139	VEHICLE TESTED AND INSPECTED
UNDER BODY	5.6228	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	3.0116	
TOTAL US CONTENT	68.5693	

COST OF FINAL ASSEMBLY: \$5,440.00

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1YZ67
 CHEVROLET CORVETTE
 CARLINE Y

ASSEMBLY LOC: BOWLING GREEN, KENTUCKY U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	2.4333	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	2.9678	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	3.4063	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	.2701	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.7995	FRONT AND REAR DOORS INSTALLED
DOORS	3.3034	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	5.4241	EXTERIOR PAINT APPLIED
ENGINE	17.8110	ELECTRICAL WIRING INSTALLED
FRAME	.0078	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	.5730	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	3.3553	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	4.6304	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	.4829	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	1.8048	SEATS INSTALLED
ROOF	4.5879	SUB FRAME AND ENGINE INSTALLED
SEATS	4.2681	TRANSMISSION INSTALLED
STEERING	.7442	TIRES MOUNTED AND INSTALLED
TRANSMISSION	3.5069	VEHICLE TESTED AND INSPECTED
UNDER BODY	5.4445	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	2.9090	
TOTAL US CONTENT	69.7314	

COST OF FINAL ASSEMBLY: \$5,498.00

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1ZB69
 CHEVROLET MALIBU E2
 CARLINE Z
 ASSEMBLY LOC: FAIRFAX, KANSAS U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	2.5432	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	2.9954	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	3.4192	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.2463	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	2.7483	FRONT AND REAR DOORS INSTALLED
DOORS	3.7530	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	2.8616	EXTERIOR PAINT APPLIED
ENGINE	.9569	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	1.7255	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	4.2870	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	1.8379	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.0752	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	1.6892	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	1.0751	SEATS INSTALLED
SEATS	1.9605	SUB FRAME AND ENGINE INSTALLED
STEERING	.0709	TRANSMISSION INSTALLED
TRANSMISSION	6.8282	TIRES MOUNTED AND INSTALLED
UNDER BODY	5.4619	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	2.6565	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	48.1929	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1ZC69
 CHEVROLET MALIBU E2
 CARLINE Z
 ASSEMBLY LOC: FAIRFAX, KANSAS U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	2.5135	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	2.9084	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	3.3398	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.2131	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	2.8744	FRONT AND REAR DOORS INSTALLED
DOORS	4.0696	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	2.7859	EXTERIOR PAINT APPLIED
ENGINE	.9265	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	1.6802	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	4.2577	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	1.7883	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.0972	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	1.6449	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	1.0520	SEATS INSTALLED
SEATS	1.9604	SUB FRAME AND ENGINE INSTALLED
STEERING	.0690	TRANSMISSION INSTALLED
TRANSMISSION	6.6421	TIRES MOUNTED AND INSTALLED
UNDER BODY	5.4617	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	1.9538	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	47.2395	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1ZD69
 CHEVROLET MALIBU E2
 CARLINE Z
 ASSEMBLY LOC: FAIRFAX, KANSAS U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	2.3732	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	2.8692	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	3.1371	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.1419	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	3.0135	FRONT AND REAR DOORS INSTALLED
DOORS	4.3050	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	3.3468	EXTERIOR PAINT APPLIED
ENGINE	1.1154	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	1.5815	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	3.9173	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	1.6851	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.0693	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	1.5477	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	1.0135	SEATS INSTALLED
SEATS	2.7936	SUB FRAME AND ENGINE INSTALLED
STEERING	.1173	TRANSMISSION INSTALLED
TRANSMISSION	6.1836	TIRES MOUNTED AND INSTALLED
UNDER BODY	6.0754	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	1.1758	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	47.4634	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1ZE69
 CHEVROLET MALIBU E2
 CARLINE Z
 ASSEMBLY LOC: FAIRFAX, KANSAS U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.5287	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	2.0922	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.1108	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	.5113	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	2.0007	FRONT AND REAR DOORS INSTALLED
DOORS	2.7282	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	12.6060	EXTERIOR PAINT APPLIED
ENGINE	.0903	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	1.0369	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	2.6091	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	1.0719	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.0656	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	.9980	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	.6705	SEATS INSTALLED
SEATS	1.0569	SUB FRAME AND ENGINE INSTALLED
STEERING	.2047	TRANSMISSION INSTALLED
TRANSMISSION	19.8640	TIRES MOUNTED AND INSTALLED
UNDER BODY	4.1637	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	1.3201	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	56.7303	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1ZF69
 CHEVROLET MALIBU E2
 CARLINE Z
 ASSEMBLY LOC: FAIRFAX, KANSAS U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.8632	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	2.3087	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.4612	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	.6458	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	2.1109	FRONT AND REAR DOORS INSTALLED
DOORS	3.4454	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	2.8179	EXTERIOR PAINT APPLIED
ENGINE	15.0846	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	1.2745	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	2.5183	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	1.3197	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.0591	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	1.2132	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	.8832	SEATS INSTALLED
SEATS	.0197	SUB FRAME AND ENGINE INSTALLED
STEERING	.0744	TRANSMISSION INSTALLED
TRANSMISSION	.1588	TIRES MOUNTED AND INSTALLED
UNDER BODY	5.0078	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	.9384	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	44.2058	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 12N43
 CHEVROLET COLORADO
 CARLINE 52

ASSEMBLY LOC: WENTZVILLE, MISSOURI U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.4840	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	1.6539	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.5757	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	.9824	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	2.0931	FRONT AND REAR DOORS INSTALLED
COMM. BODY EQUIP	.0068	BODY PRIMED AND SEALED
DOORS	3.1339	EXTERIOR PAINT APPLIED
ELECT SYS & INST PNL	3.4820	ELECTRICAL WIRING INSTALLED
ENGINE	16.5299	EXTERIOR MOLDINGS INSTALLED
FRAME	2.4842	AIR CONDITIONING AND HEATER INSTALLED
FRT AXLE/SUSPENSION	1.3496	INSTRUMENT PANEL INSTALLED
FUEL TANK / EXHAUST	3.1620	DOOR HARDWARE AND WINDOWS INSTALLED
HOOD/FRONT END COMP.	1.4312	INTERIOR TRIM & FLOOR COVERING INSTALLED
RADIATOR & GRILLE	1.4442	SEATS INSTALLED
REAR AXLE/SUSPENSION	.6434	SUB FRAME AND ENGINE INSTALLED
ROOF	.4784	TRANSMISSION INSTALLED
SEATS	.0442	TIRES MOUNTED AND INSTALLED
STEERING	.5767	VEHICLE TESTED AND INSPECTED
TRANSMISSION	8.8721	FINISHED VEHICLE SHIPPED
UNDER BODY	2.7587	
WHEELS & TIRES	3.4666	
TOTAL US CONTENT	58.6540	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 12P43
 CHEVROLET COLORADO
 CARLINE 52

ASSEMBLY LOC: WENTZVILLE, MISSOURI U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.4478	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	1.8233	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.5033	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	.9486	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	2.0158	FRONT AND REAR DOORS INSTALLED
COMM. BODY EQUIP	.0066	BODY PRIMED AND SEALED
DOORS	3.2026	EXTERIOR PAINT APPLIED
ELECT SYS & INST PNL	2.6813	ELECTRICAL WIRING INSTALLED
ENGINE	10.4814	EXTERIOR MOLDINGS INSTALLED
FRAME	2.4465	AIR CONDITIONING AND HEATER INSTALLED
FRT AXLE/SUSPENSION	1.2279	INSTRUMENT PANEL INSTALLED
FUEL TANK / EXHAUST	5.0549	DOOR HARDWARE AND WINDOWS INSTALLED
HOOD/FRONT END COMP.	1.4291	INTERIOR TRIM & FLOOR COVERING INSTALLED
RADIATOR & GRILLE	1.3668	SEATS INSTALLED
REAR AXLE/SUSPENSION	.5969	SUB FRAME AND ENGINE INSTALLED
ROOF	.4633	TRANSMISSION INSTALLED
SEATS	3.5154	TIRES MOUNTED AND INSTALLED
STEERING	.5586	VEHICLE TESTED AND INSPECTED
TRANSMISSION	5.3179	FINISHED VEHICLE SHIPPED
UNDER BODY	3.7517	
WHEELS & TIRES	2.1728	
TOTAL US CONTENT	53.0136	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 4GP69
 BUICK REGAL
 CARLINE 0G
 ASSEMBLY LOC: OSHAWA, ONTARIO CANADA

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.4975	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	1.3178	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	1.1358	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	2.1264	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.3883	FRONT AND REAR DOORS INSTALLED
DOORS	.3821	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	1.7985	EXTERIOR PAINT APPLIED
ENGINE	18.7472	ELECTRICAL WIRING INSTALLED
FRAME	.0127	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	2.0323	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	.2658	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	1.3470	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	1.3505	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	.7644	SEATS INSTALLED
ROOF	.3826	SUB FRAME AND ENGINE INSTALLED
SEATS	.0542	TRANSMISSION INSTALLED
STEERING	1.9027	TIRES MOUNTED AND INSTALLED
TRANSMISSION	7.1801	VEHICLE TESTED AND INSPECTED
UNDER BODY	2.5465	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	1.7670	
TOTAL US CONTENT	47.0003	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 4GR69
 BUICK REGAL
 CARLINE 0G
 ASSEMBLY LOC: OSHAWA, ONTARIO CANADA

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.5137	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	1.2530	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	1.0689	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.8396	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.3592	FRONT AND REAR DOORS INSTALLED
DOORS	.3333	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	1.6996	EXTERIOR PAINT APPLIED
ENGINE	17.8346	ELECTRICAL WIRING INSTALLED
FRAME	.0250	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	1.7814	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	.2321	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	1.2771	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	1.2772	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	.8129	SEATS INSTALLED
ROOF	.4219	SUB FRAME AND ENGINE INSTALLED
SEATS	.0512	TRANSMISSION INSTALLED
STEERING	1.4139	TIRES MOUNTED AND INSTALLED
TRANSMISSION	5.3982	VEHICLE TESTED AND INSPECTED
UNDER BODY	2.4607	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	1.6446	
TOTAL US CONTENT	42.6993	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 4GS69
 BUICK REGAL
 CARLINE 0G
 ASSEMBLY LOC: OSHAWA, ONTARIO CANADA

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.4270	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	1.2688	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	1.0347	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.7434	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.3725	FRONT AND REAR DOORS INSTALLED
DOORS	.3121	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	2.1215	EXTERIOR PAINT APPLIED
ENGINE	16.9522	ELECTRICAL WIRING INSTALLED
FRAME	.0192	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	1.6697	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	.2232	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	1.2127	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	1.2437	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	.7037	SEATS INSTALLED
ROOF	.4094	SUB FRAME AND ENGINE INSTALLED
SEATS	.0487	TRANSMISSION INSTALLED
STEERING	1.2081	TIRES MOUNTED AND INSTALLED
TRANSMISSION	5.6572	VEHICLE TESTED AND INSPECTED
UNDER BODY	2.4780	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	1.4653	
TOTAL US CONTENT	41.5722	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 4PG69
 BUICK VERANO
 CARLINE P

ASSEMBLY LOC: LAKE ORION, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.0921	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	1.8016	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	3.2056	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.2695	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.6111	FRONT AND REAR DOORS INSTALLED
DOORS	3.6651	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	1.2646	EXTERIOR PAINT APPLIED
ENGINE	13.3224	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	2.4059	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	4.7804	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	1.8053	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	1.3492	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	.3251	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	1.2494	SEATS INSTALLED
SEATS	.0509	SUB FRAME AND ENGINE INSTALLED
STEERING	.2199	TRANSMISSION INSTALLED
TRANSMISSION	8.8943	TIRES MOUNTED AND INSTALLED
UNDER BODY	3.3779	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	2.2505	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	53.9418	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 4PH69
 BUICK VERANO
 CARLINE P

ASSEMBLY LOC: LAKE ORION, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.0278	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	1.8964	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	3.0297	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.2008	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.2871	FRONT AND REAR DOORS INSTALLED
DOORS	3.1766	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	1.3937	EXTERIOR PAINT APPLIED
ENGINE	12.6246	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	2.2755	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	4.5219	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	1.7172	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	1.2761	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	.3075	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	1.4425	SEATS INSTALLED
SEATS	.0481	SUB FRAME AND ENGINE INSTALLED
STEERING	.2095	TRANSMISSION INSTALLED
TRANSMISSION	8.4124	TIRES MOUNTED AND INSTALLED
UNDER BODY	3.1007	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	2.1311	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	51.0803	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 4ZB79
 BUICK LACROSSE
 CARLINE Z

ASSEMBLY LOC: HAMTRAMCK, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.2343	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	3.2796	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.4208	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	.7964	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	2.0882	FRONT AND REAR DOORS INSTALLED
DOORS	4.8436	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	1.5034	EXTERIOR PAINT APPLIED
ENGINE	16.4159	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	1.1819	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	1.9552	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	1.3316	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	1.2310	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	.8242	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	1.2502	SEATS INSTALLED
SEATS	4.1993	SUB FRAME AND ENGINE INSTALLED
STEERING	.9220	TRANSMISSION INSTALLED
TRANSMISSION	.9249	TIRES MOUNTED AND INSTALLED
UNDER BODY	3.5073	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	1.6072	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	51.5181	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 4ZC79
 BUICK LACROSSE
 CARLINE Z

ASSEMBLY LOC: HAMTRAMCK, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.5114	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	3.0083	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.1742	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	.7189	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	2.2937	FRONT AND REAR DOORS INSTALLED
DOORS	4.3291	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	3.0847	EXTERIOR PAINT APPLIED
ENGINE	14.7581	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	1.0358	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	1.8466	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	1.1958	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	1.1078	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	1.4578	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	1.3075	SEATS INSTALLED
SEATS	4.6859	SUB FRAME AND ENGINE INSTALLED
STEERING	.7035	TRANSMISSION INSTALLED
TRANSMISSION	.8381	TIRES MOUNTED AND INSTALLED
UNDER BODY	3.1724	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	1.4783	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	50.7089	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 6AB69
 CADILLAC ATS
 CARLINE A

ASSEMBLY LOC: LANSING GR, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.7756	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	3.0311	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.0499	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	2.0978	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	2.4654	FRONT AND REAR DOORS INSTALLED
DOORS	5.4533	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	2.0153	EXTERIOR PAINT APPLIED
ENGINE	14.4438	ELECTRICAL WIRING INSTALLED
FRAME	.1250	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	1.2395	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	2.3078	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	2.0405	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	1.0901	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	1.4507	SEATS INSTALLED
ROOF	1.5136	SUB FRAME AND ENGINE INSTALLED
SEATS	4.3856	TRANSMISSION INSTALLED
STEERING	.9848	TIRES MOUNTED AND INSTALLED
TRANSMISSION	9.7037	VEHICLE TESTED AND INSPECTED
UNDER BODY	5.9925	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	1.7395	
TOTAL US CONTENT	65.9066	

COST OF FINAL ASSEMBLY: \$6,362.00

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 6AC47
 CADILLAC CTS
 CARLINE A

ASSEMBLY LOC: LANSING GR, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.5832	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	2.7416	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	3.1605	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.7219	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.7722	FRONT AND REAR DOORS INSTALLED
DOORS	2.7217	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	2.1100	EXTERIOR PAINT APPLIED
ENGINE	12.6468	ELECTRICAL WIRING INSTALLED
FRAME	.1065	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	1.1296	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	1.9825	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	1.8047	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	.9163	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	1.3301	SEATS INSTALLED
ROOF	2.1546	SUB FRAME AND ENGINE INSTALLED
SEATS	6.7621	TRANSMISSION INSTALLED
STEERING	.8730	TIRES MOUNTED AND INSTALLED
TRANSMISSION	8.6377	VEHICLE TESTED AND INSPECTED
UNDER BODY	5.5091	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	.0769	
TOTAL US CONTENT	58.7420	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 6AC69
 CADILLAC ATS
 CARLINE A

ASSEMBLY LOC: LANSING GR, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.6756	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	2.8669	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	1.9228	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.9449	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.9289	FRONT AND REAR DOORS INSTALLED
DOORS	4.4009	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	2.0993	EXTERIOR PAINT APPLIED
ENGINE	13.8268	ELECTRICAL WIRING INSTALLED
FRAME	.1166	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	1.2131	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	2.1410	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	1.9131	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	1.0066	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	1.3517	SEATS INSTALLED
ROOF	1.6242	SUB FRAME AND ENGINE INSTALLED
SEATS	6.2584	TRANSMISSION INSTALLED
STEERING	1.0929	TIRES MOUNTED AND INSTALLED
TRANSMISSION	9.3195	VEHICLE TESTED AND INSPECTED
UNDER BODY	5.5718	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	1.7371	
TOTAL US CONTENT	64.0134	

COST OF FINAL ASSEMBLY: \$6,396.00

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 6AD47
 CADILLAC CTS
 CARLINE A

ASSEMBLY LOC: LANSING GR, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.6562	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	2.4955	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.6989	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.5790	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	4.3809	FRONT AND REAR DOORS INSTALLED
DOORS	2.4385	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	2.5445	EXTERIOR PAINT APPLIED
ENGINE	13.2158	ELECTRICAL WIRING INSTALLED
FRAME	.0978	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	1.1257	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	2.1304	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	1.6488	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	.6811	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	1.2192	SEATS INSTALLED
ROOF	2.1032	SUB FRAME AND ENGINE INSTALLED
SEATS	6.8717	TRANSMISSION INSTALLED
STEERING	1.7195	TIRES MOUNTED AND INSTALLED
TRANSMISSION	6.8744	VEHICLE TESTED AND INSPECTED
UNDER BODY	5.0625	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	.1176	
TOTAL US CONTENT	60.6623	

COST OF FINAL ASSEMBLY: \$5,179.00

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 6AD69
 CADILLAC ATS
 CARLINE A

ASSEMBLY LOC: LANSING GR, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.6942	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	2.5304	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	1.7312	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.7753	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	2.4622	FRONT AND REAR DOORS INSTALLED
DOORS	4.1057	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	2.6923	EXTERIOR PAINT APPLIED
ENGINE	14.1906	ELECTRICAL WIRING INSTALLED
FRAME	.1054	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	1.1095	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	2.2394	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	1.7266	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	.8042	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	1.2219	SEATS INSTALLED
ROOF	1.6623	SUB FRAME AND ENGINE INSTALLED
SEATS	5.9906	TRANSMISSION INSTALLED
STEERING	1.4604	TIRES MOUNTED AND INSTALLED
TRANSMISSION	7.3752	VEHICLE TESTED AND INSPECTED
UNDER BODY	5.0655	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	1.5216	
TOTAL US CONTENT	61.4655	

COST OF FINAL ASSEMBLY: \$6,448.00

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 6AE47
 CADILLAC CTS
 CARLINE A

ASSEMBLY LOC: LANSING GR, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.1800	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	1.7069	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.0998	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.5152	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.1256	FRONT AND REAR DOORS INSTALLED
DOORS	1.2638	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	2.2495	EXTERIOR PAINT APPLIED
ENGINE	1.6049	ELECTRICAL WIRING INSTALLED
FRAME	.0146	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	.1408	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	.8750	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	1.1620	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	.0908	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	1.7092	SEATS INSTALLED
ROOF	1.2269	SUB FRAME AND ENGINE INSTALLED
SEATS	5.5897	TRANSMISSION INSTALLED
STEERING	.8330	TIRES MOUNTED AND INSTALLED
TRANSMISSION	.0933	VEHICLE TESTED AND INSPECTED
UNDER BODY	3.5164	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	1.5098	
TOTAL US CONTENT	29.5083	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 6AE69
 CADILLAC CTS
 CARLINE A

ASSEMBLY LOC: LANSING GR, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.1898	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	1.6735	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	1.1291	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.5512	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.2145	FRONT AND REAR DOORS INSTALLED
DOORS	2.3576	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	2.0863	EXTERIOR PAINT APPLIED
ENGINE	1.6525	ELECTRICAL WIRING INSTALLED
FRAME	.0151	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	.1453	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	.8868	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	1.1943	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	.0938	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	1.7644	SEATS INSTALLED
ROOF	.9356	SUB FRAME AND ENGINE INSTALLED
SEATS	5.7119	TRANSMISSION INSTALLED
STEERING	.8628	TIRES MOUNTED AND INSTALLED
TRANSMISSION	.0932	VEHICLE TESTED AND INSPECTED
UNDER BODY	3.3346	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	1.5567	
TOTAL US CONTENT	29.4502	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 6AF69
 CADILLAC CTS
 CARLINE A

ASSEMBLY LOC: LANSING GR, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.4915	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	2.3252	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.3578	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.5794	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.2563	FRONT AND REAR DOORS INSTALLED
DOORS	5.7790	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	1.4528	EXTERIOR PAINT APPLIED
ENGINE	12.4429	ELECTRICAL WIRING INSTALLED
FRAME	.1324	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	.8120	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	2.0501	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	1.8392	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	.8330	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	.9546	SEATS INSTALLED
ROOF	1.3224	SUB FRAME AND ENGINE INSTALLED
SEATS	6.6456	TRANSMISSION INSTALLED
STEERING	1.6170	TIRES MOUNTED AND INSTALLED
TRANSMISSION	7.6121	VEHICLE TESTED AND INSPECTED
UNDER BODY	4.8023	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	1.0969	
TOTAL US CONTENT	57.4036	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 6AG47
 CADILLAC ATS
 CARLINE A

ASSEMBLY LOC: LANSING GR, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.6927	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	2.4458	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.6501	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.6405	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.2977	FRONT AND REAR DOORS INSTALLED
DOORS	2.1490	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	2.5933	EXTERIOR PAINT APPLIED
ENGINE	12.9864	ELECTRICAL WIRING INSTALLED
FRAME	.1298	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	.2976	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	2.0231	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	1.8548	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	1.0002	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	1.0833	SEATS INSTALLED
ROOF	1.6940	SUB FRAME AND ENGINE INSTALLED
SEATS	7.3994	TRANSMISSION INSTALLED
STEERING	1.7581	TIRES MOUNTED AND INSTALLED
TRANSMISSION	7.0520	VEHICLE TESTED AND INSPECTED
UNDER BODY	5.1966	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	1.3540	
TOTAL US CONTENT	58.2997	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 6AG69
 CADILLAC ATS
 CARLINE A

ASSEMBLY LOC: LANSING GR, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.7568	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	2.5023	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	1.7427	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.7902	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.2626	FRONT AND REAR DOORS INSTALLED
DOORS	3.8066	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	2.6939	EXTERIOR PAINT APPLIED
ENGINE	13.5149	ELECTRICAL WIRING INSTALLED
FRAME	.1056	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	.2514	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	2.0928	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	1.8444	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	1.0982	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	1.0897	SEATS INSTALLED
ROOF	1.5837	SUB FRAME AND ENGINE INSTALLED
SEATS	6.4499	TRANSMISSION INSTALLED
STEERING	1.8066	TIRES MOUNTED AND INSTALLED
TRANSMISSION	7.3984	VEHICLE TESTED AND INSPECTED
UNDER BODY	5.1154	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	1.4089	
TOTAL US CONTENT	59.3158	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 6AJ69
 CADILLAC CTS
 CARLINE A

ASSEMBLY LOC: LANSING GR, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.1569	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	1.9844	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	1.7749	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.4628	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.2281	FRONT AND REAR DOORS INSTALLED
DOORS	2.9482	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	2.6927	EXTERIOR PAINT APPLIED
ENGINE	15.5521	ELECTRICAL WIRING INSTALLED
FRAME	.0175	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	.1285	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	3.1647	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	1.2920	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	.1073	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	1.3870	SEATS INSTALLED
ROOF	1.4896	SUB FRAME AND ENGINE INSTALLED
SEATS	5.5637	TRANSMISSION INSTALLED
STEERING	.8592	TIRES MOUNTED AND INSTALLED
TRANSMISSION	4.1292	VEHICLE TESTED AND INSPECTED
UNDER BODY	3.1607	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	1.7588	
TOTAL US CONTENT	50.8593	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 6AK69
 CADILLAC CTS
 CARLINE A

ASSEMBLY LOC: LANSING GR, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.5189	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	2.8438	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.3977	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.3855	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.2290	FRONT AND REAR DOORS INSTALLED
DOORS	3.7478	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	2.5618	EXTERIOR PAINT APPLIED
ENGINE	11.5395	ELECTRICAL WIRING INSTALLED
FRAME	.1163	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	.3702	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	1.9327	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	1.6298	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	.6542	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	.6563	SEATS INSTALLED
ROOF	1.2282	SUB FRAME AND ENGINE INSTALLED
SEATS	8.1673	TRANSMISSION INSTALLED
STEERING	1.5125	TIRES MOUNTED AND INSTALLED
TRANSMISSION	6.0727	VEHICLE TESTED AND INSPECTED
UNDER BODY	4.3753	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	.6478	
TOTAL US CONTENT	53.5883	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 6AL69
 CADILLAC CTS
 CARLINE A

ASSEMBLY LOC: LANSING GR, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.3833	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	2.5032	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.1825	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.3240	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.2119	FRONT AND REAR DOORS INSTALLED
DOORS	3.2235	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	1.9938	EXTERIOR PAINT APPLIED
ENGINE	7.5112	ELECTRICAL WIRING INSTALLED
FRAME	.1082	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	.1284	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	1.8129	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	1.5295	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	1.0619	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	1.2646	SEATS INSTALLED
ROOF	1.0188	SUB FRAME AND ENGINE INSTALLED
SEATS	7.4998	TRANSMISSION INSTALLED
STEERING	1.4682	TIRES MOUNTED AND INSTALLED
TRANSMISSION	3.5957	VEHICLE TESTED AND INSPECTED
UNDER BODY	4.0588	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	.2166	
TOTAL US CONTENT	44.0977	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 6GE69
 CADILLAC XTS
 CARLINE 0G
 ASSEMBLY LOC: OSHAWA, ONTARIO CANADA

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	2.0250	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	1.2842	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.3542	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	.5098	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.2892	FRONT AND REAR DOORS INSTALLED
DOORS	.9360	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	1.5679	EXTERIOR PAINT APPLIED
ENGINE	.7375	ELECTRICAL WIRING INSTALLED
FRAME	.0247	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	.8614	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	1.0642	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	.2893	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	.8623	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	.7527	SEATS INSTALLED
ROOF	2.0355	SUB FRAME AND ENGINE INSTALLED
SEATS	.0334	TRANSMISSION INSTALLED
STEERING	1.5924	TIRES MOUNTED AND INSTALLED
TRANSMISSION	5.4692	VEHICLE TESTED AND INSPECTED
UNDER BODY	3.0512	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	1.2244	
TOTAL US CONTENT	26.9653	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 6GV69
 CADILLAC XTS
 CARLINE 0G
 ASSEMBLY LOC: OSHAWA, ONTARIO CANADA

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.9654	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	1.1684	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.1033	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	.5250	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.1907	FRONT AND REAR DOORS INSTALLED
DOORS	.8490	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	1.4410	EXTERIOR PAINT APPLIED
ENGINE	2.2628	ELECTRICAL WIRING INSTALLED
FRAME	.0418	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	.7425	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	.8670	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	.2608	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	1.0369	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	.7319	SEATS INSTALLED
ROOF	1.8375	SUB FRAME AND ENGINE INSTALLED
SEATS	.0298	TRANSMISSION INSTALLED
STEERING	1.9157	TIRES MOUNTED AND INSTALLED
TRANSMISSION	4.9427	VEHICLE TESTED AND INSPECTED
UNDER BODY	2.7984	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	1.0987	
TOTAL US CONTENT	26.8105	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 6NF26
 CADILLAC XT5
 CARLINE N

ASSEMBLY LOC: SPRING HILL, TENNESSEE U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.8991	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	3.1691	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.6267	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.8899	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.7334	FRONT AND REAR DOORS INSTALLED
DOORS	6.4558	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	1.6746	EXTERIOR PAINT APPLIED
ENGINE	17.0663	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	1.6468	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	4.1309	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	1.3980	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.0568	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	.8886	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	1.2236	SEATS INSTALLED
SEATS	2.2880	SUB FRAME AND ENGINE INSTALLED
STEERING	2.3805	TRANSMISSION INSTALLED
TRANSMISSION	.8551	TIRES MOUNTED AND INSTALLED
UNDER BODY	6.4300	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	1.7155	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	59.5296	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 6NH26
 CADILLAC XT5
 CARLINE N

ASSEMBLY LOC: SPRING HILL, TENNESSEE U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.6799	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	3.0246	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.5210	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.7105	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	2.3726	FRONT AND REAR DOORS INSTALLED
DOORS	6.1327	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	2.0167	EXTERIOR PAINT APPLIED
ENGINE	15.5027	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	1.4564	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	3.5282	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	1.2766	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.0410	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	1.9678	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	1.1326	SEATS INSTALLED
SEATS	2.4923	SUB FRAME AND ENGINE INSTALLED
STEERING	2.1348	TRANSMISSION INSTALLED
TRANSMISSION	1.3383	TIRES MOUNTED AND INSTALLED
UNDER BODY	5.9648	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	1.5312	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	57.8257	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 6NJ26
 CADILLAC XT5
 CARLINE N

ASSEMBLY LOC: SPRING HILL, TENNESSEE U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.6256	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	2.8478	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.3169	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.5933	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	2.7313	FRONT AND REAR DOORS INSTALLED
DOORS	5.6520	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	2.0402	EXTERIOR PAINT APPLIED
ENGINE	14.4469	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	1.3402	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	3.1763	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	1.1968	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.0507	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	2.4313	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	1.0559	SEATS INSTALLED
SEATS	2.5292	SUB FRAME AND ENGINE INSTALLED
STEERING	1.9331	TRANSMISSION INSTALLED
TRANSMISSION	1.5582	TIRES MOUNTED AND INSTALLED
UNDER BODY	5.6962	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	1.8421	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	56.0650	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 6NK26
 CADILLAC XT5
 CARLINE N

ASSEMBLY LOC: SPRING HILL, TENNESSEE U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.8618	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	5.0370	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.0022	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.3229	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	3.4256	FRONT AND REAR DOORS INSTALLED
DOORS	7.4221	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	2.5445	EXTERIOR PAINT APPLIED
ENGINE	12.0846	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	1.0655	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	2.2457	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	.9840	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.0318	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	3.6144	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	.6701	SEATS INSTALLED
SEATS	3.2170	SUB FRAME AND ENGINE INSTALLED
STEERING	1.1677	TRANSMISSION INSTALLED
TRANSMISSION	2.0636	TIRES MOUNTED AND INSTALLED
UNDER BODY	5.1641	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	1.5353	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	57.4608	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 6NN26
 CADILLAC XT5
 CARLINE N

ASSEMBLY LOC: SPRING HILL, TENNESSEE U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.5344	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	2.7167	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.2936	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.5598	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	3.5565	FRONT AND REAR DOORS INSTALLED
DOORS	5.5305	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	1.7449	EXTERIOR PAINT APPLIED
ENGINE	14.3325	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	1.2561	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	2.7945	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	1.4446	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.0360	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	4.3068	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	1.0357	SEATS INSTALLED
SEATS	2.2149	SUB FRAME AND ENGINE INSTALLED
STEERING	1.3768	TRANSMISSION INSTALLED
TRANSMISSION	2.4673	TIRES MOUNTED AND INSTALLED
UNDER BODY	5.5415	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	1.6281	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	57.3721	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 6NP26
 CADILLAC XT5
 CARLINE N

ASSEMBLY LOC: SPRING HILL, TENNESSEE U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.4727	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	2.6678	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.2032	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.4844	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	3.3824	FRONT AND REAR DOORS INSTALLED
DOORS	5.3691	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	2.1336	EXTERIOR PAINT APPLIED
ENGINE	13.6508	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	1.1956	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	2.6585	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	1.3700	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.0358	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	4.1022	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	.9861	SEATS INSTALLED
SEATS	2.4536	SUB FRAME AND ENGINE INSTALLED
STEERING	1.3102	TRANSMISSION INSTALLED
TRANSMISSION	2.3382	TIRES MOUNTED AND INSTALLED
UNDER BODY	5.5977	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	.2060	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	54.6189	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 6NR26
 CADILLAC XT5
 CARLINE N

ASSEMBLY LOC: SPRING HILL, TENNESSEE U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.7850	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	4.6141	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	1.9173	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.2720	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	4.5232	FRONT AND REAR DOORS INSTALLED
DOORS	7.1029	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	2.6433	EXTERIOR PAINT APPLIED
ENGINE	11.6887	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	1.0245	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	2.1785	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	1.1849	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.0291	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	3.5152	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	.6437	SEATS INSTALLED
SEATS	3.0519	SUB FRAME AND ENGINE INSTALLED
STEERING	1.1228	TRANSMISSION INSTALLED
TRANSMISSION	2.0121	TIRES MOUNTED AND INSTALLED
UNDER BODY	4.9731	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	.1764	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	55.4598	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL TNB26
 GMC ACADIA
 CARLINE N

ASSEMBLY LOC: SPRING HILL, TENNESSEE U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.9326	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	3.3729	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.9216	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.5342	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.4969	FRONT AND REAR DOORS INSTALLED
DOORS	5.5976	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	3.6542	EXTERIOR PAINT APPLIED
ENGINE	13.8784	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	1.7670	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	2.4201	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	1.6807	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.0744	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	1.5997	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	1.2328	SEATS INSTALLED
SEATS	3.4849	SUB FRAME AND ENGINE INSTALLED
STEERING	1.9922	TRANSMISSION INSTALLED
TRANSMISSION	.4663	TIRES MOUNTED AND INSTALLED
UNDER BODY	6.8203	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	2.3841	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	58.3120	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL TNC26
 GMC ACADIA
 CARLINE N

ASSEMBLY LOC: SPRING HILL, TENNESSEE U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.7377	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	3.0184	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.6213	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.4045	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	2.5259	FRONT AND REAR DOORS INSTALLED
DOORS	5.2972	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	3.8023	EXTERIOR PAINT APPLIED
ENGINE	16.7365	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	1.6673	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	3.5646	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	1.5803	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.0433	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	2.4206	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	1.3804	SEATS INSTALLED
SEATS	3.3167	SUB FRAME AND ENGINE INSTALLED
STEERING	1.7877	TRANSMISSION INSTALLED
TRANSMISSION	5.8945	TIRES MOUNTED AND INSTALLED
UNDER BODY	6.2391	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	1.9242	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	66.9634	

COST OF FINAL ASSEMBLY: \$4,371.00

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL TND26
 GMC ACADIA
 CARLINE N

ASSEMBLY LOC: SPRING HILL, TENNESSEE U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.6048	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	3.0936	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.4422	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.3115	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	2.7861	FRONT AND REAR DOORS INSTALLED
DOORS	4.9772	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	3.9316	EXTERIOR PAINT APPLIED
ENGINE	16.6818	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	1.5671	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	3.6431	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	1.3994	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.0563	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	2.6711	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	1.8824	SEATS INSTALLED
SEATS	3.1835	SUB FRAME AND ENGINE INSTALLED
STEERING	1.6608	TRANSMISSION INSTALLED
TRANSMISSION	6.9552	TIRES MOUNTED AND INSTALLED
UNDER BODY	5.9587	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	1.9527	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	67.7599	

COST OF FINAL ASSEMBLY: \$4,423.00

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL TNE26
 GMC ACADIA
 CARLINE N

ASSEMBLY LOC: SPRING HILL, TENNESSEE U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.5678	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	3.0573	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.3559	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.2717	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	2.7687	FRONT AND REAR DOORS INSTALLED
DOORS	4.8776	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	4.8114	EXTERIOR PAINT APPLIED
ENGINE	16.6473	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	1.5268	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	3.6744	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	1.4336	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.0354	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	2.4607	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	1.8682	SEATS INSTALLED
SEATS	3.4394	SUB FRAME AND ENGINE INSTALLED
STEERING	1.6069	TRANSMISSION INSTALLED
TRANSMISSION	7.1951	TIRES MOUNTED AND INSTALLED
UNDER BODY	5.6492	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	2.2624	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	68.5108	

COST OF FINAL ASSEMBLY: \$4,447.00

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL TNF26
 GMC ACADIA
 CARLINE N

ASSEMBLY LOC: SPRING HILL, TENNESSEE U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.4254	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	2.6309	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.2180	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.1541	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	3.2093	FRONT AND REAR DOORS INSTALLED
DOORS	5.5413	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	4.3236	EXTERIOR PAINT APPLIED
ENGINE	15.1268	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	1.3655	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	3.3223	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	1.3892	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.0516	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	2.8370	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	1.9904	SEATS INSTALLED
SEATS	3.3169	SUB FRAME AND ENGINE INSTALLED
STEERING	2.0955	TRANSMISSION INSTALLED
TRANSMISSION	6.8778	TIRES MOUNTED AND INSTALLED
UNDER BODY	5.4652	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	1.9910	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	66.3328	

COST OF FINAL ASSEMBLY: \$4,523.00

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1AG37
 CHEVROLET CAMARO
 CARLINE A
 ASSEMBLY LOC: LANSING, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	.7874	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	2.8785	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	1.9679	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.5663	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.8195	FRONT AND REAR DOORS INSTALLED
DOORS	2.9037	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	3.5968	EXTERIOR PAINT APPLIED
ENGINE	16.9534	ELECTRICAL WIRING INSTALLED
FRAME	.0641	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	.8530	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	2.0805	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	2.7363	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	1.4150	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	1.8370	SEATS INSTALLED
ROOF	.7373	SUB FRAME AND ENGINE INSTALLED
SEATS	4.6747	TRANSMISSION INSTALLED
STEERING	.5550	TIRES MOUNTED AND INSTALLED
TRANSMISSION	7.8932	VEHICLE TESTED AND INSPECTED
UNDER BODY	7.9171	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	2.2620	
TOTAL US CONTENT	65.4998	

COST OF FINAL ASSEMBLY: \$3,986.00

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1AG67
 CHEVROLET CAMARO
 CARLINE A
 ASSEMBLY LOC: LANSING, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.1614	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	2.4992	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.8283	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.3191	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	2.1880	FRONT AND REAR DOORS INSTALLED
DOORS	2.5881	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	3.4587	EXTERIOR PAINT APPLIED
ENGINE	15.5471	ELECTRICAL WIRING INSTALLED
FRAME	.0325	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	.7381	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	2.1027	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	2.3843	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	.9606	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	1.5808	SEATS INSTALLED
ROOF	9.4868	SUB FRAME AND ENGINE INSTALLED
SEATS	4.0509	TRANSMISSION INSTALLED
STEERING	.4758	TIRES MOUNTED AND INSTALLED
TRANSMISSION	7.4633	VEHICLE TESTED AND INSPECTED
UNDER BODY	7.1291	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	2.1243	
TOTAL US CONTENT	70.1202	

COST OF FINAL ASSEMBLY: \$4,054.00

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1AH37
 CHEVROLET CAMARO
 CARLINE A
 ASSEMBLY LOC: LANSING, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST OF ASSEMBLY OPERATIONS -----	
BODY FRONT	.7084	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	2.8744	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	1.7697	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.3838	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	2.2483	FRONT AND REAR DOORS INSTALLED
DOORS	2.8979	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	3.9472	EXTERIOR PAINT APPLIED
ENGINE	16.1043	ELECTRICAL WIRING INSTALLED
FRAME	.0575	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	.7680	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	2.3112	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	2.5452	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	1.0937	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	1.6498	SEATS INSTALLED
ROOF	1.0109	SUB FRAME AND ENGINE INSTALLED
SEATS	5.7240	TRANSMISSION INSTALLED
STEERING	.5001	TIRES MOUNTED AND INSTALLED
TRANSMISSION	7.2870	VEHICLE TESTED AND INSPECTED
UNDER BODY	7.4956	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	2.3148	
TOTAL US CONTENT	64.6927	

COST OF FINAL ASSEMBLY: \$4,033.00

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1AH67
 CHEVROLET CAMARO
 CARLINE A
 ASSEMBLY LOC: LANSING, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.0711	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	2.6000	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.6484	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.2183	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.8981	FRONT AND REAR DOORS INSTALLED
DOORS	2.7258	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	3.6551	EXTERIOR PAINT APPLIED
ENGINE	14.2533	ELECTRICAL WIRING INSTALLED
FRAME	.0303	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	.6808	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	2.2303	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	2.3014	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	.9201	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	1.4615	SEATS INSTALLED
ROOF	8.7784	SUB FRAME AND ENGINE INSTALLED
SEATS	5.1069	TRANSMISSION INSTALLED
STEERING	.4394	TIRES MOUNTED AND INSTALLED
TRANSMISSION	6.5588	VEHICLE TESTED AND INSPECTED
UNDER BODY	6.9915	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	2.0419	
TOTAL US CONTENT	67.6124	

COST OF FINAL ASSEMBLY: \$4,095.00

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1AJ37
 CHEVROLET CAMARO
 CARLINE A
 ASSEMBLY LOC: LANSING, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	.6818	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	2.4252	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	1.6624	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.6716	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	2.4956	FRONT AND REAR DOORS INSTALLED
DOORS	2.4908	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	3.2815	EXTERIOR PAINT APPLIED
ENGINE	2.7643	ELECTRICAL WIRING INSTALLED
FRAME	.0256	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	.6956	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	3.6726	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	2.5019	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	.1619	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	1.7879	SEATS INSTALLED
ROOF	.6324	SUB FRAME AND ENGINE INSTALLED
SEATS	3.9143	TRANSMISSION INSTALLED
STEERING	.4691	TIRES MOUNTED AND INSTALLED
TRANSMISSION	4.4579	VEHICLE TESTED AND INSPECTED
UNDER BODY	6.7539	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	2.4996	
TOTAL US CONTENT	45.0470	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1AJ67
 CHEVROLET CAMARO
 CARLINE A
 ASSEMBLY LOC: LANSING, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.0563	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	2.2508	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.5679	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.3976	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.7404	FRONT AND REAR DOORS INSTALLED
DOORS	2.3998	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	3.2238	EXTERIOR PAINT APPLIED
ENGINE	2.0478	ELECTRICAL WIRING INSTALLED
FRAME	.0237	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	.6714	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	3.0993	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	2.2758	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	.0832	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	1.6322	SEATS INSTALLED
ROOF	8.6312	SUB FRAME AND ENGINE INSTALLED
SEATS	3.6869	TRANSMISSION INSTALLED
STEERING	.4330	TIRES MOUNTED AND INSTALLED
TRANSMISSION	7.1446	VEHICLE TESTED AND INSPECTED
UNDER BODY	6.5137	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	2.3120	
TOTAL US CONTENT	53.1924	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1AK37
 CHEVROLET CAMARO
 CARLINE A
 ASSEMBLY LOC: LANSING, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	.6235	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	2.5862	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	1.4942	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.4439	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.7443	FRONT AND REAR DOORS INSTALLED
DOORS	2.7566	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	4.0344	EXTERIOR PAINT APPLIED
ENGINE	2.5153	ELECTRICAL WIRING INSTALLED
FRAME	.0234	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	.5175	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	3.4051	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	2.4056	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	.1480	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	1.5015	SEATS INSTALLED
ROOF	.8932	SUB FRAME AND ENGINE INSTALLED
SEATS	5.0681	TRANSMISSION INSTALLED
STEERING	.4766	TIRES MOUNTED AND INSTALLED
TRANSMISSION	5.8628	VEHICLE TESTED AND INSPECTED
UNDER BODY	6.8122	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	2.2841	
TOTAL US CONTENT	46.5977	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1AK67
 CHEVROLET CAMARO
 CARLINE A
 ASSEMBLY LOC: LANSING, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	.9582	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	2.4539	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.4043	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.3033	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.9557	FRONT AND REAR DOORS INSTALLED
DOORS	2.6627	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	3.6977	EXTERIOR PAINT APPLIED
ENGINE	1.8726	ELECTRICAL WIRING INSTALLED
FRAME	.0215	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	.4916	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	3.3293	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	2.2896	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	.0753	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	1.3641	SEATS INSTALLED
ROOF	7.8130	SUB FRAME AND ENGINE INSTALLED
SEATS	4.6852	TRANSMISSION INSTALLED
STEERING	.3922	TIRES MOUNTED AND INSTALLED
TRANSMISSION	5.4497	VEHICLE TESTED AND INSPECTED
UNDER BODY	6.4543	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	2.0977	
TOTAL US CONTENT	51.7726	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1A137
 CHEVROLET CAMARO
 CARLINE A
 ASSEMBLY LOC: LANSING, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	.3754	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	1.5946	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	.9186	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.6652	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.5372	FRONT AND REAR DOORS INSTALLED
DOORS	1.8751	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	2.6223	EXTERIOR PAINT APPLIED
ENGINE	16.8696	ELECTRICAL WIRING INSTALLED
FRAME	.0184	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	.2404	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	1.9556	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	1.8798	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	.1065	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	1.5113	SEATS INSTALLED
ROOF	.5365	SUB FRAME AND ENGINE INSTALLED
SEATS	.4768	TRANSMISSION INSTALLED
STEERING	.2589	TIRES MOUNTED AND INSTALLED
TRANSMISSION	19.8961	VEHICLE TESTED AND INSPECTED
UNDER BODY	3.7690	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	1.6780	
TOTAL US CONTENT	59.7864	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1AL67
 CHEVROLET CAMARO
 CARLINE A
 ASSEMBLY LOC: LANSING, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	.5957	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	1.4935	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	1.5017	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.5687	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.5111	FRONT AND REAR DOORS INSTALLED
DOORS	1.7109	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	2.1210	EXTERIOR PAINT APPLIED
ENGINE	15.9826	ELECTRICAL WIRING INSTALLED
FRAME	.0175	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	.2288	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	1.8669	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	1.8036	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	.1014	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	.4355	SEATS INSTALLED
ROOF	4.8943	SUB FRAME AND ENGINE INSTALLED
SEATS	.4011	TRANSMISSION INSTALLED
STEERING	.2455	TIRES MOUNTED AND INSTALLED
TRANSMISSION	22.2900	VEHICLE TESTED AND INSPECTED
UNDER BODY	3.7169	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	1.5985	
TOTAL US CONTENT	64.0864	

COST OF FINAL ASSEMBLY: \$4,512.00

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1FB48
 CHEVROLET BOLT
 CARLINE F

ASSEMBLY LOC: LAKE ORION, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.0523	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	2.1368	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	1.2922	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	.4501	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.7237	FRONT AND REAR DOORS INSTALLED
DOORS	3.4248	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	.6965	EXTERIOR PAINT APPLIED
ENGINE	.0153	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	.1128	EXTERIOR MOLDINGS INSTALLED
HOOD/FRONT END COMP.	.9069	AIR CONDITIONING AND HEATER INSTALLED
RADIATOR & GRILLE	.4550	INSTRUMENT PANEL INSTALLED
REAR AXLE/SUSPENSION	.0669	DOOR HARDWARE AND WINDOWS INSTALLED
ROOF	.3068	INTERIOR TRIM & FLOOR COVERING INSTALLED
SEATS	2.8855	SEATS INSTALLED
STEERING	.0043	SUB FRAME AND ENGINE INSTALLED
TRANSMISSION	.4897	TRANSMISSION INSTALLED
UNDER BODY	2.8562	TIRES MOUNTED AND INSTALLED
WHEELS & TIRES	.0210	VEHICLE TESTED AND INSPECTED
TOTAL US CONTENT	17.8978	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1GX69
 CHEVROLET IMPALA
 CARLINE 0G
 ASSEMBLY LOC: OSHAWA, ONTARIO CANADA

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.7943	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	1.4643	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	3.2929	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.9283	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.4842	FRONT AND REAR DOORS INSTALLED
DOORS	3.2878	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	2.3143	EXTERIOR PAINT APPLIED
ENGINE	9.1961	ELECTRICAL WIRING INSTALLED
FRAME	.0018	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	2.5097	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	3.1395	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	2.0353	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	1.2518	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	.7829	SEATS INSTALLED
ROOF	1.0573	SUB FRAME AND ENGINE INSTALLED
SEATS	.5579	TRANSMISSION INSTALLED
STEERING	1.9520	TIRES MOUNTED AND INSTALLED
TRANSMISSION	4.0486	VEHICLE TESTED AND INSPECTED
UNDER BODY	2.0976	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	2.6133	
TOTAL US CONTENT	45.8109	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1GY69
 CHEVROLET IMPALA
 CARLINE 0G
 ASSEMBLY LOC: OSHAWA, ONTARIO CANADA

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.7428	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	1.8871	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	3.2264	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	2.0291	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.4701	FRONT AND REAR DOORS INSTALLED
DOORS	3.1065	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	2.3227	EXTERIOR PAINT APPLIED
ENGINE	6.4997	ELECTRICAL WIRING INSTALLED
FRAME	.0019	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	2.3750	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	2.9961	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	1.8807	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	1.1703	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	.7400	SEATS INSTALLED
ROOF	1.1028	SUB FRAME AND ENGINE INSTALLED
SEATS	.1860	TRANSMISSION INSTALLED
STEERING	1.5320	TIRES MOUNTED AND INSTALLED
TRANSMISSION	5.1082	VEHICLE TESTED AND INSPECTED
UNDER BODY	2.0910	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	1.5368	
TOTAL US CONTENT	42.0061	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1GZ69
 CHEVROLET IMPALA
 CARLINE 0G

ASSEMBLY LOC: HAMTRAMCK, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.7568	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	2.0080	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.9640	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.8906	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.4212	FRONT AND REAR DOORS INSTALLED
DOORS	3.1217	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	2.3387	EXTERIOR PAINT APPLIED
ENGINE	.6185	ELECTRICAL WIRING INSTALLED
FRAME	.0024	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	2.1695	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	2.8053	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	1.7353	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	1.0939	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	.6753	SEATS INSTALLED
ROOF	1.2057	SUB FRAME AND ENGINE INSTALLED
SEATS	.4296	TRANSMISSION INSTALLED
STEERING	.8327	TIRES MOUNTED AND INSTALLED
TRANSMISSION	7.7590	VEHICLE TESTED AND INSPECTED
UNDER BODY	1.8916	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	1.8773	
TOTAL US CONTENT	37.5982	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 6AB47
 CADILLAC CTS A1
 CARLINE A
 ASSEMBLY LOC: LANSING, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.7294	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	2.5740	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	3.8411	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.8896	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	2.4791	FRONT AND REAR DOORS INSTALLED
DOORS	4.0150	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	1.9672	EXTERIOR PAINT APPLIED
ENGINE	13.8434	ELECTRICAL WIRING INSTALLED
FRAME	.1166	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	1.2008	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	2.1622	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	1.9619	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	1.0038	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	1.4589	SEATS INSTALLED
ROOF	2.1336	SUB FRAME AND ENGINE INSTALLED
SEATS	3.9155	TRANSMISSION INSTALLED
STEERING	.4643	TIRES MOUNTED AND INSTALLED
TRANSMISSION	9.2156	VEHICLE TESTED AND INSPECTED
UNDER BODY	6.0384	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	.0261	
TOTAL US CONTENT	62.0379	

COST OF FINAL ASSEMBLY: \$5,082.00

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 6GB69
 CADILLAC XTS
 CARLINE 0G
 ASSEMBLY LOC: OSHAWA, ONTARIO CANADA

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	2.7141	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	2.1366	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.0987	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	2.0466	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	2.1511	FRONT AND REAR DOORS INSTALLED
DOORS	1.1975	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	2.0875	EXTERIOR PAINT APPLIED
ENGINE	.1265	ELECTRICAL WIRING INSTALLED
FRAME	.0190	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	1.7569	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	1.5567	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	.4018	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	1.1710	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	.7668	SEATS INSTALLED
ROOF	.7807	SUB FRAME AND ENGINE INSTALLED
SEATS	.0448	TRANSMISSION INSTALLED
STEERING	2.1138	TIRES MOUNTED AND INSTALLED
TRANSMISSION	7.4551	VEHICLE TESTED AND INSPECTED
UNDER BODY	3.3583	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	1.9514	
TOTAL US CONTENT	35.9358	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 6GC69
 CADILLAC XTS
 CARLINE 0G
 ASSEMBLY LOC: OSHAWA, ONTARIO CANADA

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	2.1524	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	1.7511	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.1347	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.2243	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.3714	FRONT AND REAR DOORS INSTALLED
DOORS	1.1899	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	2.3606	EXTERIOR PAINT APPLIED
ENGINE	.1160	ELECTRICAL WIRING INSTALLED
FRAME	.0124	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	1.1515	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	1.4106	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	.3703	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	.9702	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	.8589	SEATS INSTALLED
ROOF	1.1376	SUB FRAME AND ENGINE INSTALLED
SEATS	.0428	TRANSMISSION INSTALLED
STEERING	1.9388	TIRES MOUNTED AND INSTALLED
TRANSMISSION	6.9735	VEHICLE TESTED AND INSPECTED
UNDER BODY	3.2404	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	1.4695	
TOTAL US CONTENT	30.8778	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 6GD69
 CADILLAC XTS
 CARLINE 0G
 ASSEMBLY LOC: OSHAWA, ONTARIO CANADA

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	2.2548	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	1.5922	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.1652	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	.8684	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.3356	FRONT AND REAR DOORS INSTALLED
DOORS	1.0908	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	2.1351	EXTERIOR PAINT APPLIED
ENGINE	.2925	ELECTRICAL WIRING INSTALLED
FRAME	.0185	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	1.0304	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	1.2738	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	.3432	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	.9158	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	.8331	SEATS INSTALLED
ROOF	1.5127	SUB FRAME AND ENGINE INSTALLED
SEATS	.0391	TRANSMISSION INSTALLED
STEERING	1.9512	TIRES MOUNTED AND INSTALLED
TRANSMISSION	6.3795	VEHICLE TESTED AND INSPECTED
UNDER BODY	3.1863	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	1.3761	
TOTAL US CONTENT	29.5955	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1NB56
 CHEVROLET TRAVERSE
 CARLINE N
 ASSEMBLY LOC: LANSING DELTA TWP, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.3873	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	4.3920	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	3.2848	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.5747	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.7784	FRONT AND REAR DOORS INSTALLED
DOORS	5.4900	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	2.3670	EXTERIOR PAINT APPLIED
ENGINE	1.9462	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	1.0775	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	4.1862	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	1.5123	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.0861	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	.8233	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	1.4089	SEATS INSTALLED
SEATS	7.8570	SUB FRAME AND ENGINE INSTALLED
STEERING	.2814	TRANSMISSION INSTALLED
TRANSMISSION	.0071	TIRES MOUNTED AND INSTALLED
UNDER BODY	6.2687	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	2.1469	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	47.8766	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1NC56
 CHEVROLET TRAVERSE
 CARLINE N
 ASSEMBLY LOC: LANSING DELTA TWP, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.3590	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	3.8354	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	3.2181	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.5427	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.9170	FRONT AND REAR DOORS INSTALLED
DOORS	5.3785	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	2.3937	EXTERIOR PAINT APPLIED
ENGINE	1.9067	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	1.0556	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	4.1072	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	1.4815	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.0844	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	.8065	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	1.3803	SEATS INSTALLED
SEATS	7.5755	SUB FRAME AND ENGINE INSTALLED
STEERING	.0088	TRANSMISSION INSTALLED
TRANSMISSION	.0074	TIRES MOUNTED AND INSTALLED
UNDER BODY	6.1383	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	2.1026	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	46.3000	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1NE56
 CHEVROLET TRAVERSE
 CARLINE N
 ASSEMBLY LOC: LANSING DELTA TWP, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	.9526	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	4.5302	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.2411	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.0805	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.4406	FRONT AND REAR DOORS INSTALLED
DOORS	3.6061	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	2.0974	EXTERIOR PAINT APPLIED
ENGINE	1.3051	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	.7386	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	2.0584	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	.9931	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.0591	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	.9272	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	1.9731	SEATS INSTALLED
SEATS	6.2680	SUB FRAME AND ENGINE INSTALLED
STEERING	.9811	TRANSMISSION INSTALLED
TRANSMISSION	.0311	TIRES MOUNTED AND INSTALLED
UNDER BODY	5.2801	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	1.8507	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	38.4152	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 4NB56
 BUICK ENCLAVE
 CARLINE N

ASSEMBLY LOC: LANSING DELTA TWP, MICHIGAN U.S.A.

US CONTENT BY SYSTEM	PERCENTAGE OF VEHICLE COST	DESCRIPTION OF ASSEMBLY OPERATIONS
BODY FRONT	1.1718	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	3.2810	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.7598	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.3083	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	2.1598	FRONT AND REAR DOORS INSTALLED
DOORS	6.2376	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	1.5035	EXTERIOR PAINT APPLIED
ENGINE	1.6174	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	.9048	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	2.4807	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	1.3531	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.0687	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	.6875	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	1.0030	SEATS INSTALLED
SEATS	5.2924	SUB FRAME AND ENGINE INSTALLED
STEERING	.2284	TRANSMISSION INSTALLED
TRANSMISSION	.0068	TIRES MOUNTED AND INSTALLED
UNDER BODY	5.7868	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	.2436	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	38.0959	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 4NC56
 BUICK ENCLAVE
 CARLINE N

ASSEMBLY LOC: LANSING DELTA TWP, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	.9664	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	3.4890	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.3523	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.0935	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	2.0036	FRONT AND REAR DOORS INSTALLED
DOORS	5.2547	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	2.1011	EXTERIOR PAINT APPLIED
ENGINE	1.3116	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	.7500	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	2.0681	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	1.1236	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.0739	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	.9318	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	1.8809	SEATS INSTALLED
SEATS	9.1602	SUB FRAME AND ENGINE INSTALLED
STEERING	.0062	TRANSMISSION INSTALLED
TRANSMISSION	.0320	TIRES MOUNTED AND INSTALLED
UNDER BODY	4.1740	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	.2023	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	38.9764	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 4ND56
 BUICK ENCLAVE
 CARLINE N

ASSEMBLY LOC: LANSING DELTA TWP, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	.8973	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	3.2602	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	2.1230	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.0152	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.3169	FRONT AND REAR DOORS INSTALLED
DOORS	5.0249	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	1.9707	EXTERIOR PAINT APPLIED
ENGINE	1.2181	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	.6976	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	1.9201	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	1.0432	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.0530	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	.8651	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	1.7462	SEATS INSTALLED
SEATS	10.2701	SUB FRAME AND ENGINE INSTALLED
STEERING	.0057	TRANSMISSION INSTALLED
TRANSMISSION	.0297	TIRES MOUNTED AND INSTALLED
UNDER BODY	4.5062	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	1.7230	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	38.6873	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL TXM26
 GMC TERRAIN D2
 CARLINE X

ASSEMBLY LOC: SAN LUIS POTOSI, MEXICO

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	.0371	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	.1325	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	.0088	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.0304	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.0627	FRONT AND REAR DOORS INSTALLED
DOORS	.2983	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	.6338	EXTERIOR PAINT APPLIED
ENGINE	15.3059	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	.0162	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	.0948	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	.2477	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.0025	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	.2928	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	.0032	SEATS INSTALLED
SEATS	.0151	SUB FRAME AND ENGINE INSTALLED
STEERING	.0055	TRANSMISSION INSTALLED
TRANSMISSION	.0335	TIRES MOUNTED AND INSTALLED
UNDER BODY	.1756	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	.1092	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	18.5068	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL TXN26
 GMC TERRAIN D2
 CARLINE X

ASSEMBLY LOC: SAN LUIS POTOSI, MEXICO

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	.0357	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	.1276	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	.0085	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	.9934	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.0605	FRONT AND REAR DOORS INSTALLED
DOORS	.3944	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	.6113	EXTERIOR PAINT APPLIED
ENGINE	14.7549	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	.0156	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	.0914	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	.2388	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.0024	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	.2823	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	.0018	SEATS INSTALLED
SEATS	.0146	SUB FRAME AND ENGINE INSTALLED
STEERING	.0053	TRANSMISSION INSTALLED
TRANSMISSION	.0323	TIRES MOUNTED AND INSTALLED
UNDER BODY	.1693	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	.1044	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	17.9454	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1XP26
 CHEVROLET EQUINOX D2
 CARLINE X
 ASSEMBLY LOC: INGERSOLL, ONTARIO CANADA

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	.0184	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	.1767	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	.0055	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	.6846	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.0572	FRONT AND REAR DOORS INSTALLED
DOORS	.6695	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	.7840	EXTERIOR PAINT APPLIED
ENGINE	32.5742	ELECTRICAL WIRING INSTALLED
FUEL TANK / EXHAUST	.1168	EXTERIOR MOLDINGS INSTALLED
HOOD/FRONT END COMP.	.0935	AIR CONDITIONING AND HEATER INSTALLED
RADIATOR & GRILLE	.0008	INSTRUMENT PANEL INSTALLED
REAR AXLE/SUSPENSION	.2454	DOOR HARDWARE AND WINDOWS INSTALLED
ROOF	.0038	INTERIOR TRIM & FLOOR COVERING INSTALLED
SEATS	.9897	SEATS INSTALLED
STEERING	.0013	SUB FRAME AND ENGINE INSTALLED
TRANSMISSION	.0032	TRANSMISSION INSTALLED
UNDER BODY	.1313	TIRES MOUNTED AND INSTALLED
WHEELS & TIRES	.0002	VEHICLE TESTED AND INSPECTED
TOTAL US CONTENT	36.5571	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1XR26
 CHEVROLET EQUINOX D2
 CARLINE X
 ASSEMBLY LOC: INGERSOLL, ONTARIO CANADA

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	.0167	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	.1603	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	.0049	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	.6105	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.0519	FRONT AND REAR DOORS INSTALLED
DOORS	.6115	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	.7128	EXTERIOR PAINT APPLIED
ENGINE	29.5564	ELECTRICAL WIRING INSTALLED
FUEL TANK / EXHAUST	.1059	EXTERIOR MOLDINGS INSTALLED
HOOD/FRONT END COMP.	.1753	AIR CONDITIONING AND HEATER INSTALLED
RADIATOR & GRILLE	.0007	INSTRUMENT PANEL INSTALLED
REAR AXLE/SUSPENSION	.2226	DOOR HARDWARE AND WINDOWS INSTALLED
ROOF	.0034	INTERIOR TRIM & FLOOR COVERING INSTALLED
SEATS	1.1215	SEATS INSTALLED
STEERING	.0012	SUB FRAME AND ENGINE INSTALLED
TRANSMISSION	.0187	TRANSMISSION INSTALLED
UNDER BODY	.0863	TIRES MOUNTED AND INSTALLED
WHEELS & TIRES	.0002	VEHICLE TESTED AND INSPECTED
TOTAL US CONTENT	33.4618	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 1XS26
 CHEVROLET EQUINOX D2
 CARLINE X
 ASSEMBLY LOC: INGERSOLL, ONTARIO CANADA

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	.0164	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	.2254	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	.0049	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	.6117	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.0511	FRONT AND REAR DOORS INSTALLED
DOORS	.7092	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	1.5037	EXTERIOR PAINT APPLIED
ENGINE	29.1023	ELECTRICAL WIRING INSTALLED
FUEL TANK / EXHAUST	.1043	EXTERIOR MOLDINGS INSTALLED
HOOD/FRONT END COMP.	.1726	AIR CONDITIONING AND HEATER INSTALLED
RADIATOR & GRILLE	.0007	INSTRUMENT PANEL INSTALLED
REAR AXLE/SUSPENSION	.2192	DOOR HARDWARE AND WINDOWS INSTALLED
ROOF	.0034	INTERIOR TRIM & FLOOR COVERING INSTALLED
SEATS	1.2229	SEATS INSTALLED
STEERING	.0012	SUB FRAME AND ENGINE INSTALLED
TRANSMISSION	.0029	TRANSMISSION INSTALLED
UNDER BODY	.1173	TIRES MOUNTED AND INSTALLED
WHEELS & TIRES	.0002	VEHICLE TESTED AND INSPECTED
TOTAL US CONTENT	34.0703	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL TXL26
 GMC TERRAIN D2
 CARLINE X
 ASSEMBLY LOC: SAN LUIS POTOSI, MEXICO

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	.0395	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	.1409	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	.0094	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	1.1091	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.0703	FRONT AND REAR DOORS INSTALLED
DOORS	.3175	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	.6747	EXTERIOR PAINT APPLIED
ENGINE	16.3712	ELECTRICAL WIRING INSTALLED
FRT AXLE/SUSPENSION	.0190	EXTERIOR MOLDINGS INSTALLED
FUEL TANK / EXHAUST	.1009	AIR CONDITIONING AND HEATER INSTALLED
HOOD/FRONT END COMP.	.2636	INSTRUMENT PANEL INSTALLED
RADIATOR & GRILLE	.0027	DOOR HARDWARE AND WINDOWS INSTALLED
REAR AXLE/SUSPENSION	.3065	INTERIOR TRIM & FLOOR COVERING INSTALLED
ROOF	.0059	SEATS INSTALLED
SEATS	.0161	SUB FRAME AND ENGINE INSTALLED
STEERING	.0059	TRANSMISSION INSTALLED
TRANSMISSION	.0102	TIRES MOUNTED AND INSTALLED
UNDER BODY	.1869	VEHICLE TESTED AND INSPECTED
WHEELS & TIRES	.1152	FINISHED VEHICLE SHIPPED
TOTAL US CONTENT	19.7664	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/17

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL C25743
 K2XX HD SILVERADO/SIERRA - CREW CAB
 CARLINE 06
 ASSEMBLY LOC: FLINT, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.6299	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP. FRAMING	3.5976	SIDE AND OUTER PANELS WELDED TO
BODY SIDE & REAR PANELS INSTALLED	2.7155	WINDSHIELD REINFORCEMENTS AND ROOF
BRAKES	3.7139	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.4886	FRONT AND REAR DOORS INSTALLED
COMM. BODY EQUIP	.0073	BODY PRIMED AND SEALED
DOORS	4.8702	EXTERIOR PAINT APPLIED
ELECT SYS & INST PNL	2.6228	ELECTRICAL WIRING INSTALLED
ENGINE	4.8881	EXTERIOR MOLDINGS INSTALLED
FRAME INSTALLED	.1177	AIR CONDITIONING AND HEATER
FRT AXLE/SUSPENSION	1.4286	INSTRUMENT PANEL INSTALLED
FUEL TANK / EXHAUST INSTALLED	2.5550	DOOR HARDWARE AND WINDOWS
HOOD/FRONT END COMP. INSTALLED	1.8832	INTERIOR TRIM & FLOOR COVERING
RADIATOR & GRILLE	1.3341	SEATS INSTALLED
REAR AXLE/SUSPENSION	7.5934	SUB FRAME AND ENGINE INSTALLED
ROOF	.6578	TRANSMISSION INSTALLED
SEATS	5.9098	TIRES MOUNTED AND INSTALLED
STEERING	3.3429	VEHICLE TESTED AND INSPECTED
TRANSMISSION	7.2062	FINISHED VEHICLE SHIPPED
UNDER BODY	2.0265	
WHEELS & TIRES	2.7857	
TOTAL US CONTENT	62.3759	

COST OF FINAL ASSEMBLY: \$3,146.00

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL C25753
 K2XX HD SILVERADO/SIERRA - EXT CAB
 CARLINE 06
 ASSEMBLY LOC: FORT WAYNE, INDIANA U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.7843	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP. FRAMING	3.7102	SIDE AND OUTER PANELS WELDED TO
BODY SIDE & REAR PANELS INSTALLED	2.9412	WINDSHIELD REINFORCEMENTS AND ROOF
BRAKES	4.1545	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.5744	FRONT AND REAR DOORS INSTALLED
COMM. BODY EQUIP	.0080	BODY PRIMED AND SEALED
DOORS	4.9166	EXTERIOR PAINT APPLIED
ELECT SYS & INST PNL	2.5649	ELECTRICAL WIRING INSTALLED
ENGINE	.6968	EXTERIOR MOLDINGS INSTALLED
FRAME INSTALLED	.1296	AIR CONDITIONING AND HEATER
FRT AXLE/SUSPENSION	1.7676	INSTRUMENT PANEL INSTALLED
FUEL TANK / EXHAUST INSTALLED	3.0697	DOOR HARDWARE AND WINDOWS
HOOD/FRONT END COMP. INSTALLED	2.0316	INTERIOR TRIM & FLOOR COVERING
RADIATOR & GRILLE	1.3667	SEATS INSTALLED
REAR AXLE/SUSPENSION	8.0608	SUB FRAME AND ENGINE INSTALLED
ROOF	.5572	TRANSMISSION INSTALLED
SEATS	2.8414	TIRES MOUNTED AND INSTALLED
STEERING	3.5900	VEHICLE TESTED AND INSPECTED
TRANSMISSION	7.5910	FINISHED VEHICLE SHIPPED
UNDER BODY	2.0250	
WHEELS & TIRES	2.9143	
TOTAL US CONTENT	58.2966	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL C25903
 K2XX HD SILVERADO/SIERRA - REG CAB
 CARLINE 06
 ASSEMBLY LOC: FORT WAYNE, INDIANA U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.7550	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP. FRAMING	3.7566	SIDE AND OUTER PANELS WELDED TO
BODY SIDE & REAR PANELS INSTALLED	2.9913	WINDSHIELD REINFORCEMENTS AND ROOF
BRAKES	4.6028	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.6681	FRONT AND REAR DOORS INSTALLED
COMM. BODY EQUIP	.0085	BODY PRIMED AND SEALED
DOORS	3.1092	EXTERIOR PAINT APPLIED
ELECT SYS & INST PNL	2.9005	ELECTRICAL WIRING INSTALLED
ENGINE	.7924	EXTERIOR MOLDINGS INSTALLED
FRAME INSTALLED	.1422	AIR CONDITIONING AND HEATER
FRT AXLE/SUSPENSION	1.9385	INSTRUMENT PANEL INSTALLED
FUEL TANK / EXHAUST INSTALLED	3.3524	DOOR HARDWARE AND WINDOWS
HOOD/FRONT END COMP. INSTALLED	2.2365	INTERIOR TRIM & FLOOR COVERING
RADIATOR & GRILLE	1.4978	SEATS INSTALLED
REAR AXLE/SUSPENSION	8.8400	SUB FRAME AND ENGINE INSTALLED
ROOF	.3828	TRANSMISSION INSTALLED
SEATS	.1506	TIRES MOUNTED AND INSTALLED
STEERING	3.8369	VEHICLE TESTED AND INSPECTED
TRANSMISSION	8.3248	FINISHED VEHICLE SHIPPED
UNDER BODY	1.3516	
WHEELS & TIRES	3.1372	
TOTAL US CONTENT	56.7767	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL C25943
 K2XX HD SILVERADO/SIERRA - CREW CAB
 CARLINE 06
 ASSEMBLY LOC: FLINT, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.6732	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP. FRAMING	3.7140	SIDE AND OUTER PANELS WELDED TO
BODY SIDE & REAR PANELS INSTALLED	2.8361	WINDSHIELD REINFORCEMENTS AND ROOF
BRAKES	3.8907	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.3753	FRONT AND REAR DOORS INSTALLED
COMM. BODY EQUIP	.0069	BODY PRIMED AND SEALED
DOORS	4.8272	EXTERIOR PAINT APPLIED
ELECT SYS & INST PNL	2.4015	ELECTRICAL WIRING INSTALLED
ENGINE	5.4151	EXTERIOR MOLDINGS INSTALLED
FRAME INSTALLED	.1227	AIR CONDITIONING AND HEATER
FRT AXLE/SUSPENSION	1.4897	INSTRUMENT PANEL INSTALLED
FUEL TANK / EXHAUST INSTALLED	2.6544	DOOR HARDWARE AND WINDOWS
HOOD/FRONT END COMP. INSTALLED	1.9466	INTERIOR TRIM & FLOOR COVERING
RADIATOR & GRILLE	1.3884	SEATS INSTALLED
REAR AXLE/SUSPENSION	7.9338	SUB FRAME AND ENGINE INSTALLED
ROOF	.6536	TRANSMISSION INSTALLED
SEATS	5.7899	TIRES MOUNTED AND INSTALLED
STEERING	3.3314	VEHICLE TESTED AND INSPECTED
TRANSMISSION	7.5337	FINISHED VEHICLE SHIPPED
UNDER BODY	1.6559	
WHEELS & TIRES	2.7145	
TOTAL US CONTENT	63.3557	

COST OF FINAL ASSEMBLY: \$3,129.00

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL C25953
 K2XX HD SILVERADO/SIERRA - EXT CAB
 CARLINE 06
 ASSEMBLY LOC: FORT WAYNE, INDIANA U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.7138	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP. FRAMING	4.1192	SIDE AND OUTER PANELS WELDED TO
BODY SIDE & REAR PANELS INSTALLED	2.0141	WINDSHIELD REINFORCEMENTS AND ROOF
BRAKES	4.5294	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.2175	FRONT AND REAR DOORS INSTALLED
DOORS	4.4705	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	3.2122	EXTERIOR PAINT APPLIED
ENGINE	.6057	ELECTRICAL WIRING INSTALLED
FRAME	.1380	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION INSTALLED	1.8820	AIR CONDITIONING AND HEATER
FUEL TANK / EXHAUST	3.5612	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP. INSTALLED	2.1690	DOOR HARDWARE AND WINDOWS
RADIATOR & GRILLE INSTALLED	1.4549	INTERIOR TRIM & FLOOR COVERING
REAR AXLE/SUSPENSION	8.5828	SEATS INSTALLED
ROOF	.5932	SUB FRAME AND ENGINE INSTALLED
SEATS	.1847	TRANSMISSION INSTALLED
STEERING	3.6715	TIRES MOUNTED AND INSTALLED
TRANSMISSION	8.0824	VEHICLE TESTED AND INSPECTED
UNDER BODY	1.5570	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	2.7751	
TOTAL US CONTENT	55.5352	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL C35743
 K2XX HD SILVERADO/SIERRA - CREW CAB
 CARLINE 06
 ASSEMBLY LOC: FLINT, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.5820	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP. FRAMING	3.5359	SIDE AND OUTER PANELS WELDED TO
BODY SIDE & REAR PANELS INSTALLED	2.6311	WINDSHIELD REINFORCEMENTS AND ROOF
BRAKES	3.6093	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.4439	FRONT AND REAR DOORS INSTALLED
COMM. BODY EQUIP	.0071	BODY PRIMED AND SEALED
DOORS	4.6828	EXTERIOR PAINT APPLIED
ELECT SYS & INST PNL	2.6366	ELECTRICAL WIRING INSTALLED
ENGINE	5.5451	EXTERIOR MOLDINGS INSTALLED
FRAME INSTALLED	.1141	AIR CONDITIONING AND HEATER
FRT AXLE/SUSPENSION	1.3876	INSTRUMENT PANEL INSTALLED
FUEL TANK / EXHAUST INSTALLED	2.4696	DOOR HARDWARE AND WINDOWS
HOOD/FRONT END COMP. INSTALLED	1.8307	INTERIOR TRIM & FLOOR COVERING
RADIATOR & GRILLE	1.3152	SEATS INSTALLED
REAR AXLE/SUSPENSION	9.0287	SUB FRAME AND ENGINE INSTALLED
ROOF	.7067	TRANSMISSION INSTALLED
SEATS	5.9139	TIRES MOUNTED AND INSTALLED
STEERING	3.4837	VEHICLE TESTED AND INSPECTED
TRANSMISSION	7.0804	FINISHED VEHICLE SHIPPED
UNDER BODY	1.9045	
WHEELS & TIRES	4.4817	
TOTAL US CONTENT	65.3915	

COST OF FINAL ASSEMBLY: \$3,158.00

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL C35903
 K2XX HD SILVERADO/SIERRA - REG CAB
 CARLINE 06
 ASSEMBLY LOC: FORT WAYNE, INDIANA U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.6801	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP. FRAMING	3.6422	SIDE AND OUTER PANELS WELDED TO
BODY SIDE & REAR PANELS INSTALLED	2.8733	WINDSHIELD REINFORCEMENTS AND ROOF
BRAKES	4.4792	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.6189	FRONT AND REAR DOORS INSTALLED
COMM. BODY EQUIP	.0083	BODY PRIMED AND SEALED
DOORS	2.9635	EXTERIOR PAINT APPLIED
ELECT SYS & INST PNL	2.8786	ELECTRICAL WIRING INSTALLED
ENGINE	.7562	EXTERIOR MOLDINGS INSTALLED
FRAME	.1357	AIR CONDITIONING AND HEATER
INSTALLED		
FRT AXLE/SUSPENSION	1.8506	INSTRUMENT PANEL INSTALLED
FUEL TANK / EXHAUST INSTALLED	3.2755	DOOR HARDWARE AND WINDOWS
HOOD/FRONT END COMP. INSTALLED	2.1247	INTERIOR TRIM & FLOOR COVERING
RADIATOR & GRILLE	1.4305	SEATS INSTALLED
REAR AXLE/SUSPENSION	10.6129	SUB FRAME AND ENGINE INSTALLED
ROOF	.3654	TRANSMISSION INSTALLED
SEATS	.1495	TIRES MOUNTED AND INSTALLED
STEERING	3.6197	VEHICLE TESTED AND INSPECTED
TRANSMISSION	7.9475	FINISHED VEHICLE SHIPPED
UNDER BODY	1.2036	
WHEELS & TIRES	5.5835	
TOTAL US CONTENT	59.2006	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL C35943
 K2XX HD SILVERADO/SIERRA - CREW CAB
 CARLINE 06
 ASSEMBLY LOC: FLINT, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.3888	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP. FRAMING	3.3591	SIDE AND OUTER PANELS WELDED TO
BODY SIDE & REAR PANELS INSTALLED	2.1598	WINDSHIELD REINFORCEMENTS AND ROOF
BRAKES	3.3554	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.2700	FRONT AND REAR DOORS INSTALLED
COMM. BODY EQUIP	.0054	BODY PRIMED AND SEALED
DOORS	4.1475	EXTERIOR PAINT APPLIED
ELECT SYS & INST PNL	2.3884	ELECTRICAL WIRING INSTALLED
ENGINE	12.5492	EXTERIOR MOLDINGS INSTALLED
FRAME	.1007	AIR CONDITIONING AND HEATER
INSTALLED		
FRT AXLE/SUSPENSION	1.2493	INSTRUMENT PANEL INSTALLED
FUEL TANK / EXHAUST INSTALLED	1.7580	DOOR HARDWARE AND WINDOWS
HOOD/FRONT END COMP. INSTALLED	1.6512	INTERIOR TRIM & FLOOR COVERING
RADIATOR & GRILLE	1.3156	SEATS INSTALLED
REAR AXLE/SUSPENSION	8.3606	SUB FRAME AND ENGINE INSTALLED
ROOF	.6043	TRANSMISSION INSTALLED
SEATS	5.1090	TIRES MOUNTED AND INSTALLED
STEERING	2.7870	VEHICLE TESTED AND INSPECTED
TRANSMISSION	6.8662	FINISHED VEHICLE SHIPPED
UNDER BODY	2.0373	
WHEELS & TIRES	3.7348	
TOTAL US CONTENT	66.1985	

COST OF FINAL ASSEMBLY: \$3,204.00

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL C35953
 K2XX HD SILVERADO/SIERRA - EXT CAB
 CARLINE 06
 ASSEMBLY LOC: FORT WAYNE, INDIANA U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.6554	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP. FRAMING	3.8701	SIDE AND OUTER PANELS WELDED TO
BODY SIDE & REAR PANELS INSTALLED	2.0498	WINDSHIELD REINFORCEMENTS AND ROOF
BRAKES	4.3037	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.5437	FRONT AND REAR DOORS INSTALLED
COMM. BODY EQUIP	.0020	BODY PRIMED AND SEALED
DOORS	4.3731	EXTERIOR PAINT APPLIED
ELECT SYS & INST PNL	3.1163	ELECTRICAL WIRING INSTALLED
ENGINE	.7107	EXTERIOR MOLDINGS INSTALLED
FRAME INSTALLED	.1305	AIR CONDITIONING AND HEATER
FRT AXLE/SUSPENSION	1.7795	INSTRUMENT PANEL INSTALLED
FUEL TANK / EXHAUST INSTALLED	3.3539	DOOR HARDWARE AND WINDOWS
HOOD/FRONT END COMP. INSTALLED	2.0542	INTERIOR TRIM & FLOOR COVERING
RADIATOR & GRILLE	1.3754	SEATS INSTALLED
REAR AXLE/SUSPENSION	10.2051	SUB FRAME AND ENGINE INSTALLED
ROOF	.5609	TRANSMISSION INSTALLED
SEATS	.1520	TIRES MOUNTED AND INSTALLED
STEERING	3.4506	VEHICLE TESTED AND INSPECTED
TRANSMISSION	7.6419	FINISHED VEHICLE SHIPPED
UNDER BODY	1.6490	
WHEELS & TIRES	5.0937	
TOTAL US CONTENT	58.0725	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL C36043
 K2XX HD SILVERADO/SIERRA - CREW CAB
 CARLINE 06
 ASSEMBLY LOC: FLINT, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.1195	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP. FRAMING	2.8253	SIDE AND OUTER PANELS WELDED TO
BODY SIDE & REAR PANELS INSTALLED	1.3880	WINDSHIELD REINFORCEMENTS AND ROOF
BRAKES	3.2368	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.1461	FRONT AND REAR DOORS INSTALLED
DOORS	3.2697	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	2.1342	EXTERIOR PAINT APPLIED
ENGINE	23.5801	ELECTRICAL WIRING INSTALLED
FRAME	.0883	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION INSTALLED	1.1375	AIR CONDITIONING AND HEATER
FUEL TANK / EXHAUST	.8724	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP. INSTALLED	1.5307	DOOR HARDWARE AND WINDOWS
RADIATOR & GRILLE INSTALLED	1.3923	INTERIOR TRIM & FLOOR COVERING
REAR AXLE/SUSPENSION	7.6285	SEATS INSTALLED
ROOF	.5001	SUB FRAME AND ENGINE INSTALLED
SEATS	4.1935	TRANSMISSION INSTALLED
STEERING	2.5115	TIRES MOUNTED AND INSTALLED
TRANSMISSION	7.0471	VEHICLE TESTED AND INSPECTED
UNDER BODY	1.1235	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	2.1160	
TOTAL US CONTENT	67.8422	

COST OF FINAL ASSEMBLY: \$3,249.00

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL C36403
 K2XX HD SILVERADO/SIERRA - REG CAB
 CARLINE 06
 ASSEMBLY LOC: FLINT, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.2716	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP. FRAMING	3.4731	SIDE AND OUTER PANELS WELDED TO
BODY SIDE & REAR PANELS INSTALLED	1.4697	WINDSHIELD REINFORCEMENTS AND ROOF
BRAKES	4.1358	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.1924	FRONT AND REAR DOORS INSTALLED
DOORS	2.1541	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	2.8544	EXTERIOR PAINT APPLIED
ENGINE	9.0724	ELECTRICAL WIRING INSTALLED
FRAME	.1185	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION INSTALLED	1.4523	AIR CONDITIONING AND HEATER
FUEL TANK / EXHAUST	3.5629	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP. INSTALLED	1.9193	DOOR HARDWARE AND WINDOWS
RADIATOR & GRILLE INSTALLED	1.4170	INTERIOR TRIM & FLOOR COVERING
REAR AXLE/SUSPENSION	9.7753	SEATS INSTALLED
ROOF	.3254	SUB FRAME AND ENGINE INSTALLED
SEATS	3.5188	TRANSMISSION INSTALLED
STEERING	3.2089	TIRES MOUNTED AND INSTALLED
TRANSMISSION	7.6254	VEHICLE TESTED AND INSPECTED
UNDER BODY	.9373	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	3.1057	
TOTAL US CONTENT	61.5914	

COST OF FINAL ASSEMBLY: \$3,139.00

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL K25903
 K2XX HD SILVERADO/SIERRA - REG CAB
 CARLINE 06
 ASSEMBLY LOC: FORT WAYNE, INDIANA U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.5984	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP. FRAMING	3.5864	SIDE AND OUTER PANELS WELDED TO
BODY SIDE & REAR PANELS INSTALLED	2.7628	WINDSHIELD REINFORCEMENTS AND ROOF
BRAKES	4.0547	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.5198	FRONT AND REAR DOORS INSTALLED
COMM. BODY EQUIP	.0078	BODY PRIMED AND SEALED
DOORS	3.0302	EXTERIOR PAINT APPLIED
ELECT SYS & INST PNL	2.7460	ELECTRICAL WIRING INSTALLED
ENGINE	.8036	EXTERIOR MOLDINGS INSTALLED
FRAME INSTALLED	.1199	AIR CONDITIONING AND HEATER
FRT AXLE/SUSPENSION	5.7177	INSTRUMENT PANEL INSTALLED
FUEL TANK / EXHAUST INSTALLED	3.0147	DOOR HARDWARE AND WINDOWS
HOOD/FRONT END COMP. INSTALLED	2.1334	INTERIOR TRIM & FLOOR COVERING
RADIATOR & GRILLE	1.3471	SEATS INSTALLED
REAR AXLE/SUSPENSION	7.9627	SUB FRAME AND ENGINE INSTALLED
ROOF	.3447	TRANSMISSION INSTALLED
SEATS	.1371	TIRES MOUNTED AND INSTALLED
STEERING	3.5874	VEHICLE TESTED AND INSPECTED
TRANSMISSION	9.6354	FINISHED VEHICLE SHIPPED
UNDER BODY	1.4117	
WHEELS & TIRES	2.7960	
TOTAL US CONTENT	58.3188	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL K25943
 K2XX HD SILVERADO/SIERRA - CREW CAB
 CARLINE 06
 ASSEMBLY LOC: FLINT, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.3810	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP. FRAMING	3.0899	SIDE AND OUTER PANELS WELDED TO
BODY SIDE & REAR PANELS INSTALLED	2.3650	WINDSHIELD REINFORCEMENTS AND ROOF
BRAKES	3.0837	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.3155	FRONT AND REAR DOORS INSTALLED
COMM. BODY EQUIP	.0060	BODY PRIMED AND SEALED
DOORS	4.0720	EXTERIOR PAINT APPLIED
ELECT SYS & INST PNL	2.2682	ELECTRICAL WIRING INSTALLED
ENGINE	12.6578	EXTERIOR MOLDINGS INSTALLED
FRAME INSTALLED	.0927	AIR CONDITIONING AND HEATER
FRT AXLE/SUSPENSION	4.2611	INSTRUMENT PANEL INSTALLED
FUEL TANK / EXHAUST INSTALLED	1.5930	DOOR HARDWARE AND WINDOWS
HOOD/FRONT END COMP. INSTALLED	1.5852	INTERIOR TRIM & FLOOR COVERING
RADIATOR & GRILLE	1.2559	SEATS INSTALLED
REAR AXLE/SUSPENSION	6.7327	SUB FRAME AND ENGINE INSTALLED
ROOF	.5626	TRANSMISSION INSTALLED
SEATS	5.0164	TIRES MOUNTED AND INSTALLED
STEERING	2.8158	VEHICLE TESTED AND INSPECTED
TRANSMISSION	7.4832	FINISHED VEHICLE SHIPPED
UNDER BODY	2.1127	
WHEELS & TIRES	2.3632	
TOTAL US CONTENT	66.1146	

COST OF FINAL ASSEMBLY: \$3,227.00

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL K35903
 K2XX HD SILVERADO/SIERRA - REG CAB
 CARLINE 06
 ASSEMBLY LOC: FORT WAYNE, INDIANA U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.5286	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP. FRAMING	3.7694	SIDE AND OUTER PANELS WELDED TO
BODY SIDE & REAR PANELS INSTALLED	2.6509	WINDSHIELD REINFORCEMENTS AND ROOF
BRAKES	3.8772	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.5761	FRONT AND REAR DOORS INSTALLED
COMM. BODY EQUIP	.0075	BODY PRIMED AND SEALED
DOORS	2.9543	EXTERIOR PAINT APPLIED
ELECT SYS & INST PNL	2.6889	ELECTRICAL WIRING INSTALLED
ENGINE	.7795	EXTERIOR MOLDINGS INSTALLED
FRAME INSTALLED	.1147	AIR CONDITIONING AND HEATER
FRT AXLE/SUSPENSION	5.4678	INSTRUMENT PANEL INSTALLED
FUEL TANK / EXHAUST INSTALLED	2.9019	DOOR HARDWARE AND WINDOWS
HOOD/FRONT END COMP. INSTALLED	2.0433	INTERIOR TRIM & FLOOR COVERING
RADIATOR & GRILLE	1.2882	SEATS INSTALLED
REAR AXLE/SUSPENSION	9.5736	SUB FRAME AND ENGINE INSTALLED
ROOF	.3296	TRANSMISSION INSTALLED
SEATS	.1361	TIRES MOUNTED AND INSTALLED
STEERING	3.4226	VEHICLE TESTED AND INSPECTED
TRANSMISSION	9.2363	FINISHED VEHICLE SHIPPED
UNDER BODY	1.7303	
WHEELS & TIRES	2.8515	
TOTAL US CONTENT	58.9293	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL K35953
 K2XX HD SILVERADO/SIERRA - EXT CAB
 CARLINE 06
 ASSEMBLY LOC: FORT WAYNE, INDIANA U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	3.0608	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP. FRAMING	4.3619	SIDE AND OUTER PANELS WELDED TO
BODY SIDE & REAR PANELS INSTALLED	2.2268	WINDSHIELD REINFORCEMENTS AND ROOF
BRAKES	3.7667	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.7182	FRONT AND REAR DOORS INSTALLED
COMM. BODY EQUIP	.0068	BODY PRIMED AND SEALED
DOORS	4.3431	EXTERIOR PAINT APPLIED
ELECT SYS & INST PNL	1.4572	ELECTRICAL WIRING INSTALLED
ENGINE	-.6681	EXTERIOR MOLDINGS INSTALLED
FRAME INSTALLED	.1043	AIR CONDITIONING AND HEATER
FRT AXLE/SUSPENSION	4.9722	INSTRUMENT PANEL INSTALLED
FUEL TANK / EXHAUST INSTALLED	2.6564	DOOR HARDWARE AND WINDOWS
HOOD/FRONT END COMP. INSTALLED	1.7606	INTERIOR TRIM & FLOOR COVERING
RADIATOR & GRILLE	1.3483	SEATS INSTALLED
REAR AXLE/SUSPENSION	8.7088	SUB FRAME AND ENGINE INSTALLED
ROOF	.4789	TRANSMISSION INSTALLED
SEATS	.1320	TIRES MOUNTED AND INSTALLED
STEERING	2.9252	VEHICLE TESTED AND INSPECTED
TRANSMISSION	7.7709	FINISHED VEHICLE SHIPPED
UNDER BODY	2.8723	
WHEELS & TIRES	3.2856	
TOTAL US CONTENT	57.2898	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL K36003
 K2XX HD SILVERADO/SIERRA - CHASSIS CAB
 CARLINE 06
 ASSEMBLY LOC: FLINT, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	.9790	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP. FRAMING	2.5154	SIDE AND OUTER PANELS WELDED TO
BODY SIDE & REAR PANELS INSTALLED	1.0967	WINDSHIELD REINFORCEMENTS AND ROOF
BRAKES	3.1199	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.1111	FRONT AND REAR DOORS INSTALLED
DOORS	1.6765	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	2.2055	EXTERIOR PAINT APPLIED
ENGINE	27.4351	ELECTRICAL WIRING INSTALLED
FRAME	.0844	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION INSTALLED	3.8794	AIR CONDITIONING AND HEATER
FUEL TANK / EXHAUST	3.7420	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP. INSTALLED	1.4833	DOOR HARDWARE AND WINDOWS
RADIATOR & GRILLE INSTALLED	1.4085	INTERIOR TRIM & FLOOR COVERING
REAR AXLE/SUSPENSION	7.2498	SEATS INSTALLED
ROOF	.2425	SUB FRAME AND ENGINE INSTALLED
SEATS	2.6036	TRANSMISSION INSTALLED
STEERING	2.3895	TIRES MOUNTED AND INSTALLED
TRANSMISSION	8.4892	VEHICLE TESTED AND INSPECTED
UNDER BODY	.7276	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	1.0471	
TOTAL US CONTENT	72.4870	

COST OF FINAL ASSEMBLY: \$3,275.00

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL K36043
 K2XX HD SILVERADO/SIERRA - CREW CAB
 CARLINE 06
 ASSEMBLY LOC: FLINT, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.0617	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP. FRAMING	2.5829	SIDE AND OUTER PANELS WELDED TO
BODY SIDE & REAR PANELS INSTALLED	1.2815	WINDSHIELD REINFORCEMENTS AND ROOF
BRAKES	2.9833	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.0928	FRONT AND REAR DOORS INSTALLED
DOORS	3.0269	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	2.0372	EXTERIOR PAINT APPLIED
ENGINE	24.2183	ELECTRICAL WIRING INSTALLED
FRAME	.0817	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION INSTALLED	3.7583	AIR CONDITIONING AND HEATER
FUEL TANK / EXHAUST	.6379	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP. INSTALLED	1.4219	DOOR HARDWARE AND WINDOWS
RADIATOR & GRILLE INSTALLED	1.3251	INTERIOR TRIM & FLOOR COVERING
REAR AXLE/SUSPENSION	7.0275	SEATS INSTALLED
ROOF	.4610	SUB FRAME AND ENGINE INSTALLED
SEATS	3.9396	TRANSMISSION INSTALLED
STEERING	2.2939	TIRES MOUNTED AND INSTALLED
TRANSMISSION	7.9465	VEHICLE TESTED AND INSPECTED
UNDER BODY	1.0340	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	1.0897	
TOTAL US CONTENT	68.3027	

COST OF FINAL ASSEMBLY: \$3,293.00

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL K36403
 K2XX HD SILVERADO/SIERRA - REG CAB
 CARLINE 06
 ASSEMBLY LOC: FLINT, MICHIGAN U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.1846	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP. FRAMING	3.3105	SIDE AND OUTER PANELS WELDED TO
BODY SIDE & REAR PANELS INSTALLED	1.3296	WINDSHIELD REINFORCEMENTS AND ROOF
BRAKES	3.7403	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	.1188	FRONT AND REAR DOORS INSTALLED
DOORS	2.0626	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	2.5628	EXTERIOR PAINT APPLIED
ENGINE	10.9265	ELECTRICAL WIRING INSTALLED
FRAME	.1024	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION INSTALLED	4.7086	AIR CONDITIONING AND HEATER
FUEL TANK / EXHAUST	3.3628	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP. INSTALLED	1.7452	DOOR HARDWARE AND WINDOWS
RADIATOR & GRILLE INSTALLED	1.3248	INTERIOR TRIM & FLOOR COVERING
REAR AXLE/SUSPENSION	8.8376	SEATS INSTALLED
ROOF	.2943	SUB FRAME AND ENGINE INSTALLED
SEATS	3.2148	TRANSMISSION INSTALLED
STEERING	2.9050	TIRES MOUNTED AND INSTALLED
TRANSMISSION	8.6782	VEHICLE TESTED AND INSPECTED
UNDER BODY	.8498	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	1.7290	
TOTAL US CONTENT	62.9892	

COST OF FINAL ASSEMBLY: \$3,181.00

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL T2M43
 GMC CANYON
 CARLINE 52

ASSEMBLY LOC: WENTZVILLE, MISSOURI U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.7007	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP. FRAMING	1.6117	SIDE AND OUTER PANELS WELDED TO
BODY SIDE & REAR PANELS INSTALLED	3.3464	WINDSHIELD REINFORCEMENTS AND ROOF
BRAKES	1.9375	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	2.3964	FRONT AND REAR DOORS INSTALLED
COMM. BODY EQUIP	.0091	BODY PRIMED AND SEALED
DOORS	3.9719	EXTERIOR PAINT APPLIED
ELECT SYS & INST PNL	1.5442	ELECTRICAL WIRING INSTALLED
ENGINE	15.4539	EXTERIOR MOLDINGS INSTALLED
FRAME INSTALLED	3.2859	AIR CONDITIONING AND HEATER
FRT AXLE/SUSPENSION	.3993	INSTRUMENT PANEL INSTALLED
FUEL TANK / EXHAUST INSTALLED	.8997	DOOR HARDWARE AND WINDOWS
HOOD/FRONT END COMP. INSTALLED	2.0420	INTERIOR TRIM & FLOOR COVERING
RADIATOR & GRILLE	2.0765	SEATS INSTALLED
REAR AXLE/SUSPENSION	3.8526	SUB FRAME AND ENGINE INSTALLED
ROOF	.6407	TRANSMISSION INSTALLED
SEATS	2.1847	TIRES MOUNTED AND INSTALLED
STEERING	.1576	VEHICLE TESTED AND INSPECTED
TRANSMISSION	.1840	FINISHED VEHICLE SHIPPED
UNDER BODY	3.0490	
WHEELS & TIRES	2.8807	
TOTAL US CONTENT	53.6257	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL T2M53
 GMC CANYON
 CARLINE 52

ASSEMBLY LOC: WENTZVILLE, MISSOURI U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.6551	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP. FRAMING	1.5136	SIDE AND OUTER PANELS WELDED TO
BODY SIDE & REAR PANELS INSTALLED	3.3126	WINDSHIELD REINFORCEMENTS AND ROOF
BRAKES	1.9371	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	2.3563	FRONT AND REAR DOORS INSTALLED
COMM. BODY EQUIP	.0088	BODY PRIMED AND SEALED
DOORS	3.7163	EXTERIOR PAINT APPLIED
ELECT SYS & INST PNL	1.6476	ELECTRICAL WIRING INSTALLED
ENGINE	15.4766	EXTERIOR MOLDINGS INSTALLED
FRAME INSTALLED	3.3104	AIR CONDITIONING AND HEATER
FRT AXLE/SUSPENSION	.7851	INSTRUMENT PANEL INSTALLED
FUEL TANK / EXHAUST INSTALLED	.9753	DOOR HARDWARE AND WINDOWS
HOOD/FRONT END COMP. INSTALLED	1.9245	INTERIOR TRIM & FLOOR COVERING
RADIATOR & GRILLE	2.0980	SEATS INSTALLED
REAR AXLE/SUSPENSION	3.3115	SUB FRAME AND ENGINE INSTALLED
ROOF	.5170	TRANSMISSION INSTALLED
SEATS	2.6072	TIRES MOUNTED AND INSTALLED
STEERING	.1577	VEHICLE TESTED AND INSPECTED
TRANSMISSION	.2694	FINISHED VEHICLE SHIPPED
UNDER BODY	2.9873	
WHEELS & TIRES	2.8691	
TOTAL US CONTENT	53.4376	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL T2N43
 GMC CANYON
 CARLINE 52

ASSEMBLY LOC: WENTZVILLE, MISSOURI U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.4908	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP. FRAMING	2.0197	SIDE AND OUTER PANELS WELDED TO
BODY SIDE & REAR PANELS INSTALLED	3.0213	WINDSHIELD REINFORCEMENTS AND ROOF
BRAKES	1.6646	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	2.2140	FRONT AND REAR DOORS INSTALLED
COMM. BODY EQUIP	.0078	BODY PRIMED AND SEALED
DOORS	3.9363	EXTERIOR PAINT APPLIED
ELECT SYS & INST PNL	2.4948	ELECTRICAL WIRING INSTALLED
ENGINE	12.2851	EXTERIOR MOLDINGS INSTALLED
FRAME INSTALLED	2.8384	AIR CONDITIONING AND HEATER
FRT AXLE/SUSPENSION	1.0499	INSTRUMENT PANEL INSTALLED
FUEL TANK / EXHAUST INSTALLED	1.5335	DOOR HARDWARE AND WINDOWS
HOOD/FRONT END COMP. INSTALLED	1.8162	INTERIOR TRIM & FLOOR COVERING
RADIATOR & GRILLE	1.6551	SEATS INSTALLED
REAR AXLE/SUSPENSION	1.3024	SUB FRAME AND ENGINE INSTALLED
ROOF	.5691	TRANSMISSION INSTALLED
SEATS	1.2070	TIRES MOUNTED AND INSTALLED
STEERING	.6612	VEHICLE TESTED AND INSPECTED
TRANSMISSION	.2104	FINISHED VEHICLE SHIPPED
UNDER BODY	2.9447	
WHEELS & TIRES	2.4820	
TOTAL US CONTENT	47.4053	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL T2N53
 GMC CANYON
 CARLINE 52

ASSEMBLY LOC: WENTZVILLE, MISSOURI U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.5401	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP. FRAMING	2.0081	SIDE AND OUTER PANELS WELDED TO
BODY SIDE & REAR PANELS INSTALLED	3.3161	WINDSHIELD REINFORCEMENTS AND ROOF
BRAKES	1.7386	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	2.3782	FRONT AND REAR DOORS INSTALLED
COMM. BODY EQUIP	.0082	BODY PRIMED AND SEALED
DOORS	3.7576	EXTERIOR PAINT APPLIED
ELECT SYS & INST PNL	2.7234	ELECTRICAL WIRING INSTALLED
ENGINE	14.3539	EXTERIOR MOLDINGS INSTALLED
FRAME INSTALLED	2.9972	AIR CONDITIONING AND HEATER
FRT AXLE/SUSPENSION	1.1521	INSTRUMENT PANEL INSTALLED
FUEL TANK / EXHAUST INSTALLED	.6129	DOOR HARDWARE AND WINDOWS
HOOD/FRONT END COMP. INSTALLED	1.7847	INTERIOR TRIM & FLOOR COVERING
RADIATOR & GRILLE	1.8764	SEATS INSTALLED
REAR AXLE/SUSPENSION	1.6103	SUB FRAME AND ENGINE INSTALLED
ROOF	.4864	TRANSMISSION INSTALLED
SEATS	2.4214	TIRES MOUNTED AND INSTALLED
STEERING	.6971	VEHICLE TESTED AND INSPECTED
TRANSMISSION	.2074	FINISHED VEHICLE SHIPPED
UNDER BODY	2.9532	
WHEELS & TIRES	2.5911	
TOTAL US CONTENT	51.2154	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL T2P53
 GMC CANYON
 CARLINE 52

ASSEMBLY LOC: WENTZVILLE, MISSOURI U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.4362	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP. FRAMING	1.9364	SIDE AND OUTER PANELS WELDED TO
BODY SIDE & REAR PANELS INSTALLED	3.1597	WINDSHIELD REINFORCEMENTS AND ROOF
BRAKES	1.6276	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	2.6429	FRONT AND REAR DOORS INSTALLED
COMM. BODY EQUIP	.0077	BODY PRIMED AND SEALED
DOORS	3.5251	EXTERIOR PAINT APPLIED
ELECT SYS & INST PNL	2.8179	ELECTRICAL WIRING INSTALLED
ENGINE	13.6647	EXTERIOR MOLDINGS INSTALLED
FRAME INSTALLED	2.8137	AIR CONDITIONING AND HEATER
FRT AXLE/SUSPENSION	1.2941	INSTRUMENT PANEL INSTALLED
FUEL TANK / EXHAUST INSTALLED	.4332	DOOR HARDWARE AND WINDOWS
HOOD/FRONT END COMP. INSTALLED	1.6815	INTERIOR TRIM & FLOOR COVERING
RADIATOR & GRILLE	1.8769	SEATS INSTALLED
REAR AXLE/SUSPENSION	.7683	SUB FRAME AND ENGINE INSTALLED
ROOF	.4533	TRANSMISSION INSTALLED
SEATS	.2993	TIRES MOUNTED AND INSTALLED
STEERING	.6544	VEHICLE TESTED AND INSPECTED
TRANSMISSION	.2824	FINISHED VEHICLE SHIPPED
UNDER BODY	2.7895	
WHEELS & TIRES	2.7428	
TOTAL US CONTENT	46.9087	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL T2T43
 GMC CANYON
 CARLINE 52

ASSEMBLY LOC: WENTZVILLE, MISSOURI U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.6625	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP. FRAMING	1.7578	SIDE AND OUTER PANELS WELDED TO
BODY SIDE & REAR PANELS INSTALLED	3.2182	WINDSHIELD REINFORCEMENTS AND ROOF
BRAKES	1.8955	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	2.3638	FRONT AND REAR DOORS INSTALLED
COMM. BODY EQUIP	.0088	BODY PRIMED AND SEALED
DOORS	3.8751	EXTERIOR PAINT APPLIED
ELECT SYS & INST PNL	1.0910	ELECTRICAL WIRING INSTALLED
ENGINE	15.3745	EXTERIOR MOLDINGS INSTALLED
FRAME INSTALLED	3.3006	AIR CONDITIONING AND HEATER
FRT AXLE/SUSPENSION	.3896	INSTRUMENT PANEL INSTALLED
FUEL TANK / EXHAUST INSTALLED	.4845	DOOR HARDWARE AND WINDOWS
HOOD/FRONT END COMP. INSTALLED	2.2265	INTERIOR TRIM & FLOOR COVERING
RADIATOR & GRILLE	2.1365	SEATS INSTALLED
REAR AXLE/SUSPENSION	2.6367	SUB FRAME AND ENGINE INSTALLED
ROOF	.6254	TRANSMISSION INSTALLED
SEATS	2.1349	TIRES MOUNTED AND INSTALLED
STEERING	.1538	VEHICLE TESTED AND INSPECTED
TRANSMISSION	.1825	FINISHED VEHICLE SHIPPED
UNDER BODY	2.9354	
WHEELS & TIRES	2.8899	
TOTAL US CONTENT	51.3445	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL T2U43
 GMC CANYON
 CARLINE 52

ASSEMBLY LOC: WENTZVILLE, MISSOURI U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.3453	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP. FRAMING	1.7493	SIDE AND OUTER PANELS WELDED TO
BODY SIDE & REAR PANELS INSTALLED	2.9777	WINDSHIELD REINFORCEMENTS AND ROOF
BRAKES	1.5499	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.9690	FRONT AND REAR DOORS INSTALLED
COMM. BODY EQUIP	.0072	BODY PRIMED AND SEALED
DOORS	3.6846	EXTERIOR PAINT APPLIED
ELECT SYS & INST PNL	2.4349	ELECTRICAL WIRING INSTALLED
ENGINE	9.4159	EXTERIOR MOLDINGS INSTALLED
FRAME INSTALLED	2.7424	AIR CONDITIONING AND HEATER
FRT AXLE/SUSPENSION	1.3048	INSTRUMENT PANEL INSTALLED
FUEL TANK / EXHAUST INSTALLED	3.1359	DOOR HARDWARE AND WINDOWS
HOOD/FRONT END COMP. INSTALLED	1.5849	INTERIOR TRIM & FLOOR COVERING
RADIATOR & GRILLE	1.4874	SEATS INSTALLED
REAR AXLE/SUSPENSION	.8466	SUB FRAME AND ENGINE INSTALLED
ROOF	.5505	TRANSMISSION INSTALLED
SEATS	.7984	TIRES MOUNTED AND INSTALLED
STEERING	.6144	VEHICLE TESTED AND INSPECTED
TRANSMISSION	.2588	FINISHED VEHICLE SHIPPED
UNDER BODY	2.8015	
WHEELS & TIRES	2.3231	
TOTAL US CONTENT	43.5835	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 12M43
 CHEVROLET COLORADO
 CARLINE 52
 ASSEMBLY LOC: WENTZVILLE, MISSOURI U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.6127	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP. FRAMING	1.9037	SIDE AND OUTER PANELS WELDED TO
BODY SIDE & REAR PANELS INSTALLED	3.3676	WINDSHIELD REINFORCEMENTS AND ROOF
BRAKES	1.8678	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	2.1282	FRONT AND REAR DOORS INSTALLED
COMM. BODY EQUIP	.0088	BODY PRIMED AND SEALED
DOORS	3.9128	EXTERIOR PAINT APPLIED
ELECT SYS & INST PNL	1.9089	ELECTRICAL WIRING INSTALLED
ENGINE	15.3389	EXTERIOR MOLDINGS INSTALLED
FRAME INSTALLED	3.2109	AIR CONDITIONING AND HEATER
FRT AXLE/SUSPENSION	.9770	INSTRUMENT PANEL INSTALLED
FUEL TANK / EXHAUST INSTALLED	.7529	DOOR HARDWARE AND WINDOWS
HOOD/FRONT END COMP. INSTALLED	1.8295	INTERIOR TRIM & FLOOR COVERING
RADIATOR & GRILLE	1.8740	SEATS INSTALLED
REAR AXLE/SUSPENSION	3.1188	SUB FRAME AND ENGINE INSTALLED
ROOF	.6255	TRANSMISSION INSTALLED
SEATS	2.1353	TIRES MOUNTED AND INSTALLED
STEERING	.1539	VEHICLE TESTED AND INSPECTED
TRANSMISSION	.2611	FINISHED VEHICLE SHIPPED
UNDER BODY	3.4575	
WHEELS & TIRES	3.0143	
TOTAL US CONTENT	53.4614	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 12M53
 CHEVROLET COLORADO
 CARLINE 52
 ASSEMBLY LOC: WENTZVILLE, MISSOURI U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.7422	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP. FRAMING	1.8765	SIDE AND OUTER PANELS WELDED TO
BODY SIDE & REAR PANELS INSTALLED	3.5717	WINDSHIELD REINFORCEMENTS AND ROOF
BRAKES	1.9803	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	2.3316	FRONT AND REAR DOORS INSTALLED
COMM. BODY EQUIP	.0092	BODY PRIMED AND SEALED
DOORS	3.7987	EXTERIOR PAINT APPLIED
ELECT SYS & INST PNL	1.8415	ELECTRICAL WIRING INSTALLED
ENGINE	15.6244	EXTERIOR MOLDINGS INSTALLED
FRAME INSTALLED	3.3804	AIR CONDITIONING AND HEATER
FRT AXLE/SUSPENSION	1.0762	INSTRUMENT PANEL INSTALLED
FUEL TANK / EXHAUST INSTALLED	1.1190	DOOR HARDWARE AND WINDOWS
HOOD/FRONT END COMP. INSTALLED	2.0458	INTERIOR TRIM & FLOOR COVERING
RADIATOR & GRILLE	1.8320	SEATS INSTALLED
REAR AXLE/SUSPENSION	4.4620	SUB FRAME AND ENGINE INSTALLED
ROOF	.5282	TRANSMISSION INSTALLED
SEATS	2.5654	TIRES MOUNTED AND INSTALLED
STEERING	.1612	VEHICLE TESTED AND INSPECTED
TRANSMISSION	.2559	FINISHED VEHICLE SHIPPED
UNDER BODY	2.9004	
WHEELS & TIRES	3.3430	
TOTAL US CONTENT	56.4466	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 12N53
 CHEVROLET COLORADO
 CARLINE 52
 ASSEMBLY LOC: WENTZVILLE, MISSOURI U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.6165	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP. FRAMING	2.0314	SIDE AND OUTER PANELS WELDED TO
BODY SIDE & REAR PANELS INSTALLED	3.4106	WINDSHIELD REINFORCEMENTS AND ROOF
BRAKES	1.8047	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	2.2005	FRONT AND REAR DOORS INSTALLED
COMM. BODY EQUIP	.0084	BODY PRIMED AND SEALED
DOORS	3.5492	EXTERIOR PAINT APPLIED
ELECT SYS & INST PNL	2.6688	ELECTRICAL WIRING INSTALLED
ENGINE	14.5904	EXTERIOR MOLDINGS INSTALLED
FRAME INSTALLED	3.0810	AIR CONDITIONING AND HEATER
FRT AXLE/SUSPENSION	1.0643	INSTRUMENT PANEL INSTALLED
FUEL TANK / EXHAUST INSTALLED	.7032	DOOR HARDWARE AND WINDOWS
HOOD/FRONT END COMP. INSTALLED	1.8971	INTERIOR TRIM & FLOOR COVERING
RADIATOR & GRILLE	1.7581	SEATS INSTALLED
REAR AXLE/SUSPENSION	2.5262	SUB FRAME AND ENGINE INSTALLED
ROOF	.4953	TRANSMISSION INSTALLED
SEATS	2.3493	TIRES MOUNTED AND INSTALLED
STEERING	.7172	VEHICLE TESTED AND INSPECTED
TRANSMISSION	.1989	FINISHED VEHICLE SHIPPED
UNDER BODY	2.8990	
WHEELS & TIRES	2.8921	
TOTAL US CONTENT	52.4633	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 12P53
 CHEVROLET COLORADO
 CARLINE 52
 ASSEMBLY LOC: WENTZVILLE, MISSOURI U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.5250	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP. FRAMING	1.9790	SIDE AND OUTER PANELS WELDED TO
BODY SIDE & REAR PANELS INSTALLED	3.2256	WINDSHIELD REINFORCEMENTS AND ROOF
BRAKES	1.7000	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	2.0719	FRONT AND REAR DOORS INSTALLED
COMM. BODY EQUIP	.0080	BODY PRIMED AND SEALED
DOORS	3.5344	EXTERIOR PAINT APPLIED
ELECT SYS & INST PNL	2.6432	ELECTRICAL WIRING INSTALLED
ENGINE	13.9681	EXTERIOR MOLDINGS INSTALLED
FRAME INSTALLED	2.9026	AIR CONDITIONING AND HEATER
FRT AXLE/SUSPENSION	1.4592	INSTRUMENT PANEL INSTALLED
FUEL TANK / EXHAUST INSTALLED	.4753	DOOR HARDWARE AND WINDOWS
HOOD/FRONT END COMP. INSTALLED	1.7752	INTERIOR TRIM & FLOOR COVERING
RADIATOR & GRILLE	1.7670	SEATS INSTALLED
REAR AXLE/SUSPENSION	.7749	SUB FRAME AND ENGINE INSTALLED
ROOF	.4681	TRANSMISSION INSTALLED
SEATS	2.2868	TIRES MOUNTED AND INSTALLED
STEERING	.6756	VEHICLE TESTED AND INSPECTED
TRANSMISSION	.2541	FINISHED VEHICLE SHIPPED
UNDER BODY	2.7612	
WHEELS & TIRES	2.5605	
TOTAL US CONTENT	48.8167	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 12T43
 CHEVROLET COLORADO
 CARLINE 52
 ASSEMBLY LOC: WENTZVILLE, MISSOURI U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.5366	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP. FRAMING	1.7448	SIDE AND OUTER PANELS WELDED TO
BODY SIDE & REAR PANELS INSTALLED	3.2639	WINDSHIELD REINFORCEMENTS AND ROOF
BRAKES	1.7862	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	2.0913	FRONT AND REAR DOORS INSTALLED
COMM. BODY EQUIP	.0085	BODY PRIMED AND SEALED
DOORS	3.7290	EXTERIOR PAINT APPLIED
ELECT SYS & INST PNL	1.8145	ELECTRICAL WIRING INSTALLED
ENGINE	15.0207	EXTERIOR MOLDINGS INSTALLED
FRAME INSTALLED	3.1618	AIR CONDITIONING AND HEATER
FRT AXLE/SUSPENSION	1.2733	INSTRUMENT PANEL INSTALLED
FUEL TANK / EXHAUST INSTALLED	.4750	DOOR HARDWARE AND WINDOWS
HOOD/FRONT END COMP. INSTALLED	1.7568	INTERIOR TRIM & FLOOR COVERING
RADIATOR & GRILLE	1.8679	SEATS INSTALLED
REAR AXLE/SUSPENSION	1.7228	SUB FRAME AND ENGINE INSTALLED
ROOF	.5982	TRANSMISSION INSTALLED
SEATS	2.0417	TIRES MOUNTED AND INSTALLED
STEERING	.1472	VEHICLE TESTED AND INSPECTED
TRANSMISSION	.3526	FINISHED VEHICLE SHIPPED
UNDER BODY	3.0158	
WHEELS & TIRES	3.0812	
TOTAL US CONTENT	50.4908	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 12U43
 CHEVROLET COLORADO
 CARLINE 52

ASSEMBLY LOC: WENTZVILLE, MISSOURI U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.4386	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP. FRAMING	1.8927	SIDE AND OUTER PANELS WELDED TO
BODY SIDE & REAR PANELS INSTALLED	3.0360	WINDSHIELD REINFORCEMENTS AND ROOF
BRAKES	1.6023	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	2.0420	FRONT AND REAR DOORS INSTALLED
COMM. BODY EQUIP	.0075	BODY PRIMED AND SEALED
DOORS	3.3657	EXTERIOR PAINT APPLIED
ELECT SYS & INST PNL	2.6780	ELECTRICAL WIRING INSTALLED
ENGINE	9.7236	EXTERIOR MOLDINGS INSTALLED
FRAME INSTALLED	2.8300	AIR CONDITIONING AND HEATER
FRT AXLE/SUSPENSION	1.1878	INSTRUMENT PANEL INSTALLED
FUEL TANK / EXHAUST INSTALLED	3.1054	DOOR HARDWARE AND WINDOWS
HOOD/FRONT END COMP. INSTALLED	1.7517	INTERIOR TRIM & FLOOR COVERING
RADIATOR & GRILLE	1.4232	SEATS INSTALLED
REAR AXLE/SUSPENSION	1.1333	SUB FRAME AND ENGINE INSTALLED
ROOF	.5558	TRANSMISSION INSTALLED
SEATS	1.2417	TIRES MOUNTED AND INSTALLED
STEERING	.6350	VEHICLE TESTED AND INSPECTED
TRANSMISSION	.2256	FINISHED VEHICLE SHIPPED
UNDER BODY	2.7255	
WHEELS & TIRES	2.7063	
TOTAL US CONTENT	45.3088	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL 12V43
 CHEVROLET COLORADO
 CARLINE 52

ASSEMBLY LOC: WENTZVILLE, MISSOURI U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	1.3405	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP. FRAMING	1.6860	SIDE AND OUTER PANELS WELDED TO
BODY SIDE & REAR PANELS INSTALLED	2.8991	WINDSHIELD REINFORCEMENTS AND ROOF
BRAKES	1.5169	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.8282	FRONT AND REAR DOORS INSTALLED
COMM. BODY EQUIP	.0072	BODY PRIMED AND SEALED
DOORS	3.4692	EXTERIOR PAINT APPLIED
ELECT SYS & INST PNL	2.4733	ELECTRICAL WIRING INSTALLED
ENGINE	8.5279	EXTERIOR MOLDINGS INSTALLED
FRAME INSTALLED	2.7309	AIR CONDITIONING AND HEATER
FRT AXLE/SUSPENSION	1.3544	INSTRUMENT PANEL INSTALLED
FUEL TANK / EXHAUST INSTALLED	3.7531	DOOR HARDWARE AND WINDOWS
HOOD/FRONT END COMP. INSTALLED	1.5321	INTERIOR TRIM & FLOOR COVERING
RADIATOR & GRILLE	1.5423	SEATS INSTALLED
REAR AXLE/SUSPENSION	.8063	SUB FRAME AND ENGINE INSTALLED
ROOF	.5316	TRANSMISSION INSTALLED
SEATS	.0467	TIRES MOUNTED AND INSTALLED
STEERING	.6098	VEHICLE TESTED AND INSPECTED
TRANSMISSION	.2409	FINISHED VEHICLE SHIPPED
UNDER BODY	2.7535	
WHEELS & TIRES	2.3109	
TOTAL US CONTENT	41.9618	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 ELIAS DE J.MARTINEZ
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 07/18/2017

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA PROGRAM
 CFR CH. VI, PART 663

GENERAL MOTORS LLC - NORTH AMERICAN OPERATIONS
 BUY AMERICA CERTIFICATION
 2018 MODEL YEAR

MODEL K35906
 CHEVROLET SUBURBAN K2XX
 CARLINE 06
 ASSEMBLY LOC: ARLINGTON, TEXAS U.S.A.

US CONTENT BY SYSTEM -----	PERCENTAGE OF VEHICLE COST -----	DESCRIPTION OF ASSEMBLY OPERATIONS -----
BODY FRONT	.7093	FLOOR PANEL WELDED TO UNDERBODY
BODY RELATED COMP.	3.4085	SIDE AND OUTER PANELS WELDED TO FRAMING
BODY SIDE & REAR	1.8458	WINDSHIELD REINFORCEMENTS AND ROOF PANELS INSTALLED
BRAKES	4.1758	HOOD, DOORS AND FENDERS INSTALLED
BUMPERS & FINAL ASM	1.7558	FRONT AND REAR DOORS INSTALLED
DOORS	3.5553	BODY PRIMED AND SEALED
ELECT SYS & INST PNL	1.4257	EXTERIOR PAINT APPLIED
ENGINE	.5960	ELECTRICAL WIRING INSTALLED
FRAME	.0037	EXTERIOR MOLDINGS INSTALLED
FRT AXLE/SUSPENSION	6.3686	AIR CONDITIONING AND HEATER INSTALLED
FUEL TANK / EXHAUST	3.6918	INSTRUMENT PANEL INSTALLED
HOOD/FRONT END COMP.	1.3513	DOOR HARDWARE AND WINDOWS INSTALLED
RADIATOR & GRILLE	.0638	INTERIOR TRIM & FLOOR COVERING INSTALLED
REAR AXLE/SUSPENSION	5.9881	SEATS INSTALLED
ROOF	.5470	SUB FRAME AND ENGINE INSTALLED
SEATS	.8835	TRANSMISSION INSTALLED
STEERING	1.1793	TIRES MOUNTED AND INSTALLED
TRANSMISSION	4.6398	VEHICLE TESTED AND INSPECTED
UNDER BODY	2.0665	FINISHED VEHICLE SHIPPED
WHEELS & TIRES	2.4439	
TOTAL US CONTENT	46.7006	

COST OF FINAL ASSEMBLY:

PREPARED BY:
 GENERAL MOTORS LLC
 GMNA PRODUCT COST
 GENERAL MOTORS LLC
 GBS FINANCE - GMNA PRODUCT COST
 LETICIA LOPEZ VEGA
 CARRETERA SALTILLO-MONTERREY KM 7.5
 RAMOS ARIZPE COAHUILA 25900 MEX
 REVISION DATE : 06/25/18

REGULATORY PROVISION:
 FEDERAL TRANSIT ADMINISTRATION
 DEPARTMENT OF TRANSPORTATION
 BUY AMERICA REQUIREMENTS
 49 CFR PART 661